Service Alert

Mazda North American Operations Irvine, CA 92618-2922



Subject:

MAZDA CONNECT SYMPTOM TROUBLESHOOTING [6TH
GENERATION VEHICLES]

Service Alert No.: SA-001/22

Last Issued: 05/23/2022

BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

Previous Service Alert:	Date(s) Issued:
SA-001/22	03/17/22, 02/14/22 and 01/11/22
SA-019/21	11/16/21, 09/28/21, 09/01/21, 06/25/21, 04/08/21 and 02/2 6/21
SA-026/20	06/11/20 and 02/11/20
SA-065/17	08/10/17

APPLICABLE MODEL(S)/VINS

2014-2018 Mazda3	2016-2021 CX-3	2016-2020 CX-9
2016-2021 Mazda6	2016-2020 CX-5	2016-2022 MX-5

DESCRIPTION

Use the symptom troubleshooting tables below to diagnose MAZDA CONNECT concerns.

REPAIR PROCEDURE

Before proceeding:

- Confirm that the Connectivity Master Unit (CMU) is updated to the latest software version. Go to MGSS ->
 Infotainment -> MAZDA CONNECT Updates
- Go to TSB 16-001/20 to view MAZDA CONNECT CMU software fix list.
- Confirm that the customers device is compatible. Go to connect.mazda.com -> Support -> Compatibility.
- Confirm that the customers device is updated to the latest software version.
- Apple Carplay/Android Auto FAQ, go to SA-070/20.
- If you suspect a counterfeit Navi SD card, ask the customer for proof of purchase. It cannot be determined by visually looking at the label. If Mazda Toolbox is used and a counterfeit SD card is detected, the customer VIN may be locked-out.

Page 1 of 17

NOTE:

- If possible, complete any one of the Microsoft Forms Questionnaires. Go to MGSS -> Infotainment -> MAZDA CONNECT Questionnaire.
- Some customers may complain that on some roads, the speed limit shown in the navigation screen is different from the actual road signs.
 - Every time MAZDA CONNECT starts (boots up when ignition turns ON), the disclaimer notification is shown to notify that there are some difference between the navigation map data and actual road signs.
 - Lead time for updating the navigation map data takes 12 months.

Index:

- No. 1 Blank Screen
- No. 2. Rear View Camera is not displayed
- No. 3 Rebooting
- No. 4 Infotainment System Has No Sound
- No. 5 Commander Switch Does Not Work
- No. 6 Bluetooth device will not pair

Service Alert No.: SA-001/22

- No. 7 Incorrect GPS position
- No. 8 Voice Recognition Does Not Work
- No. 9 Cannot Make a Hands-Free Call
- No. 10 Cannot Play Bluetooth Audio
- No. 11 Navigation address not found
- No. 12 Other Symptoms
- No. 13 How to update the Navigation SD Card Map
- No. 14 How to Check Navi SD Card VIN Lock

Page 2 of 17

No. 1 Blank Screen

Step	Inspection	Result	Action
		Yes	Go to step 2.
1	ls the Rear View Camera displayed?	No	Refer to No. 2. Rear View Camera is not displayed 2016-2017 CX-9 - See 09-034/17
2	Press the "HOME" button. Is the HOME	Yes	Normal Operation
_	screen displayed correctly?	No	Go to step 3
3	Using M-MDS, are any infotainment	Yes	Go to MGSS for DTC diagnosis.
	system DTC's stored?	No	Go to step 4.
1	Is there a device connected to the USB	Yes	Go to step 5.
	port?	No	Go to step 6.
	Disconnect the USB device. Does the	Yes	USB device is not compatible.
5	display function properly after USB device is disconnected?	No	Go to step 6.
6	le are commoder for are comer Biopiay	Yes	Go to step 7.
		No	Insert the connector correctly.
7	Are the connectors for the CMU inserted correctly?	Yes	Go to step 8.
		No	Insert the connectors correctly.
8	Illo the center display voltage at 0020	Yes	Go to step 9.
		No	Go to step 10.
	Swap the Center Display with good	Yes	Check / Replace the Center Display.
9	known vehicle. Is the screen display normal?	No	Go to step 10.
10	Swap the CMU with good known vehicle. Is the screen display normal?	Yes	Retrieve the data log if possible before replacing the CMU Document date and time of the condition
		No	Repair / Replace wiring harness. Go to MGSS View Content -> Wiring Diagram -> Body and Accessories -> Entertainment System.

Page 3 of 17

No. 2 Rear View Camera is not displayed

Step	Inspection	Result	Action	
1	Using M-MDS, are any infotainment system DTC's stored?	Yes	Go to MGSS for DTC diagnosis	
ı		No	Go to step 2.	
2	Is the vehicle equipped with 360 View	Yes	Go to step 3.	
	Monitor?	No	Go to step 4.	
3	Is the Front Camera and Side Cameras	Yes	Check / Replace the 360 View Monitor control unit.	
	displayed normally?	No	Go to step 4.	
			Go to step 5.	
4	Are images other than the Rear View Camera displayed?	Yes	2014-2018 Mazda3 5-door HB 2016-2019 CX-3 Go to 09-031/20	
		No	Go to No. 1 Blank Screen.	
5	Is the connector for the Rear View Camera Inserted correctly?	Yes	Go to step 6.	
5		No	Insert the connector correctly.	
6	Is the connector for the Center Display Inserted correctly	Yes	Go to step 7.	
		No	Insert the connector correctly	
7	Are the connectors for the CMU Inserted correctly	Yes	Go to step 8.	
		No	Insert the connectors correctly	
	Swap the Rear View Camera with good known vehicle. Is the screen display normal? Swap the CMU with good known vehicle. Is the screen display normal?	Yes	Check / Replace the Rear View Camera	
8		No	Go to Step 9	
0		Yes	Retrieve the data log if possible before replacing the CMU Document date and time of the condition	
		No	Go to MGSS, WSM, REAR MOUNT CAMERA IMAGE NOT CLEAR/NO IMAGE ON SCREEN.	

Page 4 of 17

No. 3 Rebooting

Step	Inspection	Result	Action	
1	Using M-MDS, are any infotainment system DTC's	Yes	Go to MGSS for DTC diagnosis	
ı	stored?		Go to step 2.	
		Yes	Go to step 3.	
2	Does the reboot continue after removing the Navigation SD card?		Check / Replace the Navigation SD card. Note: See TSB 09-015/20 if applicable	
3	Is there a device connected to the USB port?	Yes	Go to step 4.	
3	is there a device confidence to the OSB port?	No	Go to step 5.	
4	Disconnect the USB device. Does the reboot stop		USB device is not compatible	
4	after USB device is disconnected?	No	Go to step5.	
		Yes	Go to step 6.	
5	Does the reboot continue after ignition key OFF then back ON?	No	Retrieve the data log if possible before replacing the CMU Document date and time of the condition	
6	Does the reboot continue after vehicle battery disconnect?	Yes	Retrieve the data log if possible before replacing the CMU Document date and time of the condition	
		No	No repair needed.	

Page **5** of **17**

No. 4 Infotainment System Has No Sound

Service Alert No.: SA-001/22

Step	Inspection	Result	Action
	Using M-MDS, are any infotainment	Yes	Go to MGSS for DTC diagnosis
1	system DTC's stored?	No	Go to step 2.
2	Is the customer complaint "no sound from left side of vehicle"?	Yes	Go to step 3.
2		No	Go to step 4.
3	Is the customer's connected device an	Yes	Advise customer to update their iPhone IOS to 15.1 or higher, then go to step 4.
	iPhone?	No	Go to step 5.
	Did iPhone IOS 15.1 or higher resolve	Yes	Repair complete.
4	customer concern?	No	Collect CMU log data and contact Hotline for additional support.
5	ls sound normal other than navigation	Yes	Go to step 6.
5	guidance?	No	Go to step 7.
6	Can you hear the voice after raising the	Yes	Normal Operation.
6	navigation volume?	No	Go to step 8.
7	Can you hear sound after turning on audio	Yes	Normal Operation.
1	mode?	No	Go to step 9.
		Yes	Complete
8	Replace the Navigation SD Card. Can you hear voice after Navigation SD Card replacement?	No	Retrieve the data log if possible before replacing the CMU Document date and time of the condition
0	Can you hear sound after raising the	Yes	Normal Operation
9	volume of audio?	No	Go to step 10.
10	<< Source: USB/iPod >> Are there any problems with the media and the music files? << Source: Radio >> Are there any problems with the antenna and the reception? << Source: Bluetooth Audio >> Are there any problems with Bluetooth?	Yes	<< Source: USB/iPod >> Check the media and the compatible files. << Source: Radio >> Check the antenna, the reception, and the Tuner and Amp Unit (TAU) side. << Source: Bluetooth Audio >> Check the Bluetooth connection and the Bluetooth device.
	The there any problems with bluetoeth:	No	Go to step 11.
11	Go to MGSS "DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "94" Speaker Inspection.	Pass	Retrieve the data log if possible before replacing the CMU Document date and time of the condition
	Did the Speaker Inspection Pass?		Go to MGSS NO SOUND OUTPUT IN ALL MODES [ENTERTAINMENT SYSTEM [WITH

Page 6 of 17

No. 5 Commander Switch Does Not Work

Inspection	Result	Action
2 - 1 - 2 - 3 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	Yes	Go to MGSS for DTC diagnosis
	No	Go to step 2.
Does the Commander Switch work	Yes	Go to step 3.
correctly?	No	Go to step 4.
Does the Steering Wheel Switch work	Yes	Normal Operation.
correctly?	No	Go to step 5.
2016-2020 CX-5: Inspect connector C-	Yes	Repair as necessary
16 for corrosion due to liquid spill. Is corrosion found at C-16? Other models: Go to next step	No	Go to next step
Are fues blown/ missing?	Yes	Blown - Diagnose blown fuse Missing - Install missing fuse
	No	Go to step 6.
Go to MGSS "DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "65" Commander Switch and Steering Wheel Switch Inspections. Did the Switch Inspections Pass?	Pass	Go to step 7.
	Fail	Replaced the failed switch. Go to MGSS: • Steering Wheel Switch Removal/Installation • Commander Switch Removal/Installation
ls the connector for the Commander	Yes	Go to step 8.
Switch inserted correctly?	No	Insert the connector correctly.
Are the CMU connectors inserted correctly?	Yes	Go to step 9.
	No	Insert the connectors correctly.
Swap the Commander Switch with good	Yes	Check / Replace the Commander Switch.
known vehicle. Does the Commander Switch work correctly?	No	Go to step 10.
vehicle. Does the Commander Switch work correctly?	Yes No	Retrieve the data log if possible before replacing the CMU Document date and time of the condition Repair/Replace wiring harness. Go to MGSS View Content -> Wiring Diagram -> Body and Accessories -> Entertainment System.
	Using M-MDS, are any infotainment system DTC's stored? Does the Commander Switch work correctly? Does the Steering Wheel Switch work correctly? 2016-2020 CX-5: Inspect connector C-16 for corrosion due to liquid spill. Is corrosion found at C-16? Other models: Go to next step Are fues blown/ missing? Go to MGSS "DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "65" Commander Switch and Steering Wheel Switch Inspections. Did the Switch Inspections Pass? Is the connector for the Commander Switch inserted correctly? Are the CMU connectors inserted correctly? Swap the Commander Switch with good known vehicle. Does the Commander Switch work correctly? Swap the CMU from known good vehicle. Does the Commander Switch work	Using M-MDS, are any infotainment system DTC's stored? Does the Commander Switch work correctly? Does the Steering Wheel Switch work correctly? No 2016-2020 CX-5: Inspect connector C-16 for corrosion due to liquid spill. Is corrosion found at C-16? Other models: Go to next step Are fues blown/ missing? Are fues blown/ missing? Are fues blown/ ECONNECTIVITY MASTER UNIT (US)] Perform Diagnostic Assist Code "65" Commander Switch and Steering Wheel Switch Inspections. Did the Switch Inspections Pass? Is the connector for the Commander Switch inserted correctly? Are the CMU connectors inserted correctly? Swap the Commander Switch with good known vehicle. Does the Commander Switch work correctly? Swap the CMU from known good vehicle. Does the Commander Switch work correctly?

Page **7** of **17**

Service Alert No.: SA-001/22

No. 6 Bluetooth device will not pair

	Increasion	Result	A office	
Step				
1	Comig in MES, are any information cyclem	Yes	Go to MGSS for DTC diagnosis	
		No Yes	Go to step 2.	
2	Is Bluetooth enabled on the customers		Go to step 3.	
	device?	No	Enable Bluetooth on the customers device.	
		Yes	Go to step 4.	
3	Is the customers device paired to the vehicle?	No	Pair the customers device to the vehicle. See MGSS Bluetooth® PAIRING NOT POSSIBLE [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]	
	Is the customers device selected in MAZDA	Yes	Go to step 5.	
4	CONNECT settings?	No	Select the customers device from Bluetooth settings.	
	Delete the device from MAZDA CONNECT		Normal Operation	
5	and then re-pair it. Does Bluetooth work correctly?	No	Go to step 6.	
	Go to http:// infotainment.mazdahandsfree.com Web Site. Is the customers device compatible?	Yes	Go to step 7.	
6		No	The customers device is not compatible.	
		Yes	Go to step 8.	
7	Does the same symptom occur on another same model/year vehicle?	No	Check / Replace the CMU. Document device model, software version and occurrence of the condition. Retrieve the data log if possible before replacing the CMU Document date and time of the condition	
		Yes	Vehicle operation is normal.	
8	Reboot the customers device. Does Bluetooth work correctly?	No	Check / Replace the CMU. Document device model, software version and occurrence of the condition. Retrieve the data log if possible before replacing the CMU Document date and time of the condition	

Page 8 of 17

No. 7 Incorrect GPS position

Step	Inspection	Result	Action	
	Go to MGSS "DIAGNOSTIC ASSIST FUNCTION	Yes	Normal Operation.	
1	[CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "72" GPS information verification. Check GPS Received Level. Does the Navi system show correct vehicle position?	No	Go to step 2.	
	Using M-MDS, are any of the following DTC's	Yes	Go to step 4.	
2	stored? - B119F:1D, GPS antenna circuit malfunction - B119F:11, GPS antenna circuit malfunction - B119F:13, GPS antenna circuit malfunction - B119F:92, GPS antenna circuit malfunction	No	Go to step 3.	
	Is the wheel and tire size correct according to the	Yes	Go to step 8.	
1.5	Is the wheel and tire size correct according to the tire label?	No	Swap wheels/tires with correct size. If issue is fixed, inform the customer.	
4	I- th- ODC	Yes	Go to step 5.	
4	Is the GPS antenna connector secured properly?		Insert the connector correctly.	
5	Is the GPS wiring harness open or shorted?	Yes	Repair / Replace GPS wiring harness.	
3	is the GF3 willing harness open or shorted?	No	Go to step 6.	
6	Are the CMU connectors secured properly?	Yes	Go to step 7.	
٥	Are the Civio conhectors secured property?	No	Insert the connectors correctly.	
7	Is the CMU wiring harness open or shorted?	Yes	Repair / Replace CMU wiring harness.	
	is the Civio willing harriess open of shorted?		Go to step 8.	
		Yes	Repair completed.	
8	Replace GPS antenna. Does the Navigation system show correct position?	No	Retrieve the data log if possible before replacing the CMU Document date and time of the condition	

NOTE: Remove aftermarket GPS devices that may interfere with vehicle GPS antenna. Example: Some radar detectors may emit radio waves that interfere with the vehicle GPS antenna.

Page 9 of 17

No. 8 Voice Recognition Does Not Work

Step	Inspection	Result	Action
1	Using M-MDS, are any infotainment system DTC's stored?		Go to MGSS for DTC diagnosis
<u>'</u>			Go to step 2.
	Go to MGSS "DIAGNOSTIC ASSIST FUNCTION		Go to step 3.
2	[CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "65" Commander Switch and Steering Wheel Switch Inspections. Did the Steering SW Inspection Pass?	Fail	Go to MGSS STEERING SWITCH INSPECTION.
	Go to MGSS "DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "61" Microphone signal input condition Did the Microphone Inspection Pass?		Go to step 4.
3			Go to MGSS MICROPHONE INSPECTION.
		Yes	Repair complete
4	Go to MGSS VOICE OPERATION NOT POSSIBLE [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]] Is the vehicle repaired?	No	Retrieve the data log if possible before replacing the CMU Document date and time of the condition

No. 9 Cannot Make a Hands-Free Call

Step	Inspection	Result	Action	
1	Using M-MDS, are any infotainment system	Yes	Go to MGSS for DTC diagnosis	
'	DTC's stored?		Go to step 2.	
2	Is Bluetooth enabled on the customers	Yes	Go to step 3.	
	device?	No	Enable Bluetooth on the customers device.	
	la the quatemers device data convice	Yes	Go to step 4.	
3	Is the customers device data service strength good?	No	Move to a location where data service strength is good and retest.	
4	Is the customers device paired to the vehicle?	Yes	Go to step 5.	
4		No	Pair the customers device to the vehicle.	
	Is the customers device selected in MAZDA CONNECT settings?	Yes	Go to step 6.	
5		No	Select the customers device from Bluetooth settings.	
	Delete the device from MAZDA CONNECT and then re-pair it. Does Bluetooth work correctly?	Yes	Normal Operation	
6		No	Go to step 7.	
	Go to http://	Yes	Go to step 8.	
7	infotainment.mazdahandsfree.com Web Site. Is the customers device compatible?	No	The customers device is not compatible.	

Page 10 of 17

Servi	ice i	ΔΙ	ert	N٥	•	SA.	-001	122

8	Does the same symptom occur on another		Go to step 9.		
	same model/year vehicle?	No	Go to step 10.		
9	Reboot the customers device. Does Bluetooth work correctly?		Vehicle operation is normal.		
9			Go to step 10.		
10	Is the Bluetooth device in a place where radio waves may be blocked?	Yes	Move the Bluetooth device away from hidden location.		
	(Behind or under a sheet, in a box, in a purse/bag, ext.)	No	Go to step 11.		
11	Is the Bluetooth device contacting or blocked by metal objects?	Yes	Move the Bluetooth device away from metal objects.		
	blocked by Metal objects:	No	Go to step 12.		
12	ls a Bluetooth device and a USB device	Yes	Disconnect other USB device.		
12	connected at the same time?	No	Go to step 13.		
13	Does the problem occur in a specific geological location only?		Move to a different location. This may be caused by electrical interference by radio stations, specific small power radio stations, or amateur radio stations for mobile identification used in industrial, scientific and medical devices.		
		No	Go to step 14.		
14	Does the same symptom occur on another		Go to step 15		
	Bluetooth device?	No	The customers device is not compatible.		
15	Does the voice recognition system operate using other functions such as Bluetooth Audio?		Check / Replace the CMU. Document device model, software version and occurrence of the condition. Retrieve the data log if possible before replacing the CMU Document date and time of the condition		
		No	Go to No. 8 Voice Recognition Does Not Work		

Page **11** of **17**

Service Alert No.: SA-001/22

No. 10 Cannot Play Bluetooth Audio

Step	Inspection	Result	Action
1	Using M-MDS, are any infotainment system	Yes	Go to MGSS for DTC diagnosis
ı	DTC's stored?	No	Go to step 2.
2 Is B	ls Bluetooth enabled on the customers	Yes	Go to step 3.
	device?	No	Enable Bluetooth on the customers device.
	Is the customers device data service	Yes	Go to step 4.
3	strength good?	No	Move to a location where data service strength is good and retest.
	Is the customers device battery strength	Yes	Go to step 5
4	good?	No	Connect the customers device to a charger or recharge the device, then retest.
5	Is the customers device paired to the	Yes	Go to step 6.
3	vehicle?	No	Pair the customers device to the vehicle.
	ls the customers device selected in MAZDA	Yes	Go to step 7.
6	Is the customers device selected in MAZDA CONNECT settings?		Select the customers device from Bluetooth settings.
	Delete the device from MAZDA CONNECT	Yes	Normal Operation
7	and then re-pair it. Does Bluetooth work correctly?	No	Go to step 8.
	Go to http://	Yes	Go to step 9.
8 Si	infotainment.mazdahandsfree.com Web Site. Is the customers device compatible?		The customers device is not compatible.
9	Does the same symptom occur on another	Yes	Go to step 10.
9	same model/year vehicle?	No	Go to step 11.
10	Reboot the customers device. Does	Yes	Vehicle operation is normal.
10	Bluetooth work correctly?	No	Go to step 11.
11	Is the Bluetooth device in a place where radio waves may be blocked?	Yes	Move the Bluetooth device away from hidden location.
(1	(Behind or under a sheet, in a box, in a purse/bag, ext.)	No	Go to step 12.
	Is the Bluetooth device contacting or blocked by metal objects?	Yes	Move the Bluetooth device away from metal objects.
		No	Go to MGSS NO Bluetooth® AUDIO AND INTERNET RADIO SOUND [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]] Go to step 13 if not resolved.
			Disconnect other USB device.
13	Is a Bluetooth device and a USB device connected at the same time?	No	Check / Replace the CMU. Document device model, software version and occurrence of the condition.

Page 12 of 17

Service Alert No.: SA-001/22 Last Issued : 05/23/2022

		 Retrieve the data log if possible before replacing the CMU Document date and time of the condition
--	--	---

No. 11 Navigation address not found

Navigation system does not contain a road that I know it 1 exists and I am certain I have the most recent map update available.

Go to mapcreator.here.com, point, click and report missing address.

No. 12 Other symptoms

113. 12 3111	er symptoms Symptom	Solution				
		Solution				
SiriusXM	Unable to Connect to SiriusXM Radio Check SiriusXM Tuner	Update CMU software version to 74.00.230A or later.				
	SIRIUSXM Travel Link Parking Information Not Subscribed Error	Go to SA-007/22				
	Can SiriusXM be added if not equipped?	Go to MT-007/15				
Bluetooth	iPhone incoming SMS Text Message is not displayed	Go to MT-011/18				
	Wrong phone connected	Go to SA-063/17				
Center Display	Hot Temperature Warning message © Settings 11:24 Temperature Warning Display is too Hot. Screen performance may be decreased until it cools. OK	High-Temperature Normal Detection The Temperature Warning message displays when the MAZDA CONNECT™ screen temperature is above 176 °F (80 °C). • This is a normal screen protection function. DO NOT perform repairs for this concern. Normal screen operation will resume when the screen temperature cools. High-Temperature False Detection Temperature Warning message when the MAZDA CONNECT™ screen temperature is below 176 °F (80 °C) • Update CMU software version to 74.00.310A or later.				
	Rear view monitor is blurry	Go to MT-007/18 Go to 09-031/20 if applicable				
	Touch screen operates by itself (ghost touch)	2014-2016 Mazda3 (Japan and Mexico built) Go to SSPB6 2016-2017 Mazda6 (US spec) with VINS lower than				

Page 13 of 17


Serv	ice	ΔΙ	ort	Nο	٠.	CΔ	_001	/22
3 E I V		~	EIL	IVU	:	ЭM	~~~	166

	JM1GL******156205 (produced before December 29, 2017) 2017-2018 Mazda6 (Mexico spec) with VINS lower than JM1GL******149891 (produced before October 31, 2017) Go to 09-037/21 2017-2020 CX-5 vehicles with VINs lower than JM3KF******869654 (produced before Aug. 24, 2020) Go to 09-003/22 2014-2016 Mazda3 (Japan and Mexico built) Go to SSPB6 2016-017 CX-9 Go to SSPB9 2017-2018 Mazda3 2018-2019 Mazda6
Screen cracking (spider cracking)	2016-2019 Mazdao 2016-2018 CX-5 Go to SA-008/18 2016-2017 CX-3 2017 MX-5 2016 MX-5 vehicles with VINs lower than JM1ND******119894 (produced before July 4, 2016)
Surface Peeling	Go to 09-018/18 2016-2017 Mazda6 (US spec) with VINS lower than JM1GL******156205 (produced before December 29, 2017) 2017-2018 Mazda6 (Mexico spec) with VINS lower than JM1GL*****149891 (produced before October 31, 2017) Go to 09-037/21
	2017-2020 CX-5 vehicles with VINs lower than JM3KF*****869654 (produced before Aug. 24, 2020) Go to 09-003/22
Clock shows incorrect time	Go to SA-041/20
How to update maps	Go to Mazda Toolbox
Error message "Invalid SD Card"	1. Go to MT-001/18 2. Check VIN Lock
Navigation is inoperative	1. Go to MT-007/15 2. Go to MGSS MAP IS NOT DISPLAYED [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]
No Navigation voice guidance	Go to MGSS NO NAVIGATION GUIDANCE VOICE OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]
Smart phone device will not charge	Go to MT-022/15 Go to MT-002/18
	Surface Peeling Clock shows incorrect time How to update maps Error message "Invalid SD Card" Navigation is inoperative No Navigation voice guidance

Page 14 of 17

Service Alert No.: SA-001/22 Last Issued: 05/23/2022

Audio source improper operation when device connected to USB	Go to MT-002/18
No USB audio sound	Go to MGSS NO USB AUDIO SOUND OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]
No Aux audio sound	Go to MGSS NO AUX AUDIO SOUND OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]



Page 15 of 17

Customer is locked out of map update on Mazda Toolbox due to unauthorized or counterfeit navigation SD card. How to unlock the customer account in Mazda Toolbox 1. Purchase a Genuine Mazda Navigation SD card. 2. Customer or dealer must contact NNG helpdesk by email at piracy@nng.com and request customer account unlock. NOTE: NNG may require proof of purchase to unlock the customer account. MAZDA TOOLBOX ⟨

⟨


⟨

mazba No Map Update available There is no new update available for your device: Free map Your VIN numb - Your device is up-to-date. All available map updates have already been installed. update period AND/OR has expired 5544 MB / 15448 MB - Your free map update period has expired, click on "Buy content" to purchase. Click Map version on the left side of this page for further details. Map version

Customer needs to go to "Buy content" to purchase map update.

Page 16 of 17

No. 14 How to Check Navi SD Card VIN Lock



Page 17 of 17