

Subject: DTC B1495:87 STORED AND CANNOT BE ERASED AFTER ACCESSORY TRAILER HITCH IS INSTALLED	Service Alert No.: SA-030/22
	Last Issued : 05/05/2022

BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

Previous Service Alert	Date(s) Issued
SA-039/20	12/17/20, 10/14/20 and 03/09/20

APPLICABLE MODEL(S)/VINS

2020-2022 CX-9 (Grand Touring and Signature)

DESCRIPTION


Some vehicles may store DTC B1495:87 (LIN communication error) and cannot be cleared after accessory Trailer Hitch is installed. This may be caused by liftgate foot sensor deactivation procedure not completed during trailer hitch installation.

REPAIR PROCEDURE

1. Verify concern.
2. Follow HANDS FREE LIFTGATE SENSOR **DEACTIVATION PROCEDURE**
3. Connect MDARS and erase DTC's.
4. Verify repair.

NOTE:

- Advise the customer that they will no longer have the handsfree sensor function after trailer hitch installation.
- Advise the customer to leave the Hands-Free Liftgate "unchecked".



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.