Service Campaign

Service Campaign S7646

May 2022

Mack MMD Steering Column Bracket Hardware

Service Category Service Department

Section Function Group 641

Technician Skill Level C		Market North America	
Appli	cability		
	Mack		
	Model Years	Models	
	2021	MD6, MD7	

Introduction

Mack trucks has determined that certain model year 2021 Mack Medium Duty ("MMD") vehicles, require an inspection and retorque of the steering column mounting hardware. Follow the instructions below to check relaxed torque and then retorque all steering column mounting hardware.

Production Change Information

This bulletin applies to vehicles built within the specified production changes below.

Br	rand	Engine	Emission Level	Starting Build Date	Ending Build Date
	Mack	CU7	EM-USA17	13-January-2021	15-January-2021

Warranty Information

This repair is covered by an authorized Service Program. Reimbursement is obtained through the normal claim handling process.			
Claim Type (used only when uploading from the Dealer Bus. Sys.) B			
Main Labor Code	Description Hours		
1720-16-09-01	Campaign, General x3	0.3	
Causal Part 84755408			
SCC Authorization Code	\$7646		
Expiration Date	May 31, 2023		


Parts Information

Part Numbers	Part Names	Quantity
990940	Flange nut	*


Required Tools & Equipment


N/A Repair Procedure

- 1. Park the vehicle on a level surface.
- 2. Apply the parking brake.
- 3. Place the gear lever in neutral.
- 4. Install the wheel chocks.




5. Disconnect the cable from the negative terminal.







- 6. Remove the screw.
- 7. Remove the panel.




8. Remove the screws.



9. Remove the panel.



10.Inspect the four steering column mounting nuts for proper installation, followed by checking their relaxed torque.



Relaxed Torque Check	
Steering column, nut	9Nm (6.5 ft-lb)

11. Using a torque wrench, extension, and 13mm socket check relaxed torque on the four nuts.

Important


If the nuts move when checking at 9Nm (relaxed torque), STOP! Take pictures, email the reliability group (below information) at <u>reliability@volvo.com</u> and wait for further instructions.

You must include

- VIN
- Milage/HRs
- Pictures
- Service tech contact information
- 12. If the nuts do not move at 9Nm (relaxed torque) loosen the four mounting screws and retorque hardware to spec.

Tightening torque	
Steering column, nut	24 ±4 Nm (17±3 ft-lb)


13.Install the panel.



14.Install the screws.


15. Torque the panel screws.

Tightening torque		
Panel, screws	1.8 ±0.2 Nm (16±2 lb-in)	



16.Install the panel.

17.Install the screw.




18.Install the panel.


19.Install the Screws.

20.Torque panel the screws.


Tightening torque	
Panel, screws	1.8 ±0.2 Nm (16±2 lb-in)



21.Connect the cable to the negative terminal.



22.Remove the wheel chocks.



23.Return vehicle to service.