V O L V O

Service and Parts Business

Technical Journal

TITLE: TCAM Rebooting, VIDA Cannot maintain connection, Loss of connectivity

REF NO:	ISSUING DEPARTMENT:	CAR MARKET:			
TJ 36254.1.1	Technical Service	United States and Canada			
3 US 7	PARTNER:	ISSUE DATE:	STATUS DATE:		
	7510 Volvo Car USA	2022-04-27	2022-05-06		
FUNC GROUP: 3970	FUNC DESC: Mobile data services	Page	1 of 6		

"Right first time in Time"

Attachment

File Name	File Size
TJ 36254.jpg	0.0165 MB
TJ Instruction_36254_Locating TCAM Hardware Part Number.pdf	0.4589 MB

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

NOTE: the following only applies to vehicles equipped with a TCAM unit with a specific Hardware Part number: 32364074

To locate the Hardware Part Number that is in the vehicle, follow the instructions in the attachment *TJ Instruction 36254 Locating TCAM Hardware Part Number*

The TCAM can enter a state where it will continuously reboot itself. When this occurs one or more of the symptoms below can be observed:

- VIDA will not maintain a connection via ethernet cable or WiFi the Connection status indicator at the top of the VIDA screen will cycle between Green (connected) and Red (not connected) every 40-60 seconds.
- The vehicle/VIN may not show in VIDA
- The TCAM may appear to be stuck in Programming Mode in the VIDA Advanced Test screen.
- Customer complaint that there is no internet connection and the signal indicator at the top left of the CCD is blank with an "x".

Technical Journal 36254.1.1

Avoid any type of factory reset of the TCAM and/or infotainment system to prevent the continuous TCAM reboot.

For example, do not perform any of the following reset methods:

- In-car Settings menu Factory Reset
- VIDA Diagnostic Sequence "TCAM Reset,"
- The TCAM Backup Battery charging sequence (prompt to reset TCAM)

See instructions under Service for repair information.

TCAM = Telematics and Connectivity Antenna Module CCD = Center Console Display

CSC Customer Symptom Codes

Code	Description
22	Diagnostic communication/Wired diagnostic connection to vehicle does not work
23	Diagnostic communication/WiFi diagnostic connection to vehicle does not work
EM	Internet Connection/Does not work

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
236							2022-2022		-	202148-202212
238							2022-2022		-	202148-202212
246							2022-2022		-	202148-202212
536	ED	E400V6					2021-2022		-	202149-202212
539							2022-2022		-	202149-202212

Service:

Once the TCAM enters this state, it will not be posible to recover it and replacement is necessary.

A future software update will prevent this from occurring. Timing is not yet available.

The issue has been fixed by the supplier and in production as of structure week 2022w13. Updated parts can be identified by a red or black dot marking on the underside of the TCAM (see attachment).

NOTE: Un-marked spare parts can still be installed without issue. However, avoid factory resetting these TCAMs as described above in the Description.

Should a TCAM with Hardware Part Number 32364074 that is marked as indicated above exhibit the symptoms in the Description section, please submit a Vehicle Report following the guidelines below and proceed with replacement of the unit.

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, please use following data: VST Op number: 39744-2 and applicable CSC

VST Operation Number


VST Operation Number	Description
39744-2	Control module, remote communication replace

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3970.

To view TJ attachments continue to next page. This TJ has two attachments.

Technical Journal 36254.1.1



		Volvo Car Customer Service
		TJ Instruction
		TJ No 36254
		Date
		April 27, 2022
Title	Locating TCAM Hardware Part Nu	umber

Method 1

The hardware part number is listed in the ECU Identification tab of the Components screen for TCAM.

anning & Diagnostics Softw	ware Installation Inf	ormation Service Journals						Q	≡	යා	0
		YV4062RM4N1900821 Cus XC60 (18-), 2022, 900821	tomer Name:					List:			ī
Lists	modelifeariona	(10-), 2022, 000021									_
Planning							Reado	ut (Later) 🗊	4/14/2022 9	.59:10 AM	
Customer Symptom Codes	ECUs (Dther	ē	 Wiring Diagrams 	Parameters	Activations	Diagnostic Sequences	Images	ECU Ide	ntification	
Claim Types 🧳	ID	Name	^	Serial Number			00074049				
				Hardware Numbe	r		32334155 AA				
Technical Journals	4/211	Restraint Module Left (RML)		Diagnostic Numb	er		31654970 AT				
Service Programs	4/212	Restraint Module Right (RMR)		Software Number			32387046 AN				
Operations and Packages				Software Number			32387047 AN				
Parts	1/126	Side Obstacle Detection Control Module Left (S	SODL)	Software Number			32387049 AN				
Software	4/127	Side Obstacle Detection Control Module Right ((SODR)	Software Number			32387050 AN				
	4/68	Steering Angle Sensor Module (SAS)		Software Number			32334837 AA				
Diagnostics	4/247	Steering Wheel Module (SWM)		Software Number			32334838 AA 32334839 AA				
Components				Software Number			32334840 AA				
Service Functions	4/176	Supplemental Restraint System Module (SRS)		Software Number			32334841 AA				
	4/313	Telematics and Connectivity Antenna Module (1	ГСАМ)	Software Number			32334842 AA				
	4/28	Transmission Control Module (TCM)	_								
	4/338	Vehicle Computational Unit 1 (VCU1)									
	4/314	Vehicle Gateway Module (VGM)									
	4/249	Wide Angle Vision Module (WAM)									
	4/312	Wireless Phone Charger (WPC)									



TJ Instruction 36254	

Method 2

If the Components screen cannot be reached due to lack of connection, the Hardware Part number can be read from the most recent vehicle readout:

VIDA										0	×
Home XC60 (18-), 2022, B420T, AWF8G5 X	c										
Planning & Diagnostics Software Inst	talla	tion	n Inf	ormation Service Journ	Click VIN to	view Vehicle D	Details	Q	≡	co	Ċ
AC			VIN: Y	YV4062RM4N1900821	Customer Name	5	List: .				
Mode	el/Yea	V	View I	Details		Select Hardware	e and Software	- 0	×		
Lists		Ve	hicle [Details VOC Details						59:10 A	AM V B
▲ Planning	Н	M	ehicle	Readout General Attributes	Hardware and Software	/ariant Attributes Options	Apply vehi	:le filter	Print	es	lr 🕨 🖵
Customer Symptom Codes		Not	el The	ese values are from the latest cor	nfirmed version.		Search	Q	\sim \sim	.03	
Claim Types 🥠		0	rder II	D:						-	Status
Technical Journals		S	P No:							5	tatus
Service Programs			4	Control Module	Part No.	Hardware Serial No.	Software Part No. 32340784		^		•
Operations and Packages				SODR	32340781	000012327531	32340764 32340706 32340785 32340786				
Parts				SRS	32221255	000001482634	32346070 32346464				
Software				SWM	31443891	000011907411	32381379 32266024				
Diagnostics							32334837 32334838 32334839 Locate TCAM Hardware Pai				
Components			Г				02004840	t NO.			
Service Functions			1	ТСАМ	32334155	00000074049	32334841 32334842 32387046 32387047 32387049				
				тсм	32240940	000011103105	32387050 32138639 32252985 32317010 32350048				
				VCU1	32316183	000050678979	22350397 32350398 23250290		~		
		4/19	97	Electronic Gear Selector Mo	odule (EGSM)	Read DTCs	S Erase All				
Client Version: 22.5.1.140										8	Help