



# Service Bulletin

Bulletin No.: 21-NA-142

Date: February, 2022

## TECHNICAL

**Subject: Front Brake Grind/Groan Noise After Sitting Overnight**

**This bulletin replaces PIT5805B. Please discard PIT5805B.**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2020	2021	5GAERBKW8LJ296460	5GAERBKW9MJ238780	All	All
Cadillac	XT5	2021	2021				
	XT6						
Chevrolet	Blazer	2021	2021	SOP 2021	July 1, 2021		
	Colorado	2021	2021				
	Traverse	2020	2021	1GNERKKW5LJ296020	1GNEVKKW9MJ238781		
GMC	Acadia	2021	2021				
	Canyon						

<b>Involved Region or Country</b>	North America, China, S. Korea, Israel, Chile, Uzbekistan, Russia, Middle East, Palestine, Columbia, Peru, Japan and GM Korea.
<b>Additional Options (RPOs)</b>	
<b>Condition</b>	Some customers may comment on hearing a brake noise on the first few stops. They may describe it as a grind/groan sound, and it may feel like ABS is active, but it is not.
<b>Cause</b>	The cause of the condition may be the front disc brake pad material.
<b>Correction</b>	Replace the front disc brake pads with the improved design service parts listed below. Refer to <i>Front Disc Brake Pads Replacement</i> in the Service Manual in SI. After replacement, perform the Brake Pad and Rotor Burnishing procedure. Refer to <i>Brake Pad and Rotor Burnishing</i> in the Service Manual Complete a minimum of 20 stop events.

### Parts Information

Causal Part	Description	Part Number	Qty
X	Pad Kit-Frt Disc Brk	85520396 (Acadia, Blazer, Enclave, Traverse, XT5 and XT6)	1
	Pad Kit-Frt Disc Brk	85139417 (Colorado, Canyon)	

### Warranty Information

Repairs made for the specific concern within this bulletin will be covered for a period of 24 months or 24,000 miles or 40,000 km, whichever occurs first.

Labor Operation	Description	Base Labor Time
2486198*	New Front Disc Brake Pads Replacement	Canyon/Colorado – 0.8 hr Enclave – 0.8 hr Traverse – 0.8 hr Blazer – 0.8 hr Acadia – 0.9 hr XT5 – 0.8 hr. XT6 – 1.3 hr

\*This is a unique Labor Operation for Bulletin use only.

<b>Version</b>	4
<b>Modified</b>	Released June 21, 2021 Revised June 30, 2021 – Replaced LTG Labor Operation with Unique Bulletin Labor Operation Revised July 13, 2021 – Updated Parts Information with New Replacement Service Part # 85520396. Revised January 27, 2022 – Updated Breakpoints

