

SIB 16 03 21

2022-02-23 **DELIVERY STOP: FUEL TANK**

This Service Information Bulletin (Revision 1) replaces SI B16 01 21 dated December 2021.

What's New (Specific text highlighted):

All necessary information included to complete the delivery stop

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

E-Series	Model Description	Production Date
G05	X5 Sports Activity Vehicle	December 15, 2021 – December 20, 2021
G06	X6 Sports Activity Coupe	December 15, 2021 – December 20, 2021
G07	X7 Sports Activity Vehicle	December 15, 2021 – December 20, 2021

AFFECTED VEHICLES

BMW AG has issued a Delivery Stop (effective December 22, 2021) on certain Model Year 2022 BMW vehicles that were produced between December 15, 2021 and December 20, 2021.

Vehicles which require this Delivery Stop to be completed will show it as "Open" when checked either in AIR, or in the "Service Menu" of DCSnet (Dealer Communication System).

SITUATION

A fuel leak may develop from the fuel tank.

CAUSE

Manufacturing defect in the tank.

CORRECTION

Replace the fuel tank.

PROCEDURE

Replace the fuel tank following Repair Instruction 16 11 030 Removing and installing fuel tank (without suctioning and filling fuel).

PARTS INFORMATION

Please refer to the weekly Parts Matrix for parts ordering information.

Only use and invoice the part number below.

Part Number	Description	Quantity
16 11 9426339	Plastic fuel tank	1

Additionally, refer to ETK and the applicable ISTA repair instructions for information about one-time use fasteners and/or component-specific information regarding additional or replacement screws, gaskets, and seals that need to be installed and claimed.

Part Retention

The parts replaced to perform and submit for this Delivery Stop repair procedure are the property of BMW NA.

Your center is responsible for the proper identification, storage, and documentation of these parts. They must be held in a secure retention area until notification of claim payment is made by BMW NA through DCSnet.

If these replaced parts are requested to be returned, a corresponding DCSnet Part Return tag will be generated.

Your center is responsible to follow any special rules and regulations that apply to returning these parts to BMW.

Any return requested Recall parts that are not received by the WPRC within 60 days of the claim credit date may be subject to debit.

CLAIM INFORMATION

Reimbursement for this Action will be via normal claim entry utilizing the applicable work package information below and the part number listed above.

Defect Code:	0016650200	G05 G06 G07 Replacing tank
		Out out out itspiceong tallic

Completion before the first vehicle delivery to a customer or the vehicle is already in the workshop

Work Pkg	Labor Operation	Description (Plus work)	Labor Allowance
# 1	00 71 975	Replace the fuel tank (includes draining and returning the fuel)	Refer to AIR
Or:			
# 2	00 71 976	Replacing fuel tank with electric rear seat bench (includes draining and returning the fuel)	Refer to AIR

Or:

The vehicle arrives at your center and this Action shows open (No other Main work will be performed or claimed during this workshop visit)

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 3	00 71 402	Replace the fuel tank (includes draining and returning the fuel)	Refer to AIR
Or:			
# 4	00 71 403	Replacing fuel tank with electric rear seat bench (includes draining and returning the fuel)	Refer to AIR

Only one of the flat rate labor operation codes listed above can be used for claim submission and reimbursement. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B16 03 21 WP 1), unless otherwise required by State law.

Alternative Mobility Solution (AMS) for Vehicle Owners (RO and Claim Comments Required)

This Recall repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement, claim this item under the Defect Code noted above as follows:

Sublet Code 2 - Itemize the AMS sublet amount on the repair order and in the claim comment section.

Please refer to SI B01 29 16 for additional information.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Please contact the Warranty department by either using the Live Chat that's available in the Warranty Documentation Portal or through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections
Parts inquiries	Submit an IDS ticket to the Parts Department