



Release date:

Transaction No:

6/22/2022

Condition

Applicable Vehicles					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All (except Routan)	2014-2023	All	All	All	All

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2015173/31	6/22/22	46-19-02	Addition of mandatory brake form and reference to Volkswagen Warranty Policy and Procedures Manual.
2015173/30	02/3/22	46-19-02	To include model year 2022 applicability.
2015173/28	6/4/2020	46-19-02	To include model year 2021 applicability.
2015173/1	6/11/07	V46-07-01	Original publication.



As extracted from the Volkswagen Warranty Policy and Procedures Manual, in order to support a positive customer experience, improve quality efforts and reduce repeat repairs, Volkswagen Warranty is introducing the new Brake Diagnostic Worksheet. More information can be found under the Warranty Heading of this Technical Service Bulletin.

When applying the brakes at highway speeds the following symptoms may occur:

- Brake Pedal pulsation
- Vibration felt in Vehicle Body
- Steering Wheel shakes

Technical Service Bulletin



46-19-02 - Brake Rotor, Vibration / Pulsation (U.S. Only)

Release date:

Transaction No:

6/22/2022

2015173/31

Technical Background

For brake vibration or pulsation concerns, brake rotor machining is allowed between 6 and 12 months or 6,000 and 12,000 miles (whichever comes first) from the warranty in service date.

Production Solution

No production change required.

Service



Note:

All policies and procedures outlined in this technical bulletin also apply to sublet brake rotor machining. Improperly machined brake rotors may cause brake pulsation/vibration after several months in service. The servicing facility will be responsible for these failures.

Procedure:

 Remove Wheels and separate Brake Calipers from Carrier as outlined in Repair Manual Group 44 in Elsa.

Brake Rotor Inspection

A detailed brake rotor inspection is needed to determine if the brake rotor should be machined or replaced.

Inspect the brake rotor friction surfaces on both sides of the brake rotor for:

- Severe discoloration (bluing)
- High heat surface damage (raised hard spots)
- Visible cracks



Note:

Brake rotors showing any of the above described conditions are **NOT** serviceable. Parts must be replaced in accordance with the Volkswagen Warranty Policy and Procedure Manual.

Please see the example pictures below of damage NOT covered under warranty.



Release date:

Transaction No:

6/22/2022



Figure 1: Brake pad imprint.



Figure 3: Brake pad imprint.



Figure 2: Brake pad imprint.



Figure 4: Brake pad imprint.



Release date:

Transaction No:

6/22/2022



Figure 5: Corrosion.



Figure 7: Corrosion, brake pad stuck to brake rotor.



Figure 6: Corrosion, brake pad stuck to brake rotor.



Figure 8: Corrosion, brake pad stuck to brake rotor.



Release date:

Transaction No:

6/22/2022



Figure 9: Brake pad stuck to brake rotor



Figure 11: Brake pad imprint.





Figure 10: Brake pad stuck to brake rotor.



Release date:

Transaction No:

6/22/2022



Disc Thickness Measuring

Technician must record the beginning thickness measurements on the back of the repair order.

Each brake rotor has the minimum allowed thickness cast, stamped or laser-etched into the rotor hub.

Measure the brake rotor thickness in 4 locations using a digital or mechanical caliper/micrometer.
 Measurements MUST be taken at the same distance from the brake rotor outer circumference to ensure consistency.







Transaction No:

Release date:

6/22/2022





The brake rotor thickness measurement must exceed the minimum specification <u>after</u> the machining process is completed in order to be re-used. If the brake rotor thickness measurement does not meet this requirement after machining, replace the brake rotor.

Brake Rotor Machining



All Brake Rotors must be machined.

Recommended on-car brake lathe is the PRO-CUT International ™ PFM 9.2 (or equivalent – can be locally sourced). This design of brake lathe will produce a surface quality which will provide proper brake performance without a brake pad to brake rotor break-in period.

To ensure that a high quality brake rotor finish is produced, brake lathe cutting tools must be maintained as directed by the lathe or tool manufacturer.

Technical Service Bulletin



46-19-02 - Brake Rotor, Vibration / Pulsation (U.S. Only)

Release date:

Transaction No:

6/22/2022


2015173/31



- Follow the brake lathe manufacturer's instructions for set-up and machining.
- Wash the brake rotor with a soap and water solution upon completion of resurfacing to remove all machining particles.




46-19-02 - Brake Rotor, Vibration / Pulsation (U.S. Only)



Transaction No:

Release date:





Always replace brake rotors in pairs (front axle or rear axle). Do not replace all 4 brake rotors unless it is required.

Technical Service Bulletin



46-19-02 - Brake Rotor, Vibration / Pulsation (U.S. Only)

Release date:

Transaction No:

6/22/2022

2015173/31



- Measure brake rotor lateral run out using a caliper and dial gauge set.
- Run out must not exceed 0.1mm after machining.
- If brake rotor exceed the 0.1mm specification after machining replace the applicable brake rotors.

Warranty

The Brake Diagnostic Worksheet is required to be filled out and uploaded to Doc-IT for warranty reimbursement on all Brake claims including repair/replacement of Discs/Drums and Pads/Shoes, DICE claims where the Customer's concern involves Brakes and applicable Technical Service Bulletins. Claims may be subject to cancellation when the worksheet is incomplete or missing.

This new worksheet was developed to provide greater detail and assist with documenting the warranty justification. For your convenience, the worksheet can either be completed electronically online and saved to your files or downloaded and printed. The Brake Diagnostic Worksheet replaces the Brake Disc Measurement Form.

The Brake Diagnostic Worksheet is located in WISE under Resource Center > Forms > Brakes and is also located on the attachment page of Technical Service Bulletin 2010245, 2015173 and 2067177 within Elsa.



All documentation is needed for reimbursement and must be uploaded to WISE. For information on uploading documents and pictures in WISE, go to WISE > Resource Center > Dealer Processes & Guide, select pdf file: Wise Operations Section - Doc-IT Technical Bulletin Uploading Process Job Aid.



Release date: 6/22/2022

Transaction No:

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies
and Procedures Manual ¹⁾

Model(s)	Year(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From	VIN Range To
All (except Routan)	2014-2023	All	All	All	All

Claim Type: Use applicable Claim Type 1)

SAGA Coding

Service Number	Damage Code	HST	Damage Location	
4650	0013		001 – Left 002 – Right	
4653	0013	001 – Left 002 – Right		
	Passat, CC, Tiguan, Eos and MY14 Golf ,Atlas, A ID.4	WWO ²⁾		
Parts Manufacturer	Jetta, Beetle, Beet SportWagen and MY15 Alltrack, Tig	3ME ²⁾		

On Car Lathe is available (All vehicles)

Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = See Elsa for latest time units		
Labor Operation 3): Front and Rear Rotor Resurfacing – On Vehicle	46504699 = 120 TU And		
	46534699 = 120 TU		

Or



Release date: 6/22/2022

Transaction No:

If On Car Lathe is unavailable:				
CC/Tiguan	n/Eos/Arteon			
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = See Elsa for latest time units			
Labor Operation 3): Remove and Reinstall Front and Rear Carriers	46142050 = See Elsa for latest time units And 46152050 = See Elsa for latest time units			
Labor Operation 3): Remove and Reinstall Front and Rear Rotors	46502050 = See Elsa for latest time units And 46532050 = See Elsa for latest time units			
Labor Operation 3): Front and Rear Rotor Machining	46504699 = 160 TU And 46534699 = 160 TU			
(OR			
Tigua	an LWB			
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = See Elsa for latest time units			
Labor Operation 3): Remove and Reinstall Front and Rear Carriers	46142050 = See Elsa for latest time units And 46152050 = See Elsa for latest time units			
Labor Operation 3): Remove and Reinstall Front and Rear Rotors	46502050 = See Elsa for latest time units And 46532050 = See Elsa for latest time units			
Labor Operation 3): Front and Rear Rotor Machining	46504699 = 160 TU And 46534699 = 160 TU			
OR				



Release date: 6/22/2022

Transaction No:

Atlas/Atlas Cross Sport					
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = See Elsa for latest time units				
Labor Operation 3): Remove and Reinstall Front and Rear Carriers	46142050 = See Elsa for latest time units And 46152050 = See Elsa for latest time units				
Labor Operation 3): Remove and Reinstall Front and Rear Rotors	46502050 = See Elsa for latest time units And 46532050 = See Elsa for latest time units				
Labor Operation 3): Front and Rear Rotors Machining	46504699 = 160 TU And 46534699 = 160 TU				
	Or				
Pa	essat				
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = See Elsa for latest time units				
Labor Operation 3): Remove and Reinstall Front and Rear Rotors	46502050 = See Elsa for latest time units And 46532050 = See Elsa for latest time units				
Labor Operation 3): Front and Rear Rotors Machining	46504699 = 160 TU And 46534699 = 160 TU				
Or					
Jetta, Beetle, Beetle Cabrio and MY14 Jetta SportWagen					
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = See Elsa for latest time units				

Transaction No:

Release date:



46-19-02 - Brake Rotor, Vibration / Pulsation (U.S. Only)

Labor Operation 3): Remove and Reinstall Front and Rear Brake Carriers	46142050 = See Elsa for latest time units And 46152050 = See Elsa for latest time units		
Labor Operation 3): Remove and Reinstall Front and Rear Rotors	46502050 = See Elsa for latest time units And 46532050 = See Elsa for latest time units		
Labor Operation 3): Front and Rear Rotors Machining	46504699 = 160 TU And 46534699 = 160 TU		
	Or		
Τοι	uareg		
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = See Elsa for latest time units		
Labor Operation 3): Remove and Reinstall Front and Rear Rotors	46502050 = See Elsa for latest time units And 46532050 = See Elsa for latest time units		
Labor Operation 3): Front and Rear Rotors Machining	46504699 = 160 TU And 46534699 = 160 TU		
	Or		
MY15-22 Golf Sp	ortWagen, Alltrack		
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = See Elsa for latest time units		
Labor Operation 3): Remove and Reinstall Front Carrier	46142050 = See Elsa for latest time units		

Transaction No:

Release date:



46-19-02 - Brake Rotor, Vibration / Pulsation (U.S. Only)

Labor Operation 3): Remove and Reinstall Front and Rear Rotors	46502050 = See Elsa for latest time units And 46532050 = See Elsa for latest time units (includes		
	carrier)		
Labor Operation 3): Front and Rear Rotors	46504699 = 160 TU		
Machining	And 46534699 = 160 TU		
	Or		
	4 Golf		
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = See Elsa for latest time units		
Labor Operation 3): Remove and Reinstall Front and Rear Carrier	46142050 = See Elsa for latest time units And		
	46152050 = See Elsa for latest time units		
Labor Operation 3): Remove and Reinstall Front and Rear Rotors	46502050 = See Elsa for latest time units And		
	46532050 = See Elsa for latest time units		
Labor Operation 3): Front and Rear Rotors	46504699 = 160 TU		
Machining	And		
	46534699 = 160 TU		
	Or		
MY15-22 Golf/	GTI/Golf R/eGolf		
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	44052004 = See Elsa for latest time units		
Labor Operation 3): Remove and Reinstall Front Carrier	46142050 = See Elsa for latest time units		

Transaction No:

Release date:



46-19-02 - Brake Rotor, Vibration / Pulsation (U.S. Only)

Labor Operation 3): Remove and Reinstall Front and Rear Rotors	46502050 = See Elsa for latest time units And 46532050 = See Elsa for latest time units (includes carrier)		
Labor Operation 3): Front and Rear Rotors Machining	46504699 = 160 TU And 46534699 = 160 TU		
	Or		
I	D.4		
Front Brake	e Service Only		
Labor Operation 3): Remove and Reinstall Front Wheels	44052000 = See Elsa for latest time units		
Labor Operation 3): Remove and Reinstall Front Brake Carriers	46142050 = See Elsa for latest time units		
Labor Operation 3): Remove and Reinstall Front Rotors	46502050 = See Elsa for latest time units		
Labor Operation 3): Machining Front Rotors	46504699 = 160 TU		
Т	aos		
Front Brake	e Service Only		
Labor Operation 3): Remove and Reinstall Front Rotors	46502000 = See Elsa for latest time units		
Labor Operation 3): Machining Front Rotors	46504699 = 160 TU		
Rear Brake	Service Only		
Labor Operation 3): Remove and Reinstall Rear Rotors	46532000 = See Elsa for latest time units		
Labor Operation 3): Machining Rear Rotors	46534699 = 160 TU		

OR



Release date:

Transaction No:

6/22/2022

Front and Rear Brake Service					
Labor Operation 3): Remove and Reinstall Front and Rear Wheels	d	44052004 = See Elsa for latest time units			
Labor Operation 3): Remove and Reinstall Front and Rear Carriers	Labor Operation 3): Remove and leinstall Front and Rear Carriers			for latest time units	
Labor Operation 3): Remove and Reinstall Front and Rear Rotors		and	6502050 = See Elsa for latest time units nd 6532050 = See Elsa for latest time units		
Labor Operation 3):Front and Rear Rotors Machining		46504699 = 160 TU and 46534699 = 160 TU			
Or					
	If sul	blet machining	is usec	i:	
Outside Labor: Sublet Machining			Sublet	Machining not to exceed Elsa SRT	
Causal Part:		Select Labor			
Diagnostic Time ⁴⁾					
GFF Time expenditure	GFF Time expenditure 01500000 = 00 TU max. NO		NO		
Road Test	01210002 = 10 TU 01210004 = 10 TU			YES	
Technical Diagnosis	gnosis 01320000 = 00 TU max. NO		NO		
Claim Comments lead ("As you Tasky is al Dullatic 0045470" in a comment as at one of Warrant Claim					

Claim Comment: Input "As per Technical Bulletin 2015173" in comment section of Warranty Claim.

Page 17 of 18 Plus attachment

¹⁾ Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.

²⁾ Code per warranty vendor code policy.

³⁾ Labor Time Units (TUs) are subject to change with Elsa updates.

⁴⁾ Documentation required per Warranty Policy Procedures Manual.



Release date:

Transaction No:

6/22/2022

Required Parts and Tools

No Special Parts required.

Suggested tools and tool part numbers are current at the time of publication and listed below. (*Equivalent tools can be used or locally sourced as needed).

Suggested Brake Lathe								
Description	Part No:	Quantity						
PFM 9.2	PCI92BASEIBT	1						
Suggested Brake Measuring Tools								
Caliper and Dial Gauge Set	VAS6668	1						

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.



Volkswagen Brake Diagnostic Worksheet

completed electro	onically or printed.	rksheet is required for Completed forms mus Procedures Manual to	t be up	loaded to D	oc-IT upon SAG	A clair	n submission. Alwa	ays, refer to th	ne	
Dealer Code:										
Repair Order:										
Odometer:										
Date:										
VIN:										
•										
MANDATORY This section must be completed in its entirety.										
				n Finding		1:4:		l lee		
Manufacturers D	Defect: Applicable Technical Bulletin				The following conditions are not covered by Warranty:					
Cracks		2010245		•	Rust/Corrosion	n				
O Breaks		2015173		•	Brake pad ma	rk				
O Porous Cas	sting	O None		•	Discoloration ((bluing	g)			
Other:				•	High heat dam	nage (raised hard spots))		
What is the cond	ern the custome	r is experiencing?	Check a	all that apply	/.					
Brake Noise		O Vibration		O Pulsa		\circ	Corrosion/Discolo	oration		
				<u> </u>				What's the	е	
Location of the concern	How often does it occur?	When does it happen?		hat speed s it occur?	Is the vehic	le?	Road Condition	outside condition		
			<5 MPH		· airiiiig zoit	0		Freezing (\supset	
Front Right O	A.M./P.M. O		5-24 MI 25-49 N	<u>~</u>	Turning Right Going Uphill	<u> </u>	Rough (gravel) C	i tommai	$\frac{2}{3}$	
Rear Right O	Intermittent O	_	50-70 N		Going Downhill	Ö	Wet	Rain (Ŏ	
Other:	Other:	•	>70 MF	ч С		0	Dry C	_	\supset	
		Other:	Other:	C	Reverse Other:	$\frac{\circ}{\circ}$	Other:	Humid (\approx	
								0)	
Other conditions n	ot listed above:									
		Is the Technician	able to	o duplicate	the concern?					
Yes 🔘			No 🔘							
If the repair is	warrantable, procee	ed with claiming in SAG	A		Review DICE po	licy for	potential reimburse	ment		
Additional notes (c	optional):									