



# TECHNICAL SERVICE BULLETIN

## Various Drivability Concerns With Powertrain Malfunction (Wrench) Indicator And DTCs P1601/P061A

22-2280

12 July 2022

### Model:

<b>Ford</b> 2020-2021 Mustang GT500
--

**Issue:** Some 2020-2021 Mustang GT500 vehicles may experience erratic and harsh shifting at highway speeds and/or perceived lack of power when accelerating from a stop, with a powertrain malfunction (wrench) indicator and diagnostic trouble codes (DTCs) P1601 and/or P061A stored in the powertrain control module (PCM) while using SelectShift™. This may be due to the software in the PCM. To correct the condition, follow the Service Procedure to reprogram the PCM.

**Action:** Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2020-2021 Mustang GT500
- At least one of the following:
  - Erratic and/or harsh shifting at highway speeds
  - Perceived lack of power when accelerating from a stop
  - Illuminated powertrain malfunction (wrench) indicator light with DTCs P1601 and/or P061A stored in the PCM

**Warranty Status:** Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

### Labor Times

Description	Operation No.	Time
2020-2021 Mustang GT500 - Retrieve DTCs And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	222280A	0.4 Hrs.

### Repair/Claim Coding

Causal Part:	RECAL
Condition Code:	04

### Service Procedure

1. Reprogram the PCM using the latest software level of the appropriate Ford diagnostic scan tool.

© 2022 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.