



GROUP
ENG

MODEL
2020-2021MY
Soul (SK3)
2021MY
Seltos (SP2)

NUMBER
227 (Rev 2, 07/14/2022)

DATE
February 2021

TECHNICAL SERVICE BULLETIN

SUBJECT:

**SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)**

* NOTICE

This bulletin has been revised to include additional information. New/revised sections of this bulletin are indicated by a black bar in the margin area.

This bulletin provides the procedure to improve the logic of the Engine Control Module (ECM) on some 2020-2021MY Soul (SK3) vehicles and 2021MY Seltos (SP2) vehicles produced in the date ranges shown below, equipped with NU 2.0L ATK engines, which may exhibit engine starting related DTC P0605 and/or thermostat related DTC P2181. To correct this concern, follow the flowchart on page 2, then perform the Coolant Discharge procedure using KDS (for DTC P2181) if applicable, and/or apply the improved logic to the Engine system using the KDS ECU Upgrade function as described in this bulletin. For confirmation that the latest reflash has been applied to a vehicle you are working on, verify the ROM ID using the table on page 8 of this bulletin. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.

DTC P0605: Internal Control Module Read Only Memory (ROM) Error

DTC P2181: Thermostat Continuous Monitor Error

Model	Event No.	Production Date Range
Soul (SK3)	519	November 24, 2018 to October 24, 2020
	618	October 25, 2020 to January 4, 2021
Seltos (SP2)	520	November 20, 2019 to October 15, 2020
	619	October 16, 2020 to January 13, 2021

* NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.


This issue number is SA463.

Printed TSB copy is for reference only; information may be updated at any time.
Always refer to KGIS for the latest information.

Circulate To: General Manager Service Manager Parts Manager
 Service Advisors Technicians Body Shop Manager Fleet Repair

**SUBJECT: SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)**

Service Procedure Flowchart:



SUBJECT:

SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)

Coolant Discharging Mode Procedure:

- **NOTE:** If DTC P2181 has been stored, follow the procedure outlined below.
- **If DTC P2181 is not stored**, go directly to the 'ECU Upgrade Procedure' on page 7.

Required Conditions needed before starting the Coolant Discharging Mode Procedure	
1.	Transmission: Park (P) position / Parking Brake: ON
2.	Engine: Idling
3.	Vehicle speed: 0 mph
4.	Heater: OFF
5.	Conduct procedure indoors to raise temperature of coolant NOTE: If necessary, conduct vehicle soaking to lower the vehicle temperature


1. Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.



2. With the ignition ON, turn ON the KDS tablet. Select **KDS** from the home screen.




3. Confirm communication with VCI (A) and then configure the vehicle (B) using the **AUTO VIN** (C) feature.




**SUBJECT: SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)**

2. From the Systems / Engine Control menu, select 'Coolant Discharging Mode of Electric Thermostat' (D).

*** NOTICE**
The KDS screenshot(s) shown are from a 2021MY Seltos (SP2). Your screens may be displayed slightly different.



3. Select 'OK'.



SUBJECT:

SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)

4. Confirm the following conditions listed below are present, then select 'OK'.

1.	Transmission: Park (P) position / Parking Brake: ON
2.	Engine: Idling
3.	Coolant temperature: 32 - 78°F
4.	Vehicle speed: 0 mph
5.	Heater: OFF
6.	Conduct procedure indoors to raise temperature of coolant

NOTE: If necessary, conduct vehicle soaking to lower vehicle temperature.

S/W Management

■ Coolant discharging mode of electric thermostat

● [Coolant discharging mode of electric thermostat (ECT)]

By supplying current on the electronic thermostat, the abnormal residual coolant inside the thermostat is expelled.

●[Condition]

1. Transmission : P position / Parking brake: Operating
2. Engine : Idling
3. Temperature of coolant : 0~30°C(32~86°F)
4. Vehicle speed : 0 km/h
5. Status of heater operation : OFF
6. Carry out indoors for raising the temperature of coolant

[OK] button: Proceed with the function
[Read] button: Check the current temperature of coolant
[Cancel] button: End the function

OK Read Cancel

! Do not touch any system buttons while performing this function.

5. Wait for 180 seconds (3 minutes).

S/W Management

■ Coolant discharging mode of electric thermostat

● [Coolant discharging mode of electric thermostat (ECT)]

ECT has entered into the coolant discharging mode.

[Cancel] button: Stop the function

Current temperature of coolant : 32.0 'F


Remaining time : 179 second(s)

Cancel



**SUBJECT: SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)**

6. When the procedure is completed select **'OK'**.



7. Proceed to **'ECU Upgrade Procedure'** on page 7.



SUBJECT:

SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181 ECM LOGIC IMPROVEMENT (SA463)

ECU Upgrade Procedure:

To correct this condition, the ECU should be reprogrammed using the KDS download, as described in this bulletin.

Upgrade Event Name
519. [November 24, 2018 to October 24, 2020] SK3 NU 2.0ATK ENGINE MIL ON DTC JUDGMENT LOGIC IMPROVEMENT
618. [October 25, 2020 to January 4, 2021] SK3 NU 2.0ATK ENGINE MIL ON DTC JUDGMENT LOGIC IMPROVEMENT
520. [November 20, 2019 to October 15, 2020] SP2 NU 2.0ATK ENGINE MIL ON DTC JUDGMENT LOGIC IMPROVEMENT
619. [October 16, 2020 to January 13, 2021] SP2 NU 2.0ATK ENGINE MIL ON DTC JUDGMENT LOGIC IMPROVEMENT


* NOTICE

- A **fully charged battery** is necessary before the ECU upgrade can take place. It is recommended that a battery charger is used in ECU mode during the reflash or the use of a fully charged jump starter box connected to the battery.
- Ensure the KDS is sufficiently charged at 50% or higher prior to reflash.
- All ECU upgrades must be done with the ignition key in the 'ON' position.
- **Be careful not to disconnect the VCI-II connected to the vehicle during the ECU upgrade procedure.**
- **DO NOT** start the engine during ECU upgrade.
- **DO NOT** turn the ignition key 'OFF' or interrupt the power supply during ECU upgrade.
- When the ECU upgrade is completed, turn the ignition 'OFF' and wait 10 seconds before starting the engine.
- **ONLY** use approved ECU upgrade software designated for the correct model and model year.

❗ IMPORTANT

It is recommended to **ALWAYS** check the Electronic Parts Catalog (EPC) to locate the ECU Part Number respective to Auto/Manual Mode ROM IDs. **DO NOT** reference the parts label affixed to the ECU.

* NOTICE


Before attempting an ECU upgrade on any Kia model, make sure to first determine whether the applicable model is equipped with an immobilizer  security system. Failure to follow proper procedures may cause the PCM to become inoperative after the upgrade and any claims associated with this repair may be subject to chargeback.




SUBJECT:

**SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)**


ROM ID INFORMATION TABLE:**Upgrade Event #519 (SK3) (Production date range: November 24, 2018 – October 24, 2020)**

Model	MY	TM	IMMO 	ECU P/No.	ROM ID	
					Previous	New
SK3 (Nu 2.0L ATK)	2020	CVT	Yes	39171 2ELC0	SKASP2KS6B0A SKASP2KS6B1A	SKASP2KF6B7A
			No	39173 2ELC0	SKASP2JS6B0A SKASP2JS6B1A	SKASP2JF6B7A
		6MT	Yes	39171 2ELD0	SKAUP2AS6B0A SKAUP2AS6B1A SKAUP2AS6B1B	SKAUP2AF6B7A
			No	39173 2ELD0	SKAUP2US6B0A SKAUP2VS6B1A SKAUP2VS6B1B	SKAUP2UF6B7A
	2021	CVT	Yes	39171 2ELC1	SKBSP2KS6B2A	SKBSP2KS6B7A
			No	39173 2ELC1	SKBSP2JS6B2A	SKBSP2JS6B7A
		6MT	Yes	39171 2ELD1	SKBUP2AS6B2A	SKBUP2CS6B7A
			No	39173 2ELD1	SKBUP2US6B2A	SKBUP2VS6B7A


Upgrade Event #618 (SK3) (Production date range: October 25, 2020 – January 4, 2021)

Model	MY	TM	IMMO 	ECU P/No.	ROM ID	
					Previous	New
SK3 (Nu 2.0L ATK)	2021	CVT	Yes	39171 2ELC1	SKBSP2KS6B2A	SKBSP2KF6B7A
			No	39173 2ELC1	SKBSP2JS6B2A	SKBSP2JF6B7A
		6MT	Yes	39171 2ELD1	SKBUP2AS6B2A	SKBUP2CF6B7A
			No	39173 2ELD1	SKBUP2VS6B2A	SKBUP2VF6B7A

Upgrade Event #520 (SP2) (Production date range: November 20, 2019 – October 15, 2020)

Model	MY	TM	IMMO 	ECU P/No.	ROM ID	
					Previous	New
SP2 (Nu 2.0L ATK)	2020	CVT	Yes	39171 2EPT0 39171 2EPV0	SPAUP2KS6D2A	SPAUP2KS6D5A
			No	39173 2EPT0 39173 2EPV0	SPAUP2JS6D2A	SPAUP2JS6D5A

Upgrade Event #619 (SP2) (Production date range: October 16, 2020 – January 13, 2021)

Model	MY	TM	IMMO 	ECU P/No.	ROM ID	
					Previous	New
SP2 (Nu 2.0L ATK)	2021	CVT	Yes	39171 2EPT0 39171 2EPV0	SPAUP2KS6D2A	SPAUP2KF6D5A
			No	39173 2EPT0 39173 2EPV0	SPAUP2JS6D2A	SPAUP2JF6D5A

To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.

Printed TSB copy is for reference only; information may be updated at any time. Always refer to KGIS for the latest information.

TSB: SA463 (Rev 2) Soul (SK3), Seltos (SP2) February 2021



SUBJECT:

SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)

*** NOTICE**

Prior to performing the ECU upgrade, be sure to check that the KDS is fully charged.

1. Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.

*** NOTICE**


The ECU upgrade function on KDS operates wirelessly. It is not necessary to perform the upgrade via USB cable.




2. With the ignition ON, turn ON the KDS tablet. Select **KDS** from the home screen.



3. Confirm communication with VCI (A) and then configure the vehicle (B) using the **AUTO VIN** (C) feature.



4. Select **ECU Upgrade**.




**SUBJECT: SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)**

5. The KDS will check the server for recently uploaded Events and then automatically download **Upgrade Event**:

- #519 (SK3) (11/24/2018-10/24/2020)
OR –
- #618 (SK3) (10/25/2020-1/4/2021)
OR –
- #520 (SP2) (11/20/2019-10/15/2020)
OR –
- #619 (SP2) (10/16/2020-1/13/2021)


*** NOTICE**
The vehicle must be identified in Vehicle Selection to download an Event for that vehicle.



KDS screenshot shown above is for demonstration purposes only. Events shown in screenshot are not applicable to this bulletin.

6. Select **Auto Mode**.

CAUTION
Do NOT attempt to perform a Manual Mode upgrade UNLESS Auto Mode fails. Always follow the instructions given on the KDS in either Auto or Manual mode.




7. Select the **Engine** system under the System selection menu.

Touch **ID Check (D)** and confirm that the latest update is available.

Select appropriate **Upgrade Event** listed below, and select **Upgrade** to continue.

- #519 (SK3) (11/24/2018-10/24/2020)
OR –
- #618 (SK3) (10/25/2020-1/4/2021)
OR –
- #520 (SP2) (11/20/2019-10/15/2020)
OR –
- #619 (SP2) (10/16/2020-1/13/2021)





SUBJECT:

SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)


8. The ECU upgrade will begin and the progress of the upgrade will appear on the bar graph. Upgrade part (1/2) (E) will download the upgrade event to the VCI-II. Upgrade part (2/2) (F) will upgrade the ECU.

CAUTION
Do not touch the system buttons (like 'Back', 'Home', 'etc.') while performing ECU Upgrade.




9. If a "Communication Fail" screen appears, verify that the VCI-II and KDS are communicating properly. Touch **OK** and restart the procedure from step 4.

*** NOTICE**
If an error notice continues to appear or if the upgrade cannot be performed, DO NOT disconnect the KDS/VCI-II. Contact GIT America Help Desk at (888) 542-4371 or Techline.




10. When instructed on the KDS, turn the ignition **OFF** for ten (10) seconds then back on. Touch **OK** to continue.




**SUBJECT: SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)**


11. Once the upgrade is complete, touch **OK** to finalize the procedure.



12. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.



13. Start the engine to confirm proper operation of the vehicle.



SUBJECT:

SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)

Manual Upgrade Procedure:**★ NOTICE**

The manual upgrade should ONLY be performed if the automatic upgrade fails.

If the automatic upgrade fails, turn the ignition OFF for about 10 seconds then place it back in the ON position to reset the control unit BEFORE performing manual upgrade.

See table below for Manual Mode passwords.

Manual Mode ECU Upgrade Passwords

No.	Menu	Password
#519 (SK3)	SK3 Nu 2.0 ATK CVT +IMMO/SMK (20MY): 39171-2ELC0	5191
	SK3 Nu 2.0 ATK CVT -IMMO (20MY): 39173-2ELC0	5192
	SK3 Nu 2.0 ATK 6MT +IMMO/SMK (20MY): 39171-2ELD0	5193
	SK3 Nu 2.0 ATK 6MT -IMMO (20MY): 39173-2ELD0	5194
	SK3 Nu 2.0 ATK CVT +IMMO/SMK (21MY): 39171-2ELC1	5195
	SK3 Nu 2.0 ATK CVT -IMMO (21MY): 39173-2ELC1	5196
	SK3 Nu 2.0 ATK 6MT +IMMO/SMK (21MY): 39171-2ELD1	5197
	SK3 Nu 2.0 ATK 6MT -IMMO (21MY): 39173-2ELD1	5198
#618 (SK3)	SK3 Nu 2.0 ATK CVT +IMMO/SMK (21MY): 39171-2ELC1	5191
	SK3 Nu 2.0 ATK CVT -IMMO (21MY): 39173-2ELC1	5192
	SK3 Nu 2.0 ATK 6MT +IMMO/SMK (21MY): 39171-2ELD1	5193
	SK3 Nu 2.0 ATK 6MT -IMMO (21MY): 39173-2ELD1	5194
#520 (SP2)	SP2 Nu 2.0 ATK CVT +IMMO/SMK (20MY): 39171-2EPT0/V0	5201
	SP2 Nu 2.0 ATK CVT -IMMO (20MY): 39173-2EPT0/V0	5202
#619 (SP2)	SP2 Nu 2.0 ATK CVT +IMMO/SMK (21MY): 39171-2EPT0/V0	5201
	SP2 Nu 2.0 ATK CVT -IMMO (21MY): 39173-2EPT0/V0	5202



SUBJECT:

SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)

1.	Within the ECU Upgrade screen displayed, select Manual Mode .
2.	<p>Select the Engine system under the System selection menu. Select appropriate Upgrade Event listed below, and select Upgrade to continue.</p> <ul style="list-style-type: none"> • #519 (SK3) (11/24/2018-10/24/2020) OR – • #618 (SK3) (10/25/2020-1/4/2021) OR – • #520 (SP2) (11/20/2019-10/15/2020) OR – • #619 (SP2) (10/16/2020-1/13/2021)
3.	Select the appropriate control unit part number with reference to the ROM ID Information Table on page 8, and select OK .
4.	Enter the appropriate password from the Manual Mode password table above and select OK .
5.	The upgrade will begin and the progress of the upgrade will appear on the bar graph.
6.	When instructed on the KDS, turn the ignition OFF for ten (10) seconds then back on. Touch OK to continue.
7.	Once the upgrade is complete, touch OK to finalize the procedure.
8.	When prompted, select YES to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.
9.	Start the engine to confirm proper operation of the vehicle.



SUBJECT:

SERVICE ACTION: MIL ON DTC P0605 AND/OR P2181
ECM LOGIC IMPROVEMENT (SA463)

AFFECTED VEHICLE RANGE:

Model	Production Date Range
Soul (SK3)	November 24, 2018 to January 4, 2021
Seltos (SP2)	November 20, 2019 to January 13, 2021

WARRANTY INFORMATION:

N Code: N99 C Code: C99

Model	Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
ALL	V	39171 2EPT0	0	(SA463) KDS Additional Function and ECM Logic Improvement	210005R0	0.4 M/H	N/A	0
				(SA463) ECM Logic Improvement	210005R1	0.3 M/H		

*** NOTICE**

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference SA463 when accessing the WebDCS system.

