

### **Volvo DEF Level (UQLS) Sensor Troubleshooting Guide - US17+OBD16 Emissions and Newer**



## **Overview**



The Urea Quality Level Sensor (UQLS) is a smart sensor that is located in the top of the Urea (DEF) Tank, commonly referred to as the DEF Level Sensor or Combined Tank Unit. This smart sensor has Urea Quality, Level, and Temperature all integrated into it as one unit and reports on the DL7 (J1939-7) Datalink. This sensor is responsible for sending all the urea information to the Aftertreatment Control Module (ACM) and Engine Control Module (ECM).

# **Diagnosis and Repair**



If any of the codes in yellow below appear on the Readout in Active or Confirmed status: Continue to the diagnostic steps in the following section.

Article

DTC	DTC Description		
P205B64	Reductant Tank Temperature Sensor, Circuit		
	Range/Performance		
P203A13	Reductant Level Sensor "A", Open Circuit		
P203C00	Aftertreatment Reagent Level, Short Circuit Low		
P206A13	Reductant Quality Sensor, Open Circuit		
P206C00	Reductant Quality Sensor, Short Circuit Low		
P206B64	Reductant Quality Sensor Range/Performance		
P205A13	Reductant Tank Temperature Sensor, Open Circuit		
P205C00	Aftertreatment Reagent Tank Temperature, Short Circuit Low		

#### DO NOT REPLACE the DEF Level Sensor for any of the codes

**in green below:** <u>DO NOT</u> proceed with the diagnostics steps in this solution. None of these codes immediately indicate a failed DEF Level Sensor. Use the table in conjunction with PTT's Guided Diagnostics to find the root cause.

DTC	DTC Description	Probable Source		
P203F00	Reductant Level	Commonly low DEF quantity or		
	Low	level sensor float in DEF tank stuck		
P203B00	Aftertreatment			
	Reagent Level	System fault. Follow Guided Diagnostics.		
	Warning			
U02A200	Lost			
	Communication	Commonly a wiring harness or connection		
	with Reductant	issue.		
	Quality Module			
P24FF00	Reductant	DEF tank temp above 70°C (160°F).		
	Temperature Too	Commonly the coolant lines to the DEF tank		
	High	are swapped.		
P207F00	Deductort Ouglity	DEF quality low and SCR efficiency low.		
	Reductant Quality	Commonly a DEF quality issue.		

## **Diagnostic Steps For Yellow Codes**


- **1.** Check the sensor wiring harness connection.
  - Disconnect the harness and make sure there is no damage to the wires or pins, corrosion, or water ingress in either of the connectors. If damage is found replace in accordance with
- echnical Service Bulletin 258-040 Aftertreatment Diesel Exhaust Fluid (DEF) Tank, Level Sensor, Replacement. Located in Impact.

- **1.** Navigate to the Service tab.
- 2. In the Info Type box, make sure Technical Service Bulletins is selected.
- 3. In the Additional search values box select Keyword
- **4.** Enter 258-040 into the text entry box, press the Search button.
- **5.** A link for the article will be shown in the results. Click on the title, then choose one of the options from the window that opens.



- 2. Verify the DEF quality is at an acceptable value.
  - Use refractometer part number 88890105 to verify the DEF quality. See illustration below.





- **3.** Verify that the DEF tank is not frozen.
- 4. Ensure that the DEF tank is adequately filled.
- 5. Clear the Fault Codes.
- 6. Start the engine. Run the engine on high idle for 2 minutes at 1000 rpm or higher.
- 7. Turn the Engine Off, Key Off for 15 seconds.
- **8.** Start the engine. Run the engine on high idle for 2 minutes a second time.

#### **Evaluate the Results**


If any of the faults shown in the yellow chart above return active:

Replace the DEF Level Sensor in accordance with Impact instructions and the wires routed as shown in Technical Service Bulletin 258-040.

If none of the faults in the yellow chart above return: No troubleshooting or replacement of the DEF Level Sensor is necessary.

## **Rules for Replacement**

- · Warranty will only cover replacement of the UQLS if one of the codes in Yellow section above is present. If the UQLS is suspected to have failed with no codes present, an eService case is required for further evaluation.
- Standard Diagnostic Time for a DEF Level Sensor is 0.6 hrs.



unlocking uptime p203f00

#### **Related links and attachments**

FSB 258-040



#### Give feedback

to help improve the content of this article

# Aftertreatment Diesel Exhaust Fluid (DEF) Tank, Level Sensor, Replacement

M-258-040

June (2021)

#### Valid for

Mack Truck models built before October 21, 2019, equipped with Diesel Exhaust Fluid (DEF) tank.

## Case description

On certain Mack truck models built before October 21, 2019, equipped with Diesel Exhaust Fluid (DEF) tank, the vehicle may experience water intrusion into the level sensor protection tubing. This may be due, in part, to kinking of electrical routing protective tubes. The solution is to replace the existing level sensor assembly with new level sensor assembly and follow improved electrical routing.

#### **Parts**

Description		Old part	New part
Frame Rail-	DEF tank, 70-	23045836	23539939
Mounted	liter Capacity		
Tank	DEF tank, 45-	23045833	23539937
	liter Capacity		
	DEF tank, 70-	3045847	23045847
	liter Capacity		
	(Cummins		
	Only)		
Combination	DEF tank 25	23045822	23539923
Mounted	/33- Liter		
Tank	Capacity		
	DEF tank 25	23045830	23539935
	/33- Liter		
	Capacity		
	DEF tank 25-	23045843	23634004
	Liter		
	Capacity		
	(Cummins		
	Only)		

# Frame-mounted DEF tank with Volvo engine

. Maintain minimum 40 mm bend radius of UQLS (Urea Quality and Level Sensor) control module routing (A) at sensor head.

Note: Do not kink the UQLS control module routing.

Copyright to this documentation belongs to the Volvo Group. No reproduction, copying, change, amendment or other similar disposal is entitled without prior written consent by

The information contained herein is current at the time of its original distribution, but is subject to change. The reader is advised that printed copies are uncontrolled.



. Route and tie the UQLS control module routing with the urea harness.

Note: Use regular cable tie (B).



Copyright to this documentation belongs to the Volvo Group. No reproduction, copying, change, amendment or other similar disposal is entitled without prior written consent by the Volvo Group


The information contained herein is current at the time of its original distribution, but is subject to change. The reader is advised that printed copies are uncontrolled.

. Route and tie the UQLS control module routing with the electrical harness.

Note: Use helicopter cable tie (C).


. Route and tie UQLS control module routing with the coolant lines.

Note: Use double head cable tie (D).



. Maintain minimum 40 mm bend radius of UQLS control module routing(A) at electrical junction box.

Note: Do not kink the UQLS control module routing.




# Frame-mounted DEF tank with Cummins engine

. Maintain minimum 40 mm bend radius of UQLS (Urea Quality and Level Sensor) control module routing (A) at sensor head.

Note: Do not kink the UQLS control module routing.

. Route and tie the UQLS (Urea Quality and Level Sensor) control module routing with the coolant pipe.


Note: Use double head tie (B).




. Route and tie the UQLS control module routing with the bracket.

Note: Use cable tie (C).

Copyright to this documentation belongs to the Volvo Group. No reproduction, copying, change, amendment or other similar disposal is entitled without prior written consent by the Volvo Group





# Warranty information

This repair may be eligible for reimbursement if a product failure was experienced within time and mileage limits

Copyright to this documentation belongs to the Volvo Group. No reproduction, copying, change, amendment or other similar disposal is entitled without prior written consent by the Volvo Group

The information contained herein is current at the time of its original distribution, but is subject to change. The reader is advised that printed copies are uncontrolled.

of the applicable Warranty coverage. Reimbursement is obtained via the normal claim handling process.				
Claim Type (used only when uploading from the Dealer Bus. Sys.)	01			
Labour Code				
Primary Labour Code	2589-03-02-05			
Level sensor, tank, replace (includes harnesses routing)	0.2 –2.0 hrs			
	(Time varies per model)			
Causal Part	23539939, 23045833, 23045847			

Copyright to this documentation belongs to the Volvo Group. No reproduction, copying, change, amendment or other similar disposal is entitled without prior written consent by the Volvo Group