



Service Bulletin

Bulletin No.: 22-NA-149

Date: August, 2022

INFORMATION

Subject: Adding Cruise Control (RPO K34)

This Bulletin replaces PIT4844K. Please discard PIT4844K.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Express	2007	2022				
	Silverado 1500		2013				
	Silverado 2500/3500		2014				
GMC	Savana		2022				
	Sierra 1500		2013				
	Sierra 2500/3500		2014				

Involved Region or Country	North America
Condition	Some customers may request the installation of Cruise Control on a vehicle which did not come equipped with the option. General Motors requests that dealers locate a vehicle equipped with the customers requested options, which would include cruise control.

Recommendations / Instructions

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Please contact the Techline Customer Support Center (TCSC) at 1-800-828-6860 English or 1-800-503-3222 French to determine if a calibration is available for the vehicle. If a calibration or VCI is available, follow the instructions below:

1. Steering Wheel with Cruise Control Buttons
2. Steering Wheel SIR Coil

Note: *(If required, some Vans may have the uplevel Steering Wheel SIR Coil installed from the factory. The dealer will just need to document that the correct SIR Coil is already installed in the vehicle on the Repair Order when sending to Techline.)

3. Steering Column Wiring Harness

Note: *(If required, some Vans may have the uplevel Steering Column Wiring Harness installed from the factory. The dealer will just need to document that the correct harness is already installed in the vehicle on the Repair Order when sending to Techline.)

4. Calibration or VCI number from Techline Customer Support

Note: The Dealer will need to Fax a copy of the Repair Order that includes the Part Numbers of the Steering Wheel with buttons, SIR Coil, and Steering Column Harness that were installed to Techline before calling to obtain the VCI Number. (Some Vans may have the uplevel Steering Wheel SIR Coil and Steering Column Wiring Harness installed from the factory. The dealer will need to document that the correct P/N Steering Wheel SIR Coil and Steering Column Wiring Harness is already installed in the vehicle on the Repair Order when sending to Techline.)

Note: As this is a customer pay request, there will be a charge to the dealer. When the dealer contacts Techline they will be informed how much the fee for this request is.

Note: It is up to the dealer to identify the appropriate part numbers needed to complete this add on option using the Electronic Parts Catalog (EPC). Be sure to turn off all filters when searching EPC and identify the following items above that include RPO K34.

Note: DO NOT call Partech for parts assistance for this request.

Warranty Information

This installation procedure is to be performed at the customer's request and at their expense.

It is not a warranty repair and a claim should not be submitted for reimbursement.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

Version	1
Modified	Released July 27, 2022

