



# Preliminary Information

## PIC6466 DRL and/or Headlamp Operation With A Possible B108E Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Corvette	2022 - 2023	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may notice that the Daytime Running Lamps (DRL's) may not automatically turn on in daylight conditions. They may comment instead, that the headlamps are actually on during daylight conditions. Upon further inspection, technicians may find a B108E set as well, for the Ambient Light Sensor signal.
Concern	This concern is caused by a software anomaly. Replacing the Ambient Light Sensor may or may not resolve this issue, so it is recommended at this time that no parts be replaced for this concern.

### Correction:

For 2022 model year vehicles: The updated software is currently available in the Service Programming System (SPS) database. Reprogram the Body Control Module (BCM) with the current calibrations to resolve this concern.

For 2023 model year vehicles: The updated software is currently NOT available in the SPS database.

Once the new BCM software has been fully released for this concern, this PIC will be converted into a Bulletin. Current plans for this new software include an Over-the-Air (OTA) programming event, advise the customer to keep watch for any updates that are prompted by the Infotainment system and be sure to accept them.

Until the new software is available for all vehicles, when driving in low lighting situations, it is recommended to simply turn the headlamps on manually.

### Warranty Information

### Version History

Version	1
Modified	07/27/2022 - Created on.



GENERAL MOTORS