## WMP5 Workshop campaign — Check pressure sensors and replace if necessary

# WMP5 Workshop campaign - Check pressure sensors and replace if necessary

ID Number WMP5

Models Taycan (Y1A/Y1B)

Model Years 2020-2022

VIN list Attached below

Number of Affected VINs 3,774

Issue Description Due

Due to a manufacturing error at the supplier, pressure sensors for the refrigerant circuit were installed on the affected vehicles that do not meet the required speci-

fications.

The failure of one or more pressure sensors in the refrigerant circuit can therefore not be ruled out over the lifetime of the vehicle. As a result, there is a possibility that the air conditioning and battery cooling system will not function as normal. This can lead to an increased temperature of the high-voltage battery and, as a result, to reduced charging performance during fast charging, and possibly reduced driving performance.

What Dealers should do To prevent this from happening, the pressure sensors

must be checked and replaced if necessary.

As of the time of this posting, the repair is immediately available.

Parts can be ordered via PPL Order with no PRMS Ticket needed.

TI Number No. 199-21

## Parts required

1

Part No.	Designation	Quantity/vehicle *	Parts return **
V04015800AR	Pressure sensor	0 - 3 ea. (depending on scope) *	No
PAF106825	Hexagon-head bolt, M8 x 50	4 ea. (depending on sco- pe) *	No
N 10261307	Hexagon nut	2 ea. (depending on sco- pe) *	No

<sup>\*</sup> The exact requirement must be determined by checking the pressure sensors.

## Warranty processing

#### Validity:

This workshop campaign will be carried out up to December 9th, 2026 and will be closed on that date.

Please note that warranty claims can only be processed before this date.

#### **Scopes 1 - 8:**

Please note that each vehicle is assigned to all levels of service. The respective scope is determined **depending on the result of inspection**.

Damage Code WMP5 66 000

Repair Code 1/2

Working time 124 - 268 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

## **Customer Mobility**

If requested, transport for the affected customer can be guaranteed by offering a suitable replacement vehicle. Please invoice this additional service via WWS with the extent of service provided.

### **Further Information**

Work instruction TI No. 199/21, Group 8, Service, WMP5

Vehicle list and allocation Please see attached VIN list below

<sup>\*</sup>The parts must be stored until **such time as the related warranty or campaign claim** has been credited. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

WMP5 Workshop campaign - Check pressure sensors and replace if necessary

Technical Information\*

PCSS / AfterSales Document Database

\*The version published in PCSS is the definitive version.