



Technical Service Bulletin

94 PSS 3rd brake light warning, DTC B12C615 is stored

94 22 57 2067742/1 August 9, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3, S3, and RS 3	2022	All	Not Applicable

Condition

Customer states:

A warning for the 3rd brake light is displayed in the instrument cluster however the lamp continues to work normally.

Workshop findings:

- The warning is no longer displayed after the ignition is switched off and then on again.
- The wiring for the 3rd brake light is OK.
- The 3rd brake light works normally.

The following DTC is stored in the Electronic Central Electrical (BCM), J519 (address word 0009):

DTC B12C615 Bulb for high-mount brake light open circuit/short circuit to B+_intermittent.

Technical Background

The diagnostic software is too sensitive.

Production Solution



Technical Service Bulletin

A software solution is being prepared.

Service

1. Explain to the customer that a solution is expected to be available by the end of the 1st quarter of 2023 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Ensure there are no connection issues with the lamp. If the lamp is inoperative and the connections are ok, this PSS does not apply. In this case continue with normal diagnosis.



Note: There is no need to remove/replace suppression capacitor C24 in the wiring harness for the 3rd brake light.

3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under Related Links >> Service), or through the Technical Assistance page in Elsa.

Warranty

This TSB is informational only and not applicable to any Audi warranty.

Additional Information

All part and service references provided in this TSB (2067742) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time



Technical Service Bulletin

without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.