

# Subject:

MAZDA CONNECT SYMPTOM TROUBLESHOOTING [6TH GENERATION VEHICLES]

Service Alert No.: SA-001/22

Last Issued : 08/09/2022

# BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

Previous Service Alert:	Date(s) Issued:
SA-001/22	05/23/22, 03/17/22, 02/14/22 and 01/11/22
SA-019/21	11/16/21, 09/28/21, 09/01/21, 06/25/21, 04/08/21 and 02/2 6/21
SA-026/20	06/11/20 and 02/11/20
SA-065/17	08/10/17

## APPLICABLE MODEL(S)/VINS

2014-2018 Mazda3	2016-2021 CX-3	2016-2020 CX-9
2016-2021 Mazda6	2016-2020 CX-5	2016-2022 MX-5

# DESCRIPTION

Use the symptom troubleshooting tables below to diagnose MAZDA CONNECT concerns.

# **REPAIR PROCEDURE**

## Before proceeding:

- Confirm that the Connectivity Master Unit (CMU) is updated to the latest software version. Go to MGSS ->
  Infotainment -> MAZDA CONNECT Updates
- Go to TSB 16-001/20 to view MAZDA CONNECT CMU software fix list.
- Confirm that the customers device is compatible. Go to connect.mazda.com -> Support -> Compatibility.
- Confirm that the customers device is updated to the latest software version.
- Apple Carplay/Android Auto FAQ, go to SA-026/22.
- If you suspect a counterfeit Navi SD card, ask the customer for proof of purchase. It cannot be determined by
  visually looking at the label. If Mazda Toolbox is used and a counterfeit SD card is detected, the customer VIN
  may be locked-out.

# NOTE:

- If possible, complete any one of the Microsoft Forms Questionnaires. Go to MGSS -> Infotainment -> MAZDA CONNECT Questionnaire.
- Some customers may complain that on some roads, the speed limit shown in the navigation screen is different from the actual road signs.
  - Every time MAZDA CONNECT starts (boots up when ignition turns ON), the disclaimer notification is shown to notify that there are some difference between the navigation map data and actual road signs.
  - Lead time for updating the navigation map data takes 12 months.

# Index:

- No. 1 Blank Screen
- No. 2. Rear View Camera is not displayed
- No. 3 Rebooting
- No. 4 Infotainment System Has No Sound
- No. 5 Commander Switch Does Not Work
- No. 6 Bluetooth device will not pair
- No. 7 Incorrect GPS position
- No. 8 Voice Recognition Does Not Work
- No. 9 Cannot Make a Hands-Free Call
- No. 10 Cannot Play Bluetooth Audio
- No. 11 Other Symptoms
- No. 12 How to update the Navigation SD Card Map
- No. 13 How to Check Navi SD Card VIN Lock
- No. 14 How to Report Navigation Map Error or Missing Location

Page 2 of 17

# No. 1 Blank Screen

Step	Inspection	Result	Action
		Yes	Go to step 2.
1	Is the Rear View Camera displayed?	No	Refer to No. 2. Rear View Camera is not displayed 2016-2017 CX-9 - See 09-034/17
	Press the "HOME" button. Is the HOME	Yes	Normal Operation
۲	screen displayed correctly?	No	Go to step 3
3	Using M-MDS, are any infotainment	Yes	Go to MGSS for DTC diagnosis.
<u> </u>		No	Go to step 4.
П <u>Д</u> І		Yes	Go to step 5.
<u> </u>	port?	No	Go to step 6.
	_	Yes	USB device is not compatible.
	display function properly after USB device is disconnected?	No	Go to step 6.
	ie are connector for are contor Bioplay	Yes	Go to step 7.
<u> </u>		No	Insert the connector correctly.
7	Are the connectors for the CMU inserted correctly?	Yes	Go to step 8.
<u>′</u>		No	Insert the connectors correctly.
8	Is the center display voltage at 0920-	Yes	Go to step 9.
<u> </u>	304A terminal 1H, L wire color normal?	No	Go to step 10.
	Swap the Center Display with good	Yes	Check / Replace the Center Display.
	known vehicle. Is the screen display normal?		Go to step 10.
	Swap the CMU with good known vehicle. Is the screen display normal?	Yes	<ul> <li>Check / Replace the CMU.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>
		No	Repair / Replace wiring harness. Go to MGSS View Content -> Wiring Diagram -> Body and Accessories -> Entertainment System.

Page 3 of 17

## No. 2 Rear View Camera is not displayed

Step	Inspection	Result	Action
1	Using M-MDS, are any infotainment	Yes	Go to MGSS for DTC diagnosis
	system DTC's stored?	No	Go to step 2.
2	Is the vehicle equipped with 360 View Y Monitor?		Go to step 3.
2			Go to step 4.
3	Is the Front Camera and Side Cameras	Yes	Check / Replace the 360 View Monitor control unit.
	displayed normally?	No	Go to step 4.
			Go to step 5.
4	Are images other than the Rear View Camera displayed?	Yes	2014-2018 Mazda3 5-door HB 2016-2019 CX-3 Go to 09-031/20
		No	Go to No. 1 Blank Screen.
5	Is the connector for the Rear View Camera Inserted correctly?	Yes	Go to step 6.
5		No	Insert the connector correctly.
6	Is the connector for the Center Display Inserted correctly	Yes	Go to step 7.
0		No	Insert the connector correctly
7	Are the connectors for the CMU Inserted correctly	Yes	Go to step 8.
		No	Insert the connectors correctly
	Swap the Rear View Camera with good	Yes	Check / Replace the Rear View Camera
8	nown vehicle. Is the screen display ormal?	No	Go to Step 9
9	Swap the CMU with good known vehicle. Is the screen display normal?	Yes	<ul> <li>Check / Replace the CMU.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>
			Go to MGSS, WSM, REAR MOUNT CAMERA IMAGE NOT CLEAR/NO IMAGE ON SCREEN.

Page 4 of 17

Service Alert No.: SA-001/22	Last Issued : 08/09/2022
------------------------------	--------------------------

# No. 3 Rebooting

Step	Inspection	Result	Action
1	Using M-MDS, are any infotainment system DTC's stored?		Go to MGSS for DTC diagnosis
1			Go to step 2.
	Does the reboot continue after removing the Navigation SD card?		Go to step 3.
2			Check / Replace the Navigation SD card. <b>Note:</b> See TSB 09-015/20 if applicable
3	Is there a device connected to the USB port?	Yes	Go to step 4.
3	Is there a device connected to the USB port?	No	Go to step 5.
4	Disconnect the USB device. Does the reboot stop		USB device is not compatible
4	after USB device is disconnected?	No	Go to step5.
		Yes	Go to step 6.
5	Does the reboot continue after ignition key OFF then back ON?	No	<ul> <li>Check / Replace the CMU.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>
6	Does the reboot continue after vehicle battery disconnect?	Yes	<ul> <li>Check / Replace the CMU.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>
		No	No repair needed.

Page 5 of 17

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

# No. 4 Infotainment System Has No Sound

Step	Inspection	Result	Action
	Using M-MDS, are any infotainment	Yes	Go to MGSS for DTC diagnosis
1	system DTC's stored?	No	Go to step 2.
	Is the customer complaint "no sound from	Yes	Go to step 3.
2	left side of vehicle"?		Go to step 4.
3	Is the customer's connected device an		Advise customer to update their iPhone IOS to 15.1 or higher, then go to step 4.
	iPhone?	No	Go to step 5.
	Did iPhone IOS 15.1 or higher resolve	Yes	Repair complete.
4	customer concern?	No	Collect CMU log data and contact Hotline for additional support.
5	Is sound normal other than navigation	Yes	Go to step 6.
5	guidance?	No	Go to step 7.
6	Can you hear the voice after raising the	Yes	Normal Operation.
0	navigation volume?	No	Go to step 8.
7	Can you hear sound after turning on audio	Yes	Normal Operation.
1	mode?	No	Go to step 9.
	Replace the Navigation SD Card. Can you hear voice after Navigation SD Card replacement?	Yes	Complete
8		No	<ul> <li>Check / Replace the CMU.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>
	Can you hear sound after raising the	Yes	Normal Operation
9	volume of audio?	No	Go to step 10.
10	<< Source: USB/iPod >> Are there any problems with the media and the music files? << Source: Radio >> Are there any problems with the antenna and the reception? << Source: Bluetooth Audio >> Are there any problems with Bluetooth?	Yes	<< Source: USB/iPod >> Check the media and the compatible files. << Source: Radio >> Check the antenna, the reception, and the Tuner and Amp Unit (TAU) side. << Source: Bluetooth Audio >> Check the Bluetooth connection and the Bluetooth device.
	Are there any problems with Bluetooth?	No	Go to step 11.
11	Go to MGSS "DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "94" Speaker Inspection	Pass	<ul> <li>Check / Replace the CMU. Retrieve</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>
	Speaker Inspection. Did the Speaker Inspection Pass?		Go to MGSS NO SOUND OUTPUT IN ALL MODES [ENTERTAINMENT SYSTEM [WITH

Page 6 of 17

	CENTER DISPLAY]]					
No. 5	5 Commander Switch Does Not Work					
Step	Inspection	Result	Action			
1	Using M-MDS, are any infotainment	Yes	Go to MGSS for DTC diagnosis			
1	system DTC's stored?	No	Go to step 2.			
2	Does the Commander Switch work	Yes	Go to step 3.			
2	correctly?		Go to step 4.			
3	Does the Steering Wheel Switch work	Yes	Normal Operation.			
5	correctly?	No	Go to step 5.			
	2016-2020 CX-5: Inspect connector C-	Yes	Repair as necessary			
4	16 for corrosion due to liquid spill. Is corrosion found at C-16? Other models: Go to next step	No	Go to next step			
5	Are fues blown/ missing?	Yes	<ul><li>Blown - Diagnose blown fuse</li><li>Missing - Install missing fuse</li></ul>			
		No	Go to step 6.			
	Go to MGSS "DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "65" Commander Switch and Steering Wheel Switch Inspections. Did the Switch Inspections Pass?	Pass	Go to step 7.			
6		Fail	<ul><li>Replaced the failed switch. Go to MGSS:</li><li>Steering Wheel Switch Removal/Installation</li><li>Commander Switch Removal/Installation</li></ul>			
7	Is the connector for the Commander	Yes	Go to step 8.			
1	Switch inserted correctly?	No	Insert the connector correctly.			
8	Are the CMU connectors inserted	Yes	Go to step 9.			
0	correctly?	No	Insert the connectors correctly.			
	Swap the Commander Switch with good	Yes	Check / Replace the Commander Switch.			
9	known vehicle. Does the Commander Switch work correctly?	No	Go to step 10.			
10	Swap the CMU from known good vehicle. Does the Commander Switch work correctly?	Yes	<ul> <li>Check / Replace the CMU.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul> Repair/Replace wiring harness. Go to MGSS View Content -> Wiring Diagram -> Body and Accessories -> Entertainment System.			

### Page 7 of 17

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

No. 6 E	Bluetooth	device	will	not	pair
---------	-----------	--------	------	-----	------

Step	Inspection	Result	Action
	Using M-MDS, are any infotainment system	Yes	Go to MGSS for DTC diagnosis
1	DTC's stored?	No	Go to step 2.
	Is Bluetooth enabled on the customers		Go to step 3.
2	device?	No	Enable Bluetooth on the customers device.
		Yes	Go to step 4.
3	Is the customers device paired to the vehicle?	No	Pair the customers device to the vehicle. See MGSS Bluetooth® PAIRING NOT POSSIBLE [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]
	Is the customers device selected in MAZDA	Yes	Go to step 5.
4	CONNECT settings?	No	Select the customers device from Bluetooth settings.
	Delete the device from MAZDA CONNECT	Yes	Normal Operation
5	and then re-pair it. Does Bluetooth work correctly?	No	Go to step 6.
	Go to http://	Yes	Go to step 7.
6	infotainment.mazdahandsfree.com Web Site. Is the customers device compatible?		The customers device is not compatible.
		Yes	Go to step 8.
7	Does the same symptom occur on another same model/year vehicle?	No	<ul> <li>Check / Replace the CMU.</li> <li>Document device model, software version and occurrence of the condition.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>
		Yes	Vehicle operation is normal.
8	Reboot the customers device. Does Bluetooth work correctly?	No	<ul> <li>Check / Replace the CMU.</li> <li>Document device model, software version and occurrence of the condition.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>

Page 8 of 17

# No. 7 Incorrect GPS position

Step	Inspection	Result	Action
	Go to MGSS "DIAGNOSTIC ASSIST FUNCTION	Yes	Normal Operation.
1	[CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "72" GPS information verification. Check GPS Received Level.	No	Go to step 2.
	Does the Navi system show correct vehicle position?		
	Using M-MDS, are any of the following DTC's	Yes	Go to step 4.
2	stored? - B119F:1D, GPS antenna circuit malfunction - B119F:11, GPS antenna circuit malfunction - B119F:13, GPS antenna circuit malfunction - B119F:92, GPS antenna circuit malfunction	No	Go to step 3.
	Is the wheel and tire size correct according to the tire label?	Yes	Go to step 8.
3.		No	Swap wheels/tires with correct size. If issue is fixed, inform the customer.
4	le the CDS entenne connector accured prenerly?	Yes	Go to step 5.
4	Is the GPS antenna connector secured properly?		Insert the connector correctly.
5	Is the GPS wiring harness open or shorted?	Yes	Repair / Replace GPS wiring harness.
5		No	Go to step 6.
6	Are the CMU connectors secured properly?	Yes	Go to step 7.
0		No	Insert the connectors correctly.
7	Is the CMU wiring harness open or shorted?	Yes	Repair / Replace CMU wiring harness.
<u>'</u>		No	Go to step 8.
		Yes	Repair completed.
8	Replace GPS antenna. Does the Navigation system show correct position?	No	<ul> <li>Check / Replace the CMU.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>

Example: Some radar detectors may emit radio waves that interfere with the vehicle GPS antenna.

Page 9 of 17

# No. 8 Voice Recognition Does Not Work

Step	Inspection	Result	Action
1	Using M-MDS, are any infotainment system DTC's stored?		Go to MGSS for DTC diagnosis
<u> </u>			Go to step 2.
	Go to MGSS "DIAGNOSTIC ASSIST FUNCTION	Pass	Go to step 3.
2	[CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "65" Commander Switch and Steering Wheel Switch Inspections. Did the Steering SW Inspection Pass?	Fail	Go to MGSS STEERING SWITCH INSPECTION.
	Go to MGSS "DIAGNOSTIC ASSIST FUNCTION	Pass	Go to step 4.
3	[CONNECTIVITY MASTER UNIT (US)]" Perform Diagnostic Assist Code "61" Microphone signal input condition Did the Microphone Inspection Pass?		Go to MGSS MICROPHONE INSPECTION.
		Yes	Repair complete
4	Go to MGSS VOICE OPERATION NOT POSSIBLE [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]] Is the vehicle repaired?	No	<ul> <li>Check / Replace the CMU.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>

# No. 9 Cannot Make a Hands-Free Call

Step	Inspection	Result	Action
4	Using M-MDS, are any infotainment system	Yes	Go to MGSS for DTC diagnosis
1	DTC's stored?		Go to step 2.
2	Is Bluetooth enabled on the customers	Yes	Go to step 3.
2	device?	No	Enable Bluetooth on the customers device.
	la the quatemore device data convice	Yes	Go to step 4.
3	Is the customers device data service strength good?	No	Move to a location where data service strength is good and retest.
4	Is the customers device paired to the		Go to step 5.
4	vehicle?	No	Pair the customers device to the vehicle.
5	Is the customers device selected in MAZDA CONNECT settings?	Yes	Go to step 6.
		No	Select the customers device from Bluetooth settings.
	Delete the device from MAZDA CONNECT		Normal Operation
6	and then re-pair it. Does Bluetooth work correctly?	No	Go to step 7.
	Go to http://	Yes	Go to step 8.
7	infotainment.mazdahandsfree.com Web Site. Is the customers device compatible?		The customers device is not compatible.

## Page 10 of 17

8	Does the same symptom occur on another	Yes	Go to step 9.
	same model/year vehicle?		Go to step 10.
9	Reboot the customers device. Does	Yes	Vehicle operation is normal.
9	Bluetooth work correctly?		Go to step 10.
10	Is the Bluetooth device in a place where radio waves may be blocked? (Behind or under a sheet, in a box, in a purse/bag, ext.)		Move the Bluetooth device away from hidden location.
			Go to step 11.
11	Is the Bluetooth device contacting or	Yes	Move the Bluetooth device away from metal objects.
	blocked by metal objects?	No	Go to step 12.
12	Is a Bluetooth device and a USB device	Yes	Disconnect other USB device.
12	connected at the same time?	No	Go to step 13.
13	Does the problem occur in a specific geological location only?	Yes	Move to a different location. This may be caused by electrical interference by radio stations, specific small power radio stations, or amateur radio stations for mobile identification used in industrial, scientific and medical devices.
			Go to step 14.
14	Does the same symptom occur on another Bluetooth device?	Yes	Go to step 15
14		No	The customers device is not compatible.
15	Does the voice recognition system operate using other functions such as Bluetooth Audio?	Yes	<ul> <li>Check / Replace the CMU.</li> <li>Document device model, software version and occurrence of the condition.</li> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>
		No	Go to No. 8 Voice Recognition Does Not Work

Page 11 of 17

# No. 10 Cannot Play Bluetooth Audio

Step	Inspection	Result	Action
4	Using M-MDS, are any infotainment system	Yes	Go to MGSS for DTC diagnosis
1	DTC's stored?		Go to step 2.
2	Is Bluetooth enabled on the customers device?		Go to step 3.
			Enable Bluetooth on the customers device.
	Is the customers device data service	Yes	Go to step 4.
3	strength good?	No	Move to a location where data service strength is good and retest.
	le the quatemore device bettery strength	Yes	Go to step 5
4	Is the customers device battery strength good?	No	Connect the customers device to a charger or recharge the device, then retest.
5	Is the customers device paired to the	Yes	Go to step 6.
5	vehicle?	No	Pair the customers device to the vehicle.
	Is the customers device selected in MAZDA	Yes	Go to step 7.
6	Is the customers device selected in MAZDA CONNECT settings?	No	Select the customers device from Bluetooth settings.
	Delete the device from MAZDA CONNECT	Yes	Normal Operation
7	and then re-pair it. Does Bluetooth work correctly?	No	Go to step 8.
	Go to http://	Yes	Go to step 9.
8	infotainment.mazdahandsfree.com Web Site. Is the customers device compatible?		The customers device is not compatible.
0	Does the same symptom occur on another same model/year vehicle?		Go to step 10.
9			Go to step 11.
10	Reboot the customers device. Does	Yes	Vehicle operation is normal.
10	Bluetooth work correctly?	No	Go to step 11.
11	Is the Bluetooth device in a place where radio waves may be blocked? (Behind or under a sheet, in a box, in a purse/bag, ext.)	Yes	Move the Bluetooth device away from hidden location.
		No	Go to step 12.
	Is the Bluetooth device contacting or blocked by metal objects?	Yes	Move the Bluetooth device away from metal objects.
12		No	Go to MGSS NO Bluetooth® AUDIO AND INTERNET RADIO SOUND [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]] Go to step 13 if not resolved.
		Yes	Disconnect other USB device.
13	Is a Bluetooth device and a USB device connected at the same time?		<ul> <li>Check / Replace the CMU.</li> <li>Document device model, software version and occurrence of the condition.</li> </ul>
		n	

### Page 12 of 17

	<ul> <li>Retrieve the data log if possible before replacing the CMU</li> <li>Document date and time of the condition</li> </ul>
--	---

## No. 11 Navigation address not found

Navigation system does not contain a road that I know it exists and I am certain I have the most recent map update available.	Go to mapcreator.here.com, point, click and report missing address.
---	---

## No. 11 Other symptoms

Symptom		Solution	
SiriusXM	<ul> <li>Error Messages</li> <li>Unable to Connect to SiriusXM Radio</li> <li>Check SiriusXM Tuner</li> </ul>	Update CMU software version to 74.00.230A or later.	
	SIRIUSXM Travel Link Parking Information Not Subscribed Error	Go to SA-007/22	
	Can SiriusXM be added if not equipped?	Go to MT-007/15	
Bluetooth	iPhone incoming SMS Text Message is not displayed	Go to MT-011/18	
	Wrong phone connected	Go to SA-063/17	
Center Display	Hot Temperature Warning message Settings 11:24 Temperature Warning Display is too Hot. Screen performance may be decreased until it cools. OK	<ul> <li>High-Temperature Normal Detection</li> <li>The Temperature Warning message displays when the MAZDA CONNECT<sup>™</sup> screen temperature is above 176 °F (80 °C).</li> <li>This is a normal screen protection function. DO NOT perform repairs for this concern. Normal screen operation will resume when the screen temperature cools.</li> <li>High-Temperature False Detection</li> <li>Temperature Warning message when the MAZDA CONNECT<sup>™</sup> screen temperature is below 176 °F (80 °C)</li> <li>Update CMU software version to 74.00.310A or later.</li> </ul>	
	Rear view monitor is blurry	Go to MT-007/18 Go to 09-031/20 if applicable	
	Touch screen operates by itself (ghost touch)	2014-2016 Mazda3 (Japan and Mexico built) Go to <u>SSPB6</u>	

#### Page 13 of 17

Service Alert No.: SA-001/22

		2016-2017 Mazda6 (US spec) with VINS lower than with VINS lower than JM1GL******156205 produced on or before December 29, 2017) Go to 09-021/22
		2017/2022 Mazda6 with VINS higher than JM1GL******156205 produced after December 29, 2017) Go to SA-041/22
		2017-2020 CX-5 vehicles with VINs lower than JM3KF*****869654 (produced before Aug. 25, 2020) Go to 09-003/22
		2014-2016 Mazda3 (Japan and Mexico built) 2016-2022 Mazda6 2017-2020 CX-5 Go to SA-041/22
		2016-017 CX-9 Go to SSPB9
	Screen cracking (spider cracking)	2017-2018 Mazda3 2016 CX-5 Go to SA-008/18
		2016-2017 CX-3 2017 MX-5 2016 MX-5 vehicles with VINs lower than JM1ND******119894 (produced before July 4, 2016) Go to 09-018/18
		2014/2016 Mazda3 2017-2022 Mazda6 with VINS higher than JM1GL*****156205 produced after December 29, 2017) Go to SA-041/22
	Surface Peeling	2016-2017 Mazda6 (US spec) with VINS lower than JM1GL*****156205 (produced before December 29, 2017) Go to 09-021/22
		2017-2020 CX-5 vehicles with VINs lower than JM3KF*****869654 (produced before Aug. 25, 2020) Go to 09-003/22
Clock	Clock shows incorrect time	Go to SA-041/20
	How to update maps	Go to Mazda Toolbox
	Error message "Invalid SD Card"	1. Go to MT-001/18 2. Check VIN Lock
Navigation	Navigation is inoperative	1. Go to MT-007/15 2. Go to MGSS MAP IS NOT DISPLAYED [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]
	No Navigation voice guidance	Go to MGSS NO NAVIGATION GUIDANCE VOICE

## Page 14 of 17

		OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]
	Smart phone device will not charge	Go to MT-022/15 Go to MT-002/18
	Audio source improper operation when device connected to USB	Go to MT-002/18
USB Aux	No USB audio sound	Go to MGSS NO USB AUDIO SOUND OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]
	No Aux audio sound	Go to MGSS NO AUX AUDIO SOUND OUTPUT [ENTERTAINMENT SYSTEM [WITH CENTER DISPLAY]]

# No. 12 How to update the Navigation SD Card Map

Go to Ma:	zdausa.com		
Select Ov	vners $\rightarrow$ How to Use $\rightarrow$ Add vehic	cle year/model	$eI \rightarrow VEHICLE RESOURCES \rightarrow NAVIGATION$
	ightarrow Map Update Guide		
NOTE: Th	ne customer will be instructed to c	lownload the N	Mazda Toolbox App.
	VEHICLE RESOURCES		a state of the sta
	OWNER'S MANUALS		and the second se
	OWNER 3 MANUALS	Ŧ	
	second sectors with the		AND ADDRESS OF ADDRESS
	NAVIGATION SYSTEM	—	
	±2021 Mazda3 Hatchback	-	
	Navigation Owner's Manual		and the second sec
	C <sup>™</sup> Map Update Guide		
			Conception of the second secon
	SIRIUSXM <sup>1</sup> SATELLITE RADIO	+	
	BLUETOOTH GUIDE <sup>® 2</sup>	+	
		Т	
1	-		

### Page 15 of 17

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

	<u>55</u>	MAZDA TOOLBOX	- 🗆 🗙
	🔗 mazda	License error The Map SD Card that you are using has been involved in Fraudulent activity. Pl	lease return
License Error message in Mazda Toolbox		the card with proof of purchase to the authorized Dealership where you purcha replacement. If you have obtained the card from an unauthorized seller, please immediately to reduce risk of vehicle damage and help us stop piracy by report seller to <u>piracy@nng.com</u>	e stop using it
	Customor is locked	out of man undate on Mazda Toolhov due to unauthoriz	rod or
	counterfeit navigatio	out of map update on Mazda Toolbox due to unauthoriz on SD card.	
	How to unlook the	quetemer executin Marda Taalhay	
		customer account in Mazda Toolbox ine Mazda Navigation SD card.	
	2. Customer or deal	er must contact NNG helpdesk by email at piracy@nng.	com and
	request customer ac NOTE: NNG may re	ccount unlock. equire proof of purchase to unlock the customer account	
		MAZDA TOOLBOX	X
		No Map Update available	ENGLISH () HELP ? BACK ()
	Welcome 🕞	There is no new update available for your device:	
Free map update period	Your VIN number: JM3KFBDM0j	- Your device is up-to-date. All available map updates have already been ins	stalled.
has expired	Used / Total space: 5544 MB / 15448 MB	AND/OR - Your free map update period has expired, click on "Buy content"	to purchase.
	Map version	Click Map version on the left side of this page for further details.	
			Home

## Page 16 of 17

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "doit-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

# No. 13 How to Check Navi SD Card VIN Lock

Go to Mazda Toolbox (Version 4)				
	MAZDA TOOLBOX	X		
	🕜 mazda	Warning		
Navi SD Card VIN Unlocked (Mazda Toolbox will not read card)		Sorry, we are having trouble authenticating your SD card. Please ensure that the card is inserted into the vehicle and launched prior to updating. If not, please reinsert your SD card into the vehicle and try again.		
	MAZDA TOOLBOX	– о × ENGLISH (∰) Please login or register an account. ВАСК (Ф)		
Navi SD Card VIN Locked (VIN is displayed)	Used / Total space: 5738 MB / 15448 MB Map of North America Expiration: 0.2.22.2022 (MM.DD.YYYY) <u>Map version</u>	Login Register Forgotten password		

# No. 14 How to Report Navigation Map Error or Missing Location

 Navigation system does not contain a road that I know it exists and I am certain I have the most recent map update available.

 1
 Advise the customer to go to mapcreator.here.com

 2
 Customer will need to create a mapcreator.here.com Log In

 3
 Customer can use the HERE website to report map error or missing location. Point, click and report missing address.

 Note: Inform the customer that the map correction may take up to 6 months to appear on the latest map update.

Page 17 of 17