Service Alert

Mazda North American Operations Irvine, CA 92618-2922



| Subject: | |
|---|------------------------------|
| MAZDA CONNECT SYMPTOM TROUBLESHOOTING (7TH GENERATION VEHICLES) | Service Alert No.: SA-004/22 |
| 5_1, <u></u> , | Last Issued : 08/25/2022 |

BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

| Previous Service Alert: | Date(s) Issued: |
|-------------------------|---|
| SA-004/22 | 06/09/22, 05/12/22, 04/04/22 and 02/01/22 |
| SA-027/21 | 12/21/21, 09/28/21, 06/24/21 and 04/07/21 |
| SA-027/20 | 10/16/20, 09/22/20, 09/11/20, 07/16/20, 06/23/20, 04/08/2 0, 03/19/2020 and 02/11/20 |
| SA-042/19 | 12/12/19 and 09/25/19 |

APPLICABLE MODEL(S)/VINS:

2019-2022 Mazda3 2020-2022 CX-30 2021-2022 CX-5 2021-2022 CX-9 2022 MX-30 2023 CX-5

DESCRIPTION

Customers having MAZDA CONNECT concerns should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

NOTE: Before proceeding:

- Document the vehicle's current MAZDA CONNECT CMU software version.
- Confirm that the Connectivity Master Unit (CMU) is updated to the latest software version.
 - Go to MGSS -> Infotainment -> MAZDA CONNECT Updates
 - Go to TSB 16-001/20 to view MAZDA CONNECT CMU software fix list.
- Confirm that the customer's device is compatible. Go to connect.mazda.com -> Support -> Compatibility.
- Confirm that the customer's device is updated to the latest software version.
- If CMU log data collection is necessary, collect the data and continue troubleshooting using this document. If no failure is found, release the vehicle to the customer and inform them that the infotainment system data is being analyzed. Hotline will contact you at a later date with the results.
- Apple Carplay/Android Auto FAQ, go to SA-001/19.

Page 1 of 21

Service Alert No.: SA-004/22 Last Issued : 08/25/2022

 If you suspect a counterfeit Navi SD card, ask the customer for proof of purchase. It cannot be determined by visually looking at the label. If Mazda Toolbox is used and a counterfeit SD card is detected, the customer VIN may be locked-out.

 If possible, complete any one of the Microsoft Forms Questionnaires. Go to MGSS -> Infotainment -> MAZDA CONNECT Questionnaire.

Index:

No. 1 Blank Screen

No. 2. Rear View Camera is not displayed

No. 3 Rebooting

No. 4 Infotainment System Has No Sound

No. 5 Commander Switch Does Not Work

No. 6 Bluetooth device will not pair

No. 7 Incorrect GPS position

No. 8 Voice Recognition Does Not Work

No. 9 Cannot Make a Hands-Free Call

No. 10 Cannot Play Bluetooth Audio

No 11 How to Check VIN

No. 12 How to update the Navigation SD Card Map

No. 13 How to Check Navi SD Card VIN Lock

No. 14 How to Report Navigation Map Error or Missing Location

Page 2 of 21

Service Alert No.: SA-004/22

No. 1 Blank Screen

| Step | Inspection | | Result | Action |
|------|---|-------------------|--------|--|
| | Is the Rear View Camera displayed? | | Yes | Go to step 2. |
| 1 | | | No | Refer to No. 2. Rear View Camera is not displayed. |
| | Press and hold the Power Butt | on. Is the screen | Yes | Normal Operation. |
| | displayed correctly? | 07.5.07.0 | | |
| | Mazda3, CX-30, MX-30 | CX-5, CX-9 | | |
| 2 | | | | Go to step 3. |
| 3 | Press the "HOME" button. Is the | e HOME screen | Yes | Normal Operation. |
| | displayed correctly? | | No | Go to step 4. |
| | Using M-MDS, are any infotain | ment system DTC's | | Go to MGSS for DTC diagnosis. |
| 4 | stored? | mont dystem B 100 | | 2019-2020 vehicles - Go to step 7. 2021-2022 vehicles - Go to step 5. |
| | Except CX-50 - Go to 16-004/22. Is the CMU Serial | | | Replace the CMU per 16-004/22 instructions. Update the replacement CMU to the latest software version (see MGSS -> Infotainment/TCU -> MAZDA CONNECT Updates). |
| 5 | Number within the affected range? | | No | 2021-2022 CX-5 and CX-9 - Update CMU software version to 7000C0A-NA03_11040 or later, then go to step 6. 2021-2022 Mazda3, CX-30 and MX-30 - Retrieve CMU log data and contact Hotline for additional support. |
| | 2021-2022 CX-5 and CX-9 - Di | | Yes | Repair complete. |
| 6 | version 7000C0A-NA03_11040 or later correct customer concern? | | | Retrieve CMU log data and contact Hotline for additional support. |
| | 2021-Current CX-5 - Inspect co | | Yes | Repair as necessary. |
| 7 | corrosion due to liquid spill. Is corrosion found at C- 16? Other models - Go to next step. | | No | Go to next step. |
| 8 | Is there a device connected to | the USB port? | Yes | Go to step 9. |
| | is there a device confidented to | me oop boit: | No | Go to step 10. |
| 9 | Disconnect the USB device. Do function properly after USB dev | | Yes | USB device is not compatible. |

Page 3 of 21

| Service | Alert | No.: | SA-004/22 | |
|---------|-------|------|-----------|--|
|---------|-------|------|-----------|--|

| | | No | Go to step 10. | |
|--|--|-----|--|--|
| ls the connector for the Center Display inserted | | Yes | Go to step 11. | |
| 10 | correctly? | No | Insert the connector correctly. | |
| 11 | Are the connectors for the CMU inserted correctly? | Yes | Go to step 12. | |
| ' ' | Are the connectors for the Civio inserted correctly: | No | Insert the connectors correctly. | |
| 12 | Is the CMU voltage out (PWR CTRL OUT) at 0920- | Yes | Go to step 13. | |
| 12 | 101A Terminal 1S, SB wire, of the CMU normal? | No | Go to step 14. | |
| 13 | Swap the Center Display with good known vehicle. | Yes | Check / Replace the Center Display. | |
| ls the screen display normal? | | | Go to step 14. | |
| 14 | Swap the CMU with good known vehicle. Is the creen display normal? | | Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. | |
| | | No | Repair / Replace wiring harness. Go to MGSS View Content -> Wiring Diagram -> Body and Accessories -> Entertainment System. | |

Page 4 of 21

Service Alert No.: SA-004/22

No. 2 Rear View Camera is not displayed

| Step | Inspection | Result | Action |
|--------|---|--------|---|
| 1 | Using M-MDS, are any infotainment | Yes | Go to MGSS for DTC diagnosis. |
| ı L | system DTC's stored? | | Go to step 2. |
| 2 | Is the vehicle equipped with 360 | Yes | Go to step 3. |
| | View Monitor? | No | Go to step 4. |
| 3 | ls the Front Camera and Side | Yes | Check / Replace the 360 View Monitor control unit. |
| ٥ | Cameras displayed normally? | No | Go to step 4. |
| | Are images other than the Rear | Yes | Go to step 5. |
| | View Camera displayed? | No | Go to No. 1 Blank Screen. |
| | Go to No 12 How to Check VIN | Yes | Go to step 6. |
| II I | Does the VIN match to customer vehicle VIN? | No | Swap CMU(s) to correct vehicle(s) or replace CMU. |
| 11 6 1 | Is the connector for the Rear View | Yes | Go to step 7. |
| О | Camera Inserted correctly? | No | Insert the connector correctly. |
| 7 | Is the connector for the Center | | Go to step 8. |
| | Display Inserted correctly. | No | Insert the connector correctly. |
| | Are the connectors for the CMU | Yes | Go to step 9. |
| | Inserted correctly. | No | Insert the connectors correctly. |
| | Swap the Rear View Camera with good known vehicle. Is the screen | Yes | Check / Replace the Rear View Camera See TSB 09-021/19. |
| | display normal? | No | Go to Step 10. |
| 10 | Swap the CMU with good known vehicle. Is the screen display normal? | Yes | Check / Replace the CMU. Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. |
| | | No | Repair / Replace wiring harness. Go to MGSS View Content -> Wiring Diagram -> Body and Accessories -> Entertainment System. |

Page 5 of 21

No. 3 Rebooting

Service Alert No.: SA-004/22

| Step | Inspection | Result | Action |
|------|---|--------|--|
| | Is the customers device a Doro 7050, 7060 phone that is connected by | Yes | Update CMU software version to 7000C0A-NA01_ 11006 or later. |
| 1 | bluetooth? | No | Go to next step. |
| 2 | Using M-MDS, are any infotainment | Yes | Go to MGSS for DTC diagnosis. |
| | system DTC's stored? | No | Go to step 3. |
| 3 | Does the reboot continue after | Yes | 2019-2020 vehicles - Go to step 6. 2021-2022 vehicles - Go to step 4. |
| 3 | removing the Navigation SD card? | | Check / Replace the Navigation SD card. Go to SA-014/21 if applicable. |
| | Except CX-50 - Go to 16-004/22. Is the CMU Serial Number within the | Yes | Replace the CMU per 16-004/22 instructions. Update the replacement CMU to the latest software version (see MGSS -> Infotainment/TCU -> MAZDA CONNECT Updates). |
| | affected range? CX-50 - Go to Step 6 | No | 2021-2022 CX-5 and CX-9 - Update CMU software version to 7000C0A-NA03_11040 or later, then go to step 5. 2021-2022 Mazda3, CX-30 and MX-30 - Retrieve CMU log data and contact Hotline for additional support. |
| | 2021-2022 CX-5 and CX-9 - Did CMU | Yes | Repair Complete. |
| 5 | software version 7000C0A-NA03_ 11040 or later correct customer concern? | No | Retrieve CMU log data and contact Hotline for additional support. |
| | Is there a device connected to the | Yes | Go to step 7. |
| J | USB port? | No | Go to step 8. |
| | Disconnect the USB device. Does the | Yes | USB device is not compatible. |
| | reboot stop after USB device is disconnected? | No | Go to step 8. |
| | Does the reboot continue after ignition | Yes | Go to step 9. |
| Ľ | key OFF then back ON? | No | Check / Replace the CMU. |

Page 6 of 21

| Service Alert No.: SA-004/22 | Last Issued : 08/25/2022 |
|------------------------------|--------------------------|
|------------------------------|--------------------------|

| | | | Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. |
|---|--|-----|---|
| 9 | Does the reboot continue after vehicle battery disconnect? | Yes | Check / Replace the CMU. Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. |
| | | No | No repair needed. |

Page **7** of **21**

No. 4 Infotainment System Has No Sound

Service Alert No.: SA-004/22

| Step | Inspection | Result | Action |
|------|---|--------|---|
| | | Yes | DTC U3000:49 stored, Mazda3, CX-30 built after 7/1/2021 - Update CMU to CMU_7000C0A-NA06_12012 or later. DTC U3000:49 stored, MX-30 - Update CMU to CMU_7000C0A-NA02_11036 or later. Except DTC U3000:49 - Go to MGSS for DTC diagnosis. |
| 1 | Using M-MDS, are any infotainment system DTC's stored? | No | 2021-2022 CX-5 and CX-9 - Update CMU software version to 7000C0A-NA03_11040 or later, then go to step 2. 2021-2022 Mazda3 and CX-30 built after July 1, 2021 - Update CMU software version to 7000C0A-NA06_12012 or later, then go to step 2. 2022 MX-30 - Update CMU software version to 7000C0A-NA02_11036 or later, then go to step 2. Except vehicles listed above - Go to step 3. |
| | | Yes | Repair Complete. |
| 2 | 2021-2022 CX-5 and CX-9 2021-2022 Mazda3 and CX-30 2022 MX-30 Did CMU software correct customer concern? | No | Go to step 3. |
| | ls sound normal other than navigation | Yes | Go to step 4. |
| 3 | guidance? | No | Go to step 5. |
| 4 | Can you hear the voice after raising | Yes | Normal Operation. |
| 4 | the navigation volume? | No | Go to step 6. |
| 5 | Can you hear sound after turning on | Yes | Normal Operation. |
| | audio mode? | No | Go to step 7. |
| | | | Repair complete. |
| 6 | Replace the Navigation SD Card. Can you hear voice after Navigation SD Card replacement? | No | Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. |

Page 8 of 21

| Sarvi | α Δ | Δrt | Nο. | SAL | 004/22 | |
|--------|-----|-----|-----|-----|--------|--|
| 361 11 | - M | EIL | 140 | JM- | 004/22 | |

| 7 | Can you hear sound after raising the | Yes | Normal Operation. |
|----|---|-----------|--|
| | volume of audio? | No | Go to step 8. |
| 8 | << Source: USB/iPod >> Are there any problems with the media and the music files? << Source: Radio >> Are there any problems with the antenna and the reception? << Source: Bluetooth Audio >> Are there any problems with Bluetooth? | Yes | << Source: USB/iPod >> Check the media and the compatible files. << Source: Radio >> Check the antenna, the reception, and the Remote Tuner side. << Source: Bluetooth Audio >> Check the Bluetooth connection and the Bluetooth device. |
| | | No | Go to step 9. |
| 9 | Go to MGSS "DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]" and perform Functional Inspection/ Adjustment -> Active Speaker Check Function -> Speaker Inspection. | Pass | Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. |
| | Did the Speaker Inspection Pass? | Fail | Go to step 10. |
| 10 | Is the connector for the Speaker(s) | Yes | Go to step 11. |
| | that failed inserted correctly? | No | Insert the connector correctly. |
| 11 | Is the connector for the amplifier inserted correctly? | Yes | Go to step 12. |
| | | No | Insert the connector correctly. |
| 12 | Are the CMU connectors inserted correctly? | Yes | Go to step 13. |
| | | No | Insert the connectors correctly. |
| 13 | Swap speakers from good known vehicle. Can you hear sound? | Yes | Check / Replace the speakers. |
| | | No Yes | Go to step 14. |
| 14 | Swap the Amplifier from known good vehicle. Can you hear sound? | No | Check / Replace the Amplifier. Go to step 15. |
| | vernoie. Can you near sound: | INO | · |
| 15 | Swap the Remote Tuner from known good vehicle. Can you hear sound? | Yes | Check / Replace the Remote Tuner Review the following for possible cause of Remote Tuner failure. • CX-30 - Review SA-035/21 and 09-020/21. • Mazda3 - Review 09-020/21. • CX-5 and CX-9 - Inspect Remote Tuner for external water corrosion. Contact the Mazda National Technical Hotline before attempting any repairs. |
| | | No | Go to step 16. |
| 16 | Swap the CMU from known good vehicle. Can you hear sound? | Yes | Check / Replace the CMU. Retrieve CMU log data if possible before replacing the CMU. |

Page 9 of 21

| Service Alert No.: SA-004/22 | Last Issued : 08/25/2022 |
|------------------------------|--------------------------|
| | |

| | | Document date and time of the condition. |
|--|----|---|
| | No | Repair/Replace wiring harness. Go to MGSS View Content -> Wiring Diagram -> Body and Accessories -> Entertainment System. |

No. 5 Commander Switch Does Not Work

| Step | Inspection | Result | Action |
|---|--|---|---|
| | Using M-MDS, are any infotainment system | Yes | Go to MGSS for DTC diagnosis. |
| ' | DTC's stored? | | Go to step 2. |
| | Does the Commander Switch work | Yes | Go to step 3. |
| | correctly? | No | Go to step 4. |
| | Does the Steering Wheel Switch work | Yes | Normal Operation. |
| | correctly? | No | Go to step 5. |
| 4 | ls fuse F13 missing? | Yes | Go to SA-025/19. |
| | is tase i To illissing: | No | Go to step 8. |
| | Go to MGSS "DIAGNOSTIC ASSIST | Pass | Go to step 6. |
| | FUNCTION [CONNECTIVITY MASTER UNIT (US)]" Perform Functional Inspection/Adjustment - > Steering SW Inspection -> Did the Steering SW Inspection Pass? | Fail | Go to MGSS STEERING SWITCH INSPECTION. |
| 6 | Is the connector for the CMU inserted | Yes | Go to step 7. |
| 0 | correctly? | No | Insert the connector correctly. |
| Swap the CMU from known good vehicle. 7 Does the Steering Wheel Switch work correctly? | Yes | Check / Replace the CMU. Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. | |
| | | No | Repair/Replace wiring harness. Go to MGSS View Content -> Wiring Diagram -> Body and Accessories -> Entertainment System. |
| 0 | Go to MGSS "DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]" Perform Functional Inspection/Adjustment - > Touch Pad/Commander Inspection - > Commander switch inspection. Did the Commander switch inspection Pass? | Pass Fail | Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. Go to step 9. |

Page 10 of 21

| 9 | 9 Is the connector for the Commander Switch inserted correctly? | | Go to step 10. |
|--|---|---|---------------------------------------|
| | | | Insert the connector correctly. |
| Are the CMU connectors inserted | | Yes | Go to step 11. |
| 10 | correctly? | No | Insert the connectors correctly. |
| | Swap the Commander Switch with good | Yes | Check / Replace the Commander Switch. |
| 11 known vehicle. Does the Commander Switch work correctly? | No | Go to step 12. | |
| Swap the CMU from known good vehicle. 12 Does the Commander Switch work correctly? | Yes | Check / Replace the CMU. Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. | |
| | No | Repair/Replace wiring harness. Go to MGSS View Content -> Wiring Diagram -> Body and Accessories -> Entertainment System. | |

Page 11 of 21

No. 6 Bluetooth device will not pair

Service Alert No.: SA-004/22

| Step | Inspection | Result | Action |
|---|---|--------|---|
| 1 | Using M-MDS, are any infotainment | Yes | Go to MGSS for DTC diagnosis. |
| ı | system DTC's stored? | | Go to step 2. |
| 2 Is Bluetooth enabled on the customers | Is Bluetooth enabled on the customers | Yes | Go to step 3. |
| | device? | | Enable Bluetooth on the customers device. |
| 3 | Is the customers device paired to the | Yes | Go to step 4. |
| | vehicle? | No | Pair the customers device to the vehicle. |
| | Is the customers device selected in | Yes | Go to step 5. |
| 4 | MAZDA CONNECT settings? | No | Select the customers device from Bluetooth settings. |
| | Delete the device from MAZDA CONNECT | Yes | Normal Operation. |
| 5 | and then re-pair it. Does Bluetooth work correctly? | No | Go to step 6. |
| | Go to connect.mazda.com -> Support -> | Yes | Go to step 7. |
| 6 | 6 Compatibility. Is the customers device compatible? | | The customers device is not compatible. |
| | | Yes | Go to step 8. |
| 7 | Does the same symptom occur on another same model/year vehicle? | No | Check / Replace the CMU. Document device model, software version and occurrence of the condition. Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. |
| | | Yes | Vehicle operation is normal. |
| 8 | Reboot the customers device. Does Bluetooth work correctly? | No | Check / Replace the CMU. Document device model, software version and occurrence of the condition. Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. |

Page 12 of 21

No. 7 Incorrect GPS position

Service Alert No.: SA-004/22

| Step | Inspection | | Action |
|------|---|-----|---|
| | Go to MAZDA CONNECT -> Navi menu, Travel | Yes | Normal Operation. |
| 1 | Information -> Where Am I? -> Settings -> GPS information -> Check Available Satellites. or Go to MGSS "DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]" and perform Functional Inspection/Adjustment -> Navi System Inspection -> Check GPS Received Level. Does the Navi system show correct vehicle position? | No | Go to step 2. |
| | Using M-MDS, are any of the following DTC's stored? | Yes | Go to step 4. |
| 2 | - B119F:13, GPS antenna signal circuit malfunction (short to power or open circuit) - B119F:2B, GPS antenna signal circuit malfunction (short to ground) | No | Go to step 3. |
| | | Yes | Go to step 9. |
| 3 | Is the wheel and tire size correct according to the tire label? | No | Swap wheels/tires with correct size. If issue is fixed, inform the customer. |
| 1 | Is the CDS antenna connector acquired properly? | Yes | Go to step 5. |
| 4 | Is the GPS antenna connector secured properly? | No | Insert the connector correctly. |
| 5 | Is the GPS wiring harness open or shorted? | | Repair / Replace GPS wiring harness. |
| | | No | Go to TSB 09-021/20. |
| 6 | Did TSB 09-021/20 resolve the concern? | Yes | Repair Complete. |
| | Pid 100 00 021/20 1000/V0 till collicativ. | No | Go to step 7. |
| 7 | Are the CMU connectors secured properly? | Yes | Go to step 8. |
| | | No | Insert the connectors correctly. |
| 8 | Is the CMU wiring harness open or shorted? | | Repair / Replace CMU wiring harness. |
| | | No | Go to step 9. |
| | | Yes | Repair completed. |
| 9 | Replace GPS antenna. Does the Navigation system show correct position? | | Check / Replace the CMU. Document date and time of the condition. Retrieve CMU log data if possible before replacing the CMU. |

Page 13 of 21

| | | | Retrieve CMU backup data if possible before replacing the CMU. |
|----|---|---------|---|
| 10 | Using M-MDS, is DTC B119F:49 stored? | Yes | Go to step 11. |
| 10 | (Communication error with GNSS) | No | Go to step 13. |
| 11 | Are the CMU connectors secured properly? | Yes | Go to step 12. |
| '' | Are the Givio confidences secured property: | No | Insert the connectors correctly. |
| | | 1 Y 4 S | Repair / Replace CMU wiring harness. |
| 12 | Is the CMU wiring harness open or shorted? | No | Check / Replace the CMU. Document date and time of the condition. Retrieve CMU log data if possible before replacing the CMU. Retrieve CMU backup data if possible before replacing the CMU. |
| | Check / Replace the CMU. | Yes | Repair completed. |
| 13 | Document date and time of the condition. Retrieve CMU log data if possible before replacing the CMU. Retrieve CMU backup data if possible before replacing the CMU. Did DTC B119F:49 clear? | No | Repair / Replace GPS antenna. |

NOTE: Remove aftermarket GPS devices that may interfere with vehicle GPS antenna. Example: Some radar detectors may emit radio waves that interfere with the vehicle GPS antenna.

No. 8 Voice Recognition Does Not Work

| Step | Inspection | | Action |
|------|---|------|--|
| 1 | Using M-MDS, are any infotainment system DTC's stored? | | Go to MGSS for DTC diagnosis. |
| I | | | Go to step 2. |
| | Go to MGSS "DIAGNOSTIC ASSIST FUNCTION | Pass | Go to step 3. |
| 2 | [CONNECTIVITY MASTER UNIT (US)]" and perform Functional Inspection/Adjustment -> Steering SW Inspection Pass? | | Go to MGSS STEERING SWITCH INSPECTION. |
| 3 | Go to MGSS "DIAGNOSTIC ASSIST FUNCTION | Pass | Check / Replace the CMU. |

Page 14 of 21

| [CONNECTIVITY MASTER UNIT (US)]" and perform Functional Inspection/Adjustment -> Microphone Inspection -> Did the Microphone Inspection Pass? | Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. |
|---|--|
| | Go to MGSS MICROPHONE INSPECTION. |

No. 9 Cannot Make a Hands-Free Call

| Step | Inspection | Result | Action |
|--------|--|--------|--|
| 1 | Using M-MDS, are any | Yes | Go to MGSS for DTC diagnosis. |
| ' | infotainment system DTC's stored? | No | Go to step 2. |
| 2 | Is Bluetooth enabled on the | Yes | Go to step 3. |
| | customers device? | No | Enable Bluetooth on the customers device. |
| | Is the customers device data | Yes | Go to step 4. |
| 3 | service strength good? | No | Move to a location where data service strength is good and retest. |
| 4 | Is the customers device paired to | Yes | Go to step 5. |
| | the vehicle? | No | Pair the customers device to the vehicle. |
| 11 h 1 | Is the customers device selected | Yes | Go to step 6. |
| | in MAZDA CONNECT settings? | No | Select the customers device from Bluetooth settings. |
| | Delete the device from MAZDA | Yes | Normal Operation. |
| | CONNECT and then re-pair it. Does Bluetooth work correctly? | No | Go to step 7. |
| | Go to connect.mazda.com -> | Yes | Go to step 8. |
| 7 | Support -> Compatibility. Is the customers device compatible? | No | The customers device is not compatible. |
| | Does the same symptom occur on | Yes | Go to step 9. |
| 0 | another same model/year vehicle? | No | Go to step 10. |
| 9 | Reboot the customers device. | Yes | Vehicle operation is normal. |
| | Does Bluetooth work correctly? | No | Go to step 10. |
| | Is the Bluetooth device in a place | Yes | Move the Bluetooth device away from hidden location. |
| 10 | where radio waves may be blocked? (Behind or under a sheet, in a box, in a purse/bag, ext.) | No | Go to step 11. |
| | Is the Bluetooth device contacting | Yes | Move the Bluetooth device away from metal objects. |
| | or blocked by metal objects? | No | Go to step 12. |
| 12 | Is a Bluetooth device and a USB device connected at the same | Yes | Disconnect other USB device. |

Page 15 of 21

| | time? | No | Go to step 13. |
|--|--|-----|---|
| Does the problem occur in a Yes specific geological location only? | | Yes | Move to a different location. This may be caused by electrical interference by radio stations, specific small power radio stations, or amateur radio stations for mobile identification used in industrial, scientific and medical devices. |
| | | No | Go to step 14. |
| 14 | Does the same symptom occur on | Yes | Go to step 15. |
| 14 | another Bluetooth device? | No | The customers device is not compatible. |
| 15 | Does the voice recognition system operate using other functions such as Bluetooth Audio? | Yes | Check / Replace the CMU. Document device model, software version and occurrence of the condition. Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. |
| | | No | Go to No. 8 Voice Recognition Does Not Work. |

No. 10 Cannot Play Bluetooth Audio

| Step | Inspection | Result | Action |
|--|---|---------------|--|
| 1 | Using M-MDS, are any infotainment | Yes | Go to MGSS for DTC diagnosis |
| ı | system DTC's stored? | No | Go to step 2. |
| 2 | Is Bluetooth enabled on the customers | Yes | Go to step 3. |
| | device? | No | Enable Bluetooth on the customers device. |
| | Is the customers device data service | Yes | Go to step 4. |
| 3 | strength good? | | Move to a location where data service strength is good and retest. |
| | le the quetemore device bettery strength | Yes | Go to step 5. |
| 11 21 1 | 4 Is the customers device battery strength good? | | Connect the customers device to a charger or recharge the device, then retest. |
| 5 | Is the customers device paired to the | Yes | Go to step 6. |
| 5 | vehicle? | No | Pair the customers device to the vehicle. |
| | le the quetemore device colocted in | Yes | Go to step 7. |
| 11 6 1 | 6 Is the customers device selected in MAZDA CONNECT settings? | No | Select the customers device from Bluetooth settings. |
| II I | Delete the device from MAZDA CONNECT | Yes | Normal Operation. |
| 7 and then re-pair it. Does Bluetooth work correctly? | No | Go to step 8. | |
| 8 | Go to connect.mazda.com -> Support -> Compatibility. | Yes | Go to step 9. |


Page 16 of 21

| Service | Δ | lert l | N٥ | · S/ | 4-004/2 | 2 |
|---------|---|--------|----|------|---------|---|
| | | | | | | |

| | Is the customers device compatible? | | The customers device is not compatible. | |
|--|--|-----|---|--|
| 9 | Does the same symptom occur on another | Yes | Go to step 10. | |
| 9 | same model/year vehicle? | No | Go to step 11. | |
| Reboot the customers device. Does | | Yes | Vehicle operation is normal. | |
| 10 | Bluetooth work correctly? | No | Go to step 11. | |
| 11 | Is the Bluetooth device in a place where radio waves may be blocked? | Yes | Move the Bluetooth device away from hidden location. | |
| | (Behind or under a sheet, in a box, in a purse/bag, ext.) | No | Go to step 12. | |
| 12 Is the Bluetooth device contacting or blocked by metal objects? | | Yes | Move the Bluetooth device away from metal objects. | |
| blocked by Metal objects | blocked by metal objects: | No | Go to step 13. | |
| Is a Bluetooth device and a USB device connected at the same time? | | Yes | Disconnect other USB device. | |
| | | No | Check / Replace the CMU. Document device model, software version and occurrence of the condition. Retrieve CMU log data if possible before replacing the CMU. Document date and time of the condition. | |

Page 17 of 21

No. 11 How to Check VIN



Page 18 of 21


Service Alert No.: SA-004/22 Last Issued : 08/25/2022

No. 12 How to update the Navigation SD Card Map


Go to Mazdausa.com

Select Owners \rightarrow How to Use \rightarrow Add vehicle year/model \rightarrow VEHICLE RESOURCES \rightarrow NAVIGATION SYSTEM \rightarrow Map Update Guide

Note: The customer will be instructed to download the Mazda Toolbox App.



License Error message in Mazda Toolbox




Customer is locked out of map update on Mazda Toolbox due to unauthorized or counterfeit navigation SD card.

How to unlock the customer account in Mazda Toolbox


- 1. Purchase a Genuine Mazda Navigation SD card.
- 2. Customer or dealer must contact NNG helpdesk by email at piracy@nng.com and request customer account unlock.

Page 19 of 21



Page 20 of 21

No. 13 How to Check Navi SD Card VIN Lock



No. 14 How to Report Navigation Map Error or Missing Location

Navigation system does not contain a road that I know it exists and I am certain I have the most recent map update available.

1. Advise the customer to go to mapcreator.here.com

2. Customer will need to create a mapcreator.here.com Log In

Customer can use the HERE website to report map error or missing location. Point, click and report missing address.

Note: Inform the customer that the map correction may take up to 6 months to appear on the latest map update.

Page 21 of 21