

**WNE3 - Replacing Front Seat-Belt Buckle (Workshop Campaign)**

Model Line: **Taycan (Y1A/Y1B/Y1C)**

Model Year: **As of 2020 up to 2022**

Concerns: **Belt buckle on driver's and passenger's side**


Information: **There is a possibility that the cable length on the belt buckle switch on the driver's and passenger's side is not sufficient on the affected vehicles.**

This can cause a cable break over the extended service life of the seat height adjustment system.

Action required: Replace front seat-belt buckle.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Installation Position:



*Installation position of front belt lock*

**Parts required**

Parts Info:	Part No.	Designation - Areas of application	Number
	V04015001HE	⇒ Seat-belt buckle, driver's side	1 piece
	V04015001HF	⇒ Front seat-belt buckle (passenger side)	1 piece
	N 98923701	⇒ Cheese head screw with inside multiple-tooth head - Belt buckle	2 pieces
	9A700748300	⇒ External hexagon round-head screw M10 x 28 - Driver / passenger seat	8 pieces

**Replacing front seat-belt buckle**

- Work Procedure: 1 Replace seat-belt buckle on driver's and passenger's side ⇒ *Workshop Manual '692419 Removing and installing front seat-belt buckle'*.
- 2 Enter the campaign in the Warranty and Maintenance booklet.

**Warranty processing**

Scope 1:

<b>Labor time:</b>		
Replacing front seat-belt buckle		Labor time: <b>106 TU</b>
Includes:	Remove and install front seat	
<b>Parts required:</b>		
V04015001HE	Seat-belt buckle, driver's side	1 piece
V04015001HF	Front seat-belt buckle (passenger side)	1 piece
N 98923701	Cheese head screw with inside multiple-tooth head	2 pieces
9A700748300	External hexagon round-head screw M10 x 28	8 pieces
⇒ <b>Damage Code WNE3 066 000 2</b>		

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2022 Porsche Cars North America, Inc.