September 8, 2022

Version 1

Audio Unit Software Update

AFFECTED VEHICLES

NOTE: 5-door Civics (Hatchback) are not affected.

Year	Model	Trim	VIN Range
	Civic Coupe	EX	2HGFC3GH350002 thru 2HGFC3GH353584
	Civic Coupe	Touring	2HGFC3GH350013 thru 2HGFC3GH353394
		19XFC1GE000009 thru 19XFC1GE212889	
2016		EY	19XFC2GE001338 thru 19XFC2GE221236
2010	Civic Sodan	EA.	2HGFC1GH600049 thru 2HGFC1GH644117
	Civic Sedan		2HGFC2GH500049 thru 2HGFC2GH548745
		Touring	19XFC1GE000001 thru 19XFC1GE212880
			2HGFC1GH600064 thru 2HGFC1GH645106

SYMPTOM

There is a problem with the audio unit software, which may lead to one or both of the following symptoms:

- Rear camera is stuck on in Park.
- Rear camera image does not display when transmission is shifted to Reverse.

CORRECTIVE ACTION

Update the audio unit software with the audio-navigation system update device.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation	Description	Flat Rate	Defect	Symptom	Template	Failed Part
Number		Time	Code	Code	ID	Number
0100A1	Update the audio unit software.	0.3 hr	03214	03217	A22012A	39101-TBA-A21

Skill Level: Repair Technician

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

REQUIRED TOOLS

Tool Name	Part Number
Audio-Navigation System Update Device (purple USB update tool)	07AAU-TBAA1A0



REPAIR PROCEDURE

NOTE:

- Do not turn the Ignition/Engine to OFF until the update is complete.
- Do not remove the USB during the update.
- Do not insert the USB update device into a computer. It may be corrupted and no longer function.
- Advise the customer that all user memory, including audio presets and *Bluetooth[®]* pairing profiles, will be erased as part of the update.
- 1. Write down the customer's audio presets so they can be re-entered after the update is completed.
- 2. Prepare the vehicle for the update.
 - If the engine will be running, park the vehicle outside in a well ventilated area or attach an appropriate exhaust vent. Go to step 3.
 - If the engine will not be running, connect an active charger to the battery. Go to step 4.
- 3. Start the engine, and leave it running throughout the entire software update process. Go to step 5.
- 4. Push the Engine Start button twice to turn the Ignition to ON (not Accessory mode).
- 5. Let the audio system boot up to the home screen.



Plug the purple USB update device into the USB port below and behind the audio unit near the driver's knee area.
NOTE: The previous orange USB tool (p/n 07AAZ-TBAA100) is to be destroyed and replaced by the new purple tool.



7. Depending on the current audio software and after **50 seconds**, you will either see a blank display and the system will reboot or you will see the following update message, Select **Yes**.



8. After the system reboots, the software update should start. It takes up to **20 minutes** to complete the update. Once you start the update, you do not have to stay with the vehicle.

📳 Software Upda	te	
Current New	Ver. 1.F186.69 Ver. 1.F190.25	
•••	1 1 1	0%
Please do n or disconr	Copying ot turn off the vehi nect the USB device	cle e.

NOTE: After the update has completed, the system will reboot automatically. If the Lost Power message appears, press and hold the power button for **2 seconds** to enable the system. The GPS screen may appear and will disappear once the GPS is received.



9. Press and hold the Day/Night, Audio Power, and MENU buttons at the same time.



10. Select Detail Information & Setting.



11. Select Version.

	Return	
Monitor Check	B-CAN	
Unit Check	F-CAN	
Audio Check	Version	
Guideline Setup	Vehicle status	
Functional Setup	GPS Information	

- 12. Scroll all the way to the bottom to: **Software loader** and **System** μ **Com** and check the versions. The software should be updated to the following versions:
 - Software loader : 1.F190.25
 - System µCom : H6XF00.XX.E2.XX (the X values are different depending on model)

	Return
	HUL G2P Engine 20.8.0
	HUL TTS Engine1.0.2
	VehicleDbManager1.0
	com.mitsubishielectric.ada.util.vehiclerw4.2.2-15 4
DBOOT	1.9_20160329042950
Software loader	1.F190.25
System µCom	H6XF00.XX.E2.XX

13. After verifying the software has been updated, select **Return** to return to the **Detail Information** and **Setting** screen.



14. Select Unit Check.

	Return
Monitor Check	B-CAN
Unit Check	F-CAN
Audio Check	Version
Guideline Setup	Vehicle status
Functional Setup	GPS Information

15. Select Error History.



16. Select Hard Error.

		Return
Hard Error	Soft Error	
		-

17. Select Clear.

			Return
		20150101 020309	
Date	20150101	20150101 015750	
Time	015035	20150101 015035	
Error code	1302	20150101-014715	
Simple description	GPS Receiver Error1	20150101 011815	
-		20150101011458	
		Save	JK

18. Select Yes.

	Confirmation Deleted data cannot be	e recovered.	
	Yes	No	
e description			

19. Select Return 5 times to go back to the home screen.



- 20. Remove the USB device.
- 21. The vehicle is now updated.

END