

# MIL ON With DTC P060694

**Service Category** Drivetrain

**Section** Hybrid Transmission/Transaxle

**Market** USA

Toyota Supports  
 ASE Certification 

## Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2021 - 2022	RAV4 Prime	

## Introduction

Some 2021 – 2022 model year RAV4 Prime vehicles may exhibit a MIL ON condition with Diagnostic Trouble Code (DTC) P060694 (SAE code P0606) (Control Module Processor Unexpected Operation) present. The Hybrid Vehicle Control Computer logic has been modified to reduce the possibility of this condition. Follow the Repair Procedure in this bulletin to address this condition.

## Production Change Information

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VIN shown below.

MODEL	PLANT	DRIVETRAIN	PRODUCTION CHANGE EFFECTIVE VIN
RAV4 Prime	Shokki-Nagakusa	AWD	JTM#B3FV#ND091592

## MIL ON With DTC P060694

### Warranty Information

OP CODE	DESCRIPTION	TIME	OFFP	T1	T2
800259	Reprogram Hybrid Vehicle Control Computer	1.1	89980-4225#*	8A	74

\*Warranty claim MUST be submitted with the correct 10-digit OFFP. Choose the correct OFFP for the vehicle being repaired by searching for the parts in the Electronic Parts Catalog using the VIN filter.

#### APPLICABLE WARRANTY

- This repair is covered under the Toyota Hybrid warranty. This warranty is in effect for 96 months or 100,000 miles, whichever occurs first, from the vehicle's in service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.
- 2021 – 2022 RAV4 Prime vehicles that are registered and normally operated in California, Arizona (2012 model year only), Connecticut (starting with 2005 model year), Maine (starting with 2004 model year), Maryland (starting with 2011 model year), Massachusetts (starting with 2004 model year), New Hampshire (2005 – 2009 model year only), New Jersey (starting with 2005 model year), New Mexico (2010 – 2011 model year only), New York (beginning with 2004 model year with ZE models only; all models starting with 2016 model year), Oregon (starting with 2008 model year), Rhode Island (starting with 2005 model year), and Vermont (starting with 2004 model year) – Partial Zero Emission Vehicle (PZEV) Emission Warranty Coverage is in effect for 15 years or 150,000 miles, from the vehicle's in-service date, whichever occurs first. (Please reference Warranty Policy Bulletin POL14-09 for additional information).
- Four additional states (Delaware [beginning with 2014 model year], Colorado [starting with 2022 model year] Pennsylvania [beginning with 2008 model year], and Washington [beginning with 2009 model year]) have adopted the California Emission Warranty. However, in these states performance and long-term defect warranty coverage is 7 years or 70,000 miles, whichever occurs first.

### Parts Information

PART NUMBER		PART NAME	QTY
PREVIOUS	NEW		
89980-42250 89980-42251	89980-42252	Computer Assy, Hybrid Vehicle Control	–
00451-00001-LBL		Authorized Modifications Labels	1

#### NOTE

- The Hybrid Vehicle Control Computer should NOT be replaced as part of the Repair Procedure.
- Authorized Modifications Labels may be ordered in packages of 25 from the Materials Distribution Center (MDC) through *Dealer Daily – Parts – Dealer Support Materials Orders*.

## MIL ON With DTC P060694

### Required Tools & Equipment

SPECIAL SERVICE TOOLS (SST)	PART NUMBER	QTY
Battery Diagnostic Tool*	<a href="#">DCA-8000P T</a>	1

\*Essential SST.

**NOTE**

Additional SSTs may be ordered by calling 1-800-933-8335.

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream ADVI*	ADE	TSADVUNIT	1
Techstream 2.0		TS2UNIT	
Techstream Lite		TSLITEPDLR01	
Techstream Lite (Green Cable)		TSLP2DLR01	

\*Essential SST.

**NOTE**

- Only ONE of the Techstream units listed above is required.
- Software version 17.00.020 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.
- Use Techstream or an approved J2534 interface to perform flash reprogramming updates. Visit [techinfo.toyota.com](http://techinfo.toyota.com) for more information regarding J2534 reprogramming.

### Calibration Information


MODEL	ECU	CALIBRATION ID	
		PREVIOUS	NEW
RAV4 Prime	Main	899834222100	<a href="#">899834222200</a>
	Sub	899854203000	<a href="#">899854203100</a>

## MIL ON With DTC P060694

### Repair Procedure

1. Confirm the condition exists.  
Does the vehicle exhibit a MIL ON condition with DTC P060694 (SAE code P0606) present?
  - **YES** — Continue to step 2.
  - **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
  
2. Check for the Authorized Modifications Label affixed to the vehicle in the location shown below. Confirm if the Hybrid Control Module calibration has been updated.  
Is the calibration ID listed the latest Hybrid Vehicle Control Computer calibration?
  - **YES** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
  - **NO** — Continue to step 3.

**Figure 1. Location of Authorized Modifications Label on 2021 – 2022 RAV4 Prime**



<b>1</b>	Replacement Hybrid Vehicle Control Computer Part Number (e.g., 89980-42252)
<b>2</b>	New Calibration ID (e.g., Main – 89983422200, Sub - 899854203100)
<b>3</b>	Dealer Code

<b>4</b>	Date Completed
<b>5</b>	This SB Number

## MIL ON With DTC P060694

---

### Repair Procedure (continued)

- Flash reprogram the Hybrid Vehicle Control Computer.

#### NOTE

- The battery diagnostic tool **MUST** be used in Power Supply mode to maintain battery voltage at 13.0 – 13.5V while flash reprogramming the vehicle.
- For details on how to use the battery diagnostic tool, refer to the [DCA-8000 Instruction Manual](#) located at *TIS – Diagnostics – Tools & Equipment – Battery Diagnostics*.

Follow the procedures outlined in [T-SB-0134-16](#) *Techstream ECU Flash Reprogramming Procedure* and flash the Hybrid Vehicle Control Computer with the NEW calibration file update.

- Prepare and install the Authorized Modifications Label.
  - Using a permanent marker, enter the following information on the label:
    - Hybrid Control Module part number [Refer to the **Parts Information** section for the **NEW PART NUMBER**]
    - Calibration ID(s) [Refer to the **Calibration Information** section for the **NEW CALIBRATION ID**]
    - Dealer Code
    - Repair Date
    - Change Authority [This bulletin number]
  - Affix the Authorized Modifications Label to the vehicle at the location shown in Figure 1. The Authorized Modifications Label is available through the MDC, P/N 00451-00001-LBL.
- Test-drive the vehicle to confirm normal vehicle operation and the condition is no longer present.