

97 Check engine light sporadically lights up in instrument cluster, DTC: U014000 and U110100 are stored together 97 22 87 2068037/1 September 16, 2022.

Model(s) Year VIN Range Vehicle-Specific Equipment
--



A4, A4 allroad, S4, A5, A5 cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, A6, A7, A8, Q5, SQ5, Q7, and Q8	2019 – 2023		
RS 5, and RS 5 Sportback	2019 2021 – 2023	All	Not Applicable
A8 e quattro	2020		
S6, A6 allroad, S7, S5, SQ7, SQ8, and RS Q8	2020 – 2023		
A7 e quattro	2021 – 2022		
RS 6 Avant, RS 7, Q5, and Q5 Sportback	2021 - 2023		

Condition

Customer states:

The check engine lamp intermittently is displayed in the instrument cluster when the vehicle is started.

Workshop findings:

Page 2 of 5

© 2022 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



The following DTC is stored in the engine electronics J623 (diagnostic address 0001):

 DTC U014000: Body Computer 1/ Vehicle Electrical System Control Module, no communication, sporadic, symptom 23755.

The following DTC is stored in the onboard supply control unit J519 (diagnostic address 0009):

• DTC U110100: Component protection active, sporadic, symptom 15361024.

Technical Background

When component protection is active, the parking aid behaves in the same way as when terminal 15 is switched off and does not send any messages over the network. This causes the engine control unit to activate the warning lamp.

Production Solution

Software updated in production.

Service

This TSB replaces Pending Service Solution (PSS) 2067133: *PSS 97 Yellow check engine lamp sporadically lights up in the instrument cluster: DTC U014000 and U110100 are stored.*

- If both DTC's are stored as shown above, replace the onboard supply control unit. Ensure the replacement test plan is used for the exchange of the module.
- If other DTC's or concerns related to component protection present, resolve these using the corresponding test plan(s) in Guided Fault Finding.

Page 3 of 5



Warranty

Claim Type:	 110 Up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only. 				
Service Number:	9710				
Damage Code:	0039				
Labor Operations:	Remove and install/replace onboard supply control unit	9710 1950	See SRT with associated operations		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 100 TU)		
	Road test prior to the service procedure	No allowance	0 TU		
	Road test after the service procedure	No allowance	0 TU		
Claim Comment:	As per TSB 2068037/1				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Page 4 of 5



Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.					
Part Number	Part Description	Quantity			
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA			
See ETKA	Onboard supply control unit	1			

Additional Information

All part and service references provided in this TSB (2068037) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.