

**Taycan - Squeaking Noises from Front Seats**

**Vehicles Affected**

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	As of 2020	Y1A, Y1B, Y1C	n/a	n/a

**Revision History**

Revision	Release Date	Changes
0	September 8, 2022	Original document
1	September 27, 2022	Recommended insulating material

**Condition**


Customer concern of squeaking noises from the front seat.

**Technical Background**

This may be caused by multiple contact points within the seat assembly.

**Service Information**

Please apply insulating material to the locations indicated in the photos.



Recommended insulating material:

999 551 140 40

999 551 138 40




Figure 1 - Felt Application Points

### Warranty

As always, please document the repair completely in PCSS. For this repair, please code the "cause" as follows:

Cause location: 72090 Front Seat

Cause symptom: 2019 Squeaks

Use the following troubleshooting labor operation:

72261901 Backrest cover remove and reinstall (Left)

72261902 Backrest cover remove and reinstall (Right)

### Search Items

Seat squeaks, Taycan, Y1A, Y1B, Y1C, noises, seat frame, backrest

---

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

---