

WNL6 Workshop Campaign - Reworking fastening screws on rear lid hinge

WNL6 Workshop Campaign - Reworking fastening screws on rear lid hinge

ID Number	WNL6
Models	718 Spyder (982)
Model Years	2020-2022
VIN List	Attached
Number of Affected VINs	988
Issue Description	<p>There is a possibility that the fastening screws on the rear lid hinge on the affected vehicles were not tightened to the specified tightening torque. This can result in reduced clamping force due to falling preload force over the service life of the vehicle, resulting in a visible change in the joint appearance between the lid and side panel.</p> <p>To prevent this from happening, the fastening screws on the rear lid hinge on the affected vehicles must be tightened to the specified tightening torque.</p>
What Dealers Should do	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>As of the time of this posting, the repair is immediately available.</p>
TI Number	No. 157-22

Warranty processing

Validity:

This workshop campaign will be carried out up to August 25th, 2027 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

WNL6 Workshop Campaign - Reworking fastening screws on rear lid hinge

Damage Code	WNL6 66 000
Repair Code	1
Labour time	31 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.