

#### 40 Creaking/squeaking noises from the front end on uneven roads

40 22 48 2043424/13 October 12, 2022. Supersedes Technical Service Bulletin Group 40 number 21-28 dated September 16, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3, and S3	2015 – 2020 2022 – 2023		
A3 e-tron Sportback	2015 – 2018	All	Not Applicable
RS 3	2017 – 2020 2022 – 2023		
Q3	2019 – 2023		

### Condition

REVISION HISTORY			
Revision	Date	Purpose	
13	-	Revised header (Added Models and Model Years) Revised <i>Warranty</i> (Added Labor Operations)	
12	09/16/2021	Revised Warranty (Corrected Labor Operations)	
11	12/07/2020	Revised Warranty (Corrected Labor Operations)	

### Page 1 of 8

#### © 2022 Audi of America, Inc.



#### Customer states:

• Creaking/squeaking noises are heard from the left front or right front area of the vehicle when it is driven on uneven roads.

## **Technical Background**



Try to duplicate this condition exactly. If you cannot, do not perform this TSB.

Overview of the lower control arm and bushing (Figure 1).




Figure 1. Lower control arm and bushing.



The rear bonded rubber bushings of the front lower control arms have kidney-shaped slits (Figure 2). When the vehicle is driven on uneven roads, areas A and B (Figure 2) may come in contact, creating a creaking/squeaking noise.




Figure 2. Kidney-shaped slits (yellow arrows) of the rear bonded rubber bushings.

### **Production Solution**

### Page 3 of 8



Not applicable.

### Service

- 1. Remove both front lower control arms. Follow instructions in Elsa at Repair Manual, *Chassis >> Suspension, Wheels, Steering >> Front Suspension >> Lower Control Arm and Ball Joint >> Lower Control Arm, Removing and Installing.*
- 2. Evenly grease the kidney-shaped slits of the bonded rubber bushing (Figure 3, the area shown red) from above with 0.1g of lithium grease (part number G 052 150 A2). Use a paintbrush to apply the grease.



The lithium grease must only be applied to the areas shown in red (Figure 3).



Figure 3. Lithium grease is applied on the red highlighted area only.

3. Reinstall all components according to Elsa.

## Warranty



Claim Type:	G10 for CPO Covered	<ul> <li>G10 for CPO Covered Vehicles – Verify Owner.</li> <li>If vehicle is outside any warranty, this Technical Service Bulletin is</li> </ul>		
Service Number:	4020	4020		
Damage Code:	0020	0020		
Labor Operations:	All Models:			
	Front wheel track adjusted	4488 1550	See SRT with associated operations	
	Front wheel camber adjusted	4489 1550	See SRT with associated operations	
	Noise dampening pan removed + reinstalled (Except A3 Cabriolet)	1082 1900	See SRT with associated operations	
	Lowering subframe (Only engine code CNSB with transmission QYZ)	4007 1999	100 TU	
	Rear wheel track adjusted	4493 1550	See SRT with associated operations	
	Rear wheel camber adjusted	4494 1550	See SRT with associated operations	

### Page 5 of 8



Vehicle front + rear measured	4495 0350	See SRT with associated operations
A3 Sedan/Q3		
Both lower control arms remove + reinstall (A3)	4017 2001	See SRT with associated operations
Both lower control arms remove + reinstall (Q3)	4017 2000	See SRT with associated operations
Grease the bonded rubber bushings	4017 4199	10 TU
A3 Cabriolet:		
Both lower control arms remove + reinstall	4017 2000	See SRT with associated operations
Grease the bonded rubber bushings	4020 4199	10 TU
A3 e-tron, A3 e-tron sportback:		
Both lower control arms remove + reinstall	4017 2002	See SRT with associated operations
Disable HV system voltage	9310 0050	See SRT with associated operations



	Grease the bonded rubber bushings	4020 4199	10 TU
Diagnostic Time:	GFF (if applicable)	0150 0000	Time as stated on diagnostic protocol (Max 50 TU)
	Road test prior to service procedure	0121 0002	10 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB 2043424/13		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## **Required Parts and Tools**

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.			
Part Number	Part Description	Quantity	
G 052150A2	Lithium grease	0.1	
See ETKA	One-time use hardware according to Elsa	As needed	
See ETKA	Fasteners, Bolts, Nuts and Screws as needed per the Repair Manual	See ETKA/ELSA	

#### Page 7 of 8



#### Additional Information

More information on this system can be found in the following resources:

Elsa: Chassis >> Suspension, Wheels, Steering >> Front Suspension >> Lower Control Arm and Ball Joint >>
Lower Control Arm, Removing and Installing.

All parts and service references provided in this TSB (2043424) are subject to change and/or removal.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.