



SIB 61 17 22

2022-09-07

BATTERY DISCHARGE MESSAGE DISPLAYED, AND "AMBIENT LIGHTING" CANNOT BE ADJUSTED

MODEL

E-Series	Model Description	Affected Option Code
F44	2 Series Gran Coupe	563 Lights Package

SITUATION

After programming the vehicle using ISTA version 4.36.2x, the vehicle will not enter a sleep cycle. If the vehicle is not driven for a long time, the battery can partially discharge. This can cause a battery check control message/fault code to appear.

Additionally, the interior "Ambient lighting" color defaults to purple which cannot be adjusted.

Check control message (CCM) indicates:

- (ID 415): Energy management

Fault code stored in the BDC (Body Domain Controller):

- 80402F: Power management, battery condition: Total discharge

Note: Only F44 vehicles that have been programmed with ISTA version 4.36.2x are affected.

CAUSE

A software error in the BDC (Body Domain Controller).

CORRECTION

Program the vehicle using ISTA version **4.37.2x (S18A-22-07-545)** estimated release September 7, 2022 pending verification.

PROCEDURE

1. Determine the vehicle's current I-Level by either AIR or ISPI NEXT application.
 - If the vehicle's I-Level is below S18A-22-07-545, continue to step 2
 - Otherwise, if the I-level is greater than or equal to I-level S18A-22-07-545, continue diagnosis using ISTA
2. Program the vehicle using ISTA version **4.37.2x (S18A-22-07-545)** or higher.

Note: ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

Always connect a BMW-approved battery charger/power supply ([SIB 04 23 10](#)) when performing programming.

PARTS INFORMATION

Parts replacement is not required.

CLAIM INFORMATION

During this workshop visit, the affected vehicle may show one or more programming and encoding Technical Campaign repairs open, the programming and encoding procedure may only be invoiced one time.

Select one of these open Technical Campaigns to perform and submit for updating the vehicle's software to the required I-level or higher.

Please be sure to perform any additional before and/or after work (including attaching labels) as required by the open campaigns on the vehicle. Close any remaining open programming and encoding Campaign repairs as outlined in the corresponding Service Information Bulletin.

Only if the above situation does not apply, the BMW software solution is then:

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks, or the BMW Certified Pre-Owned Program as described below.

Defect Code:	6138270200	BDC Body Domain Controller Software error / internal device fault
---------------------	-------------------	--

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

Labor Operation	Description	Labor Allowance
00 00 006	Performing vehicle test (with vehicle diagnosis system – checking faults) (Main work)	Refer to AIR
Or:		
00 00 556	Performing vehicle test (with vehicle diagnosis system – checking faults) (Plus work)	Refer to AIR
And:		
61 21 528	Support voltage of the vehicle electrical system / recharge vehicle electrical system battery	Refer to AIR
And, as necessary:		
61 00 006*	Performing vehicle diagnosis – test module (Work time)	WT
Or		
00 58 500*	Diagnosis Worktime Flat Rate (See below)	2 FRU
And		
61 00 730	Programming/encoding control unit(s)	Refer to AIR

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006, or exclude (including 61 21 528) when the Vehicle Test is included in another repair.

Work time labor operation codes 61 00 006 and 00 58 500 are not considered a Main labor operations.

Or, if the:

Vehicle is still in the workshop due to the prior programming procedure

Labor Operation	Description	Labor Allowance
61 00 731	Additional work after 1st termination when programming/encoding Associated work (with job item no. 61 00 730)	Refer to AIR

*Based on which one applies to your center, please refer to [SI B01 01 20](#) or [B01 07 20](#) for the applicable procedure for documenting, claiming, and explaining, on the RO and in the claim comments, your diagnosis work time (WT), job/repair work time (WT), and the vehicle repairs your center performed, unless otherwise required by State law.

Programming and Encoding - Vehicle Control Units (RO and Claim Comments Required)

This procedure automatically reprograms and encodes any vehicle control modules that do not have the latest software I-level.

If one or more control modules fail during the reprogramming procedure, claim the required consequential repair work procedures to address this issue (including performing the IRAP Control Unit Recovery first as required, refer to the SIB in AIR) under the Defect Code in this bulletin with the labor operations in AIR that apply.

Please explain the additional work procedures that were performed (The why and the what) on the repair order and in the claim comments.

For covered repairs that address control module failures that occurred prior to performing this reprogramming procedure, claim this work with the Defect Code and labor operations (including diagnosis that applies*) in AIR that apply.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topics of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department