



TECHNICAL SERVICE BULLETIN

Without Remote Park Assist - Power Hood (Frunk) Exterior Buttons Inhibited During Two Stage Lock

22-2385

12 October
2022

Model:

Ford 2022 F-150 Lightning

Issue: Some 2022 F-150 Lightning vehicles not equipped with the remote park assist feature may experience an inoperative power hood (frunk) when using the exterior frunk button. This is due to the vehicle not being equipped with the front antennas for a passive key fob search. To correct this condition, follow the Service Procedure to reprogram the front hatch control module (FHCM) and body control module (BCM) which will improve frunk functionality by enabling the exterior frunk button when the hood is in an open state.

Action: Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2022 F-150 Lightning
- Not equipped with remote park assist
- Inoperative power hood (frunk) when using the exterior frunk button while the hood is opened

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2022 F-150 Lightning: Reprogram The FHCM And BCM (Do Not Use With Any Other Labor Operations)	222385A	0.4 Hrs.

Repair/Claim Coding

Causal Part:	14A626
Condition Code:	04

Service Procedure

1. Reprogram the FHCM and BCM using the latest software level from the Ford Diagnosis and Repair System (FDRS).

© 2022 Ford Motor Company
All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.