

Published date: 10/3/2022

Preliminary Information

PIP5881 Transmission Overheat Shudder Lack Of Power From A Launch - DTC P054F

Models

Brand:	Model:	Model Years:	VIN:		Engino	Transmissions:
			from	to	Engine:	Halisillissions.
Chevrolet	Silverado	2022	All	All	6.6L (L5P)	MGM MGU
GMC	Sierra	2022	All	All	6.6L (L5P)	MGM MGU

Involved Region or Country	North America & NA Exports.
	Some customers may comment that they are experiencing a check engine light, lack of power or sluggish when accelerating from a stop, elevated transmission temperatures, an engine idle surge or rough idle while stopped in gear with the driver foot on the brake pedal.
	Engine and transmission performance will be normal once the vehicle is moving.
	Transmission oil temperature will drop to normal once the vehicle is moving.
	Diagnosis will reveal DTC P054F Idle Control - Fuel Quantity Higher Than Expected.
	Monitoring of GDS data will show engine load 30% or higher when the transmission is in gear stopped with the brake pedal applied.
	Monitoring of the transmission temperature will show a rapid rise in temperature while stopped with the brake pedal applied.
	Engine load and transmission temperature will return to normal levels once vehicle is moving.

Correction:

With the engine off remove the oil level check plug and get a sample of transmission fluid.

If the fluid is severely distressed the transmission torque converter has experienced an internal failure.

** With a transmission build dates between January 3,2022 (Julian Date 003) and April 4,2022 (Julian Date 094).



Using the picture above as a guide.

Calendar Year – third and fourth digits should be 22

Build Date – fifth, sixth and seventh digits should be between 003 and 094 **

Replacement of the Torque Convertor and Transmission filter will be required.

*** Note - This P/I will update to a TSB in the future. ***

Version History

Version	1
Modified	10/03/2022 - Created on.

















GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.