



Preliminary Information

PIT5954 WIFI Hotspot Inoperative And OnStar Red LED And No Button Response After Remote Start With Keyfob

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2020	All	All	All	All
GMC	Sierra	2020	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UE1, IOS, IOT
Condition	Customers may comment that Wifi Hotspot is inoperative, and the OnStar has a red LED and no button response when using remote start feature from the keyfob.
Cause	The cause of the concern is unknown at this time. Engineering is working to identify the root cause.

Correction:

Engineering is aware of the concern and working on the field fix.

The PI will be updated when a fix is made available. Until a fix is available, the concern can be temporarily corrected by turning off the ignition and then restarting the vehicle manually.

Do Not replace any parts at this time.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
3487638*	OnStar LED Red And Wifi Hotspot Inoperative After Remote Vehicle Start	.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	10/7/2022 - Created.

