



Preliminary Information

PIP5873 3.0L Diesel (LZ0) Engine Exchange Program

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500	2023	All	All	3.0L (LZ0)	All
GMC	Sierra 1500	2023	All	All	3.0L (LZ0)	All

Involved Region or Country	North America
Condition	Engine Exchange
Cause	New Product Monitoring

This PI will cover the engine exchange program only for the 2023 model listed above.

Additional PIs will be published for each engine or component as they are introduced.

During the launch of the 2023 model year, the following engine will be under an exchange program:

3.0L Diesel Engine (LZ0)

Product teams continually seek valuable information for engineering improvements.

To assist in this effort, an engine exchange program will be used for the listed engine and vehicles.

Any repairs involving engine components not identified in the table below, engine noise concerns, oil consumption or related symptoms may require an engine exchange.

Important: Engine block and internal components along with any component in which a cylinder head has to be removed to perform the repair will require an engine exchange.

Please note that this list is subject to change as the program progresses.

You will be notified by the PQC consultant if additional items are considered serviceable on a particular engine.

The 2023 model year engine exchange program will be administered by the GM Product Quality Center (PQC).

Dealerships are required to contact the PQC (not GM Technical Assistance (TAC)) to request an exchange.

Prior to contacting the PQC, please make sure to complete the "OEM Engine Exchange" template in this PI.

Use of the templates will minimize the time spent in contact with the PQC and avoid the need of a second interaction.

Guidelines for honoring exchange requests under this program are being strictly enforced.

The PQC may refer the dealer technician to TAC if additional diagnosis is required.

TAC will be available for product inquiries that do not require assembly replacement.

Please have the part number available prior to contacting the PQC/TAC.

U.S. Dealers:

Please contact the Product Quality Center (PQC) by opening a new case via Dealer Case Management (DCM) From the DCM home page, click on "New PQC Case" found on the Technical Assistance tab.

Canadian Dealers:

Please contact the PQC by email at PQC@gm.com or by calling 1-866-654-7654 to receive the PQC -Parts Restriction Template then, return the completed Parts Restriction Questions for engineering review.

Components that may be removed and serviced without exchange are identified by an "X" in the appropriate column of the table below.

Any repairs involving engine components not identified in the table below, engine noise concerns, oil consumption, or related symptoms may require an engine exchange.

Important: Engine block and internal components along with any component in which a cylinder head has to be removed to perform the repair will require an engine exchange.

Please note that this list is subject to change as the program progresses.

You will be notified by the PQC consultant if additional items are considered serviceable on a particular engine.

Serviceable Components	3.0L (LZ0)
Accessory Drive	X
A/C Compressor	X
AI Coolant Hoses	X
All Engine Sensors	X
Brackets	X
Coolant Pump	X
Cooling System Bypass Pipe	X
Cooling System Hoses	X
Cooling System Radiator Inlet / Outlet Pipes	X
Crankshaft Dampner	X
EGR Cooler Assembly	X
EGR Cooler Pipes	X
EGR Temperature Sensor	X
EGR Valve	X
Engine Coolant Flow Control Valve	X
Engine Coolant Sensor	X
Engine Control Module (ECM)	X
Engine Cover / Beauty Cover	X

Engine / Transmission Mounts	X
Engine Oil Cooler	X
Engine Wiring Harness	X
Exhaust Manifold / Gasket	X
Exhaust Temperature Sensors	X
Flywheel / Flex Plate	X
Fuel Injectors	X
Fuel Injector Wiring Harness	X
Fuel Lines - High and Low Pressure	X
Fuel Pipes and High Pressure Fuel Pump Assembly	X
Fuel Rail	X
Generator	X
Glow Plugs	X
Heater Outlet / Inlet Fittings	X
Intake Air Ducts and Related Components	X
Intake Air Temperature Sensor	X
Intake manifold	X
Manifold Absolute Pressure / Intake Air Temperature Sensor	X
Mass Airflow Sensor	X
Oil Fill Cap	X
Oil Filter	X
Oil Level Indicator and Tube	X
Lower Oil Pan Gaskets	X
Oil Pressure Switch / Sensor	X
Oil Pressure Control Valve Solenoid	X
PCV Hose	X
Starter Motor and Solenoid	X
Throttle Body/Related Components	X
Turbocharger Assembly	X

Note: The above service parts list of components may be requested through the normal GM Parts return process for engineering evaluation for cause through the WPC parts return process.

Important: Engine repairs or failures caused by components external to the engine do NOT fall under the exchange program. For example, if an engine failure is caused by incorrectly installed engine coolant lines, the engine assembly (or parts required to complete a repair) must be obtained from General Motors Customer Care and Aftersales (GMCC&A) through the normal parts ordering process.

The exchange program is created as a way to correct internal concerns and to take what is learned and find a way to eliminate these concerns. External components causing a failure do not provide any useful information in improving an engine. The engine received from GMCC&A through the normal parts ordering process will be a new service engine.

Procedures:

A thorough diagnosis must be performed on the condition in order to prevent unnecessary component replacements. Contact the Product Quality Center (PQC) to verify the proper diagnosis has been performed.

Upon review of the diagnosis, the PQC will establish a case reference number and make arrangements for shipping an exchange unit to your dealership.

The replaced engine must be returned to the Warranty Parts Center (WPC)

DO NOT SHIP AN ENGINE TO THE (WPC) WITHOUT AN OFFICIAL WPC REQUEST

Important: Failure to return the replaced engine by the due date will result in the dealership being debited the entire warranty claim (parts and labor). The removed unit must be returned complete in the original exchange shipping container. For effective engineering analysis, please do not remove any components. Dress items on the removed unit must remain the same as the replacement engine (e.g., exhaust manifolds, throttle body, etc.). Dealerships returning engines/components that have been even partially disassembled will be judged as violating this procedure and, as such, will be billed for all materials furnished.

Notice: The exchange unit will be shipped with a quantity of oil (one quart over full, refer to bulletin 22-NA-192). Verify the oil level before starting the engine. Low oil level could result in internal engine damage.

Low oil level could result in internal engine damage.

WPC Request:

The Warranty Parts Center (WPC) will fax a Special Part Request to your dealership requesting the return of the removed engine.

DO NOT wait for the warranty claim to be paid before returning the removed engine.

The Special Part Request will provide a request number

This request number must be written on the outside of the return container using a permanent marker.

Failure to write the request number on the return container may delay the processing of your return.

If you do not receive the WPC Special Part Request, contact Julie Cumo at 248-371-9939 (for French call PQC 1-866-654-7654) to obtain the proper paperwork in order to return the removed engine. Failure to return the engine may result in a debit.

Shipping Preparation:

1. Remove the engine assembly/component as outlined in the applicable Service Manual.
2. Drain all fluids from the removed engine.
3. Retorque any fasteners that were loosened or removed to the original torque specification.
4. Remove any plastic shipping plugs and covers from the exchange unit and install them on the removed unit.
5. If the concerned engine leaks, mark the area directly on the engine with a permanent marker.
6. Write the PQC case reference number on the repair order form.
7. Write the PQC case reference number directly on the component in a visible location.
8. Insert a copy of the WPC Special Part Request, repair order with technician comments, and the completed OEM Engine Exchange Worksheet (template in this bulletin) into a plastic bag and securely fasten to the engine.
9. Place the removed engine into the original shipping container.

Shipping Instructions:

1. Write the WPC request number and the PQC case reference number on the outside of the container with a permanent marker.
2. U.S. Dealers – Please go to www.gmwpc.com, click on the UPS emblem, enter your BAC and select “dealer inquires.” Select “available forms” located on the left side of the screen in blue, then select “Central Transport BOL.” A partially complete BOL will appear. Please print this Central Transport BOL and fill out “from” section with your dealer information and complete the description fields.

Canadian Dealers – Refer to the latest version of Corporate Bulletin Number 99-00-89-019 for detailed shipping information.

3. Contact the specified carrier to arrange for pick-up of the removed engine. If lift gate service is necessary, please request it at the time of arranging pick-up service.

4. Have the driver sign the bill of lading. Retain a copy of the signed bill of lading. Attach your copy to the original repair order. This will be your proof of returning the removed engine.

5. Ship all return exchanges/components Third Party Freight Collect with appropriate paperwork

to:

GM Warranty Parts Center

45 Northpointe Drive

Orion, MI 48359

OEM Engine Exchange Worksheet

Contact's First and Last Name/Position:

Technician's Direct Phone:

Parts Manager's name:

Dealership's Shipping Address:

Q1: Customer's concern?

Was the concern duplicated? (Y/N)

Q2: Was TAC contacted? (Y/N)

- **TAC Case #:**
- **TAC Recommendations:**
- **Continue with the following Template questions**

Q3: Was the DMA contacted? (Y/N)

- **If yes, provide the DMA Name/Email:**
{If the DMA authorized replacement, STOP. Do not continue template.} Contact PQC with the template

Q4: Has the vehicle been modified with non-production accessories? (Y/N)

Describe the Modifications

Q5: Is the vehicle for personal or commercial use?

Q6: Describe the failure of the engine:

Q7: Using GDS2 does the vehicle have any DTCs in the ECM/TCM/BCM? (Y/N)

List all the codes and the module they set in. Perform necessary diagnosis related to these codes.

If diagnostics have not been completed for these codes, explain why.

Q8: Are there any leaks (Y/N)

- **What type of leak?**
- **Location of the leak?**

Q9: Are there any Noises (Y/N)

- **What kind of noise?**
- **Location and frequency of the noise?**
- **When does it occur?**
- **How long does it last?**

Q10: Any Lubrication Concerns (Y/N)

- **Oil level when vehicle arrived:**
- **Last oil change (if applicable):**
- **Oil pressure readings:**
- **Results of oil consumption test:**
- **Was the oil contaminated?**
- **If yes, what type of contamination?**

Q11: Any Performance Concerns (Y/N)

- **Low power?**
- **Misfire?**
- **Detonation?**
- **Blue smoke?**

- **White smoke?**
- **Will vehicle crank?**
- **Vibration?**

Q12: Did the engine show evidence of:

- **Overheating?**
- **Coolant consumption?**
- **Coolant contamination?**
- **Low compression?**

If yes to any of the above, please provide the readings:

Parts Information

For vehicles repaired under warranty, use:

Description	Part Number	Quantity
Engine (LZ0)	12731655	1

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4067490	Engine Replacement	Use Published Labor Operation Time
Add	Administrative Allowance	0.2 HR
For engine exchange only: A \$400.00 misc. net allowance for the engine can be claimed in the warranty transaction		

Version History

Version	1
Modified	10/06/2022 - Created



GENERAL MOTORS

© 2022 General Motors. All Rights Reserved.