



NUMBER: 21-030-22

GROUP: 21 - Transmission and Transfer Case

DATE: October 5, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Flash: Transmission Control Module (TCM) Updates

OVERVIEW:

This bulletin involves reprogramming the TCM with the latest available software.

MODELS:

2022	(D2)	RAM 3500 Pickup
2022	(DD)	RAM 3500 Cab Chassis
2022	(DP)	RAM 4500/5500 Cab Chassis

NOTE: This bulletin applies to vehicles within the following markets/countries: North America.

NOTE: This bulletin applies to vehicles equipped with the following:

- D2 vehicles equipped with an 6.7L I6 Cummins HO Turbo Diesel Engine (Sales Code ETM) and an 6-SPD Auto Aisin AS69RC HD Transmission (Sales Code DF2).
- DD/DP vehicles equipped with an 6.7L I6 Cummins Turbo Diesel Engine (Sales Code ETN) or with an 6.4L V8 Heavy Duty Hemi Engine (Sales Code ESB) and an 6-SPD Auto Aisin AS69RC HD Transmission (Sales Code DF2) or an 6-SPD Auto Aisin AS66RC HD Trans (Sales Code DF3).

SYMPTOM/CONDITION:

Customers may comment on one or more of the following:

- Harsh shifts.
- Poor shift quality, with light pedal. **(Sales Codes ETM and ETN Only).**
- Poor shift quality, 32-48 kph (20-30 mph), at low rpm with light to medium pedal apply, typically tipping in from zero pedal. **(Sales Codes ETM and ETN Only).**
- Coasting shift bump with exhaust brake and/or tow/haul active. **(Sales Codes ETM and ETN Only).**
- Poor shift quality, often when increasing pedal during a shift. **(Sales Code ESB Only).**
- Squawk/chirp/squeak type noise during a 3-4 upshift. **(D2 Only).**
- Poor 1-2 upshift quality. **(D2 with ETM or DD/DP with Sales Code ESB Only).**

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the one listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the TCM with the latest available software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-19-05-RP	Module, Transmission Control (TCM) - Reprogram (0 - Introduction)	2 - Automatic Transmission	0.3 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 5 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

CC	Customer Concern
----	------------------