

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 22-193, date of issue October 18, 2022. All applicable Sold and Un-Sold RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

**SUBJECT:**

Sunroof Misaligned

**OVERVIEW:**

This bulletin involves inspecting the sunroof glass to roof flushness and if needed, adjusting the sunroof glass.

**MODELS:**

2022 (WD) Dodge Durango

**NOTE:** This bulletin applies to vehicles within the following markets/countries: North America, Enlarged Europe, India/Asia Pacific, Middle East/Africa and South America.

**NOTE:** This bulletin applies to vehicles built on or after March 01, 2022 (MDH 0301XX) on or before June 28, 2022 (MDH 0628XX) equipped with a Power Sunroof (Sales Code GWA).

**SYMPTOM/CONDITION:**

Customers may comment on the following:

- Sunroof misaligned, causing a water leak into the vehicle.

**DIAGNOSIS:**

If a customer's VIN is listed in VIP or your RSU/VIN list, perform the Inspection Procedure. **This RSU only applies to vehicles on the RSU VIN list.**

1. Measure sunroof glass to roof flushness ([Fig. 1](#)). The sunroof glass should be between -2.5 mm (0.098 in.) to flush at the front and flush to +2.5 mm (0.098 in.) at the rear.



Fig. 1

Measuring Sunroof Glass To Roof Flushness

2. Was the sunroof glass between -2.5 mm (0.098 in.) to flush at the front and flush to +2.5 mm (0.098 in.) at the rear (Fig. 1) ?
  - YES>>> Further diagnosis should be performed, use inspect LOP (23-30-65-9P) to close the active RSU.
  - NO>>> Proceed to [Step 1](#) of the Repair Procedure.

**REPAIR PROCEDURE:**

**NOTE: No parts are required for this Repair Procedure. Only adjust the two outer screws on each side of the sunroof (Fig. 2) . Do not loosen the middle screw on either side of the sunroof.**

1. Adjust the sunroof glass (Fig. 2) . Refer to the detailed service procedures available in DealerConnect> Service Library under: Service Info>23 - Body / Sunroof, Single Pane / Glass, Sunroof / Adjustments.



Fig. 2

Left Side Sunroof Adjusting Screws (Right Side Identical)

1 - Two Left Side Adjusting Screws To Adjust

2. Perform a sunroof glass seal leak test. Refer to the detailed service procedures available in DealerConnect> Service Library under: Service Info>23 - Body / Sunroof, Single Pane / Diagnosis and Testing.
3. Did the sunroof leak water?
  - YES>>> Repeat [Step 1](#) through [Step 2](#) until no water leaks are present.
  - NO>>> This bulletin has been completed.

**NOTE: Obtain duly approval for replacement of the headliner if it is wet. Do not automatically replace the headliner. Refer to the detailed service procedures and LOP times available in DealerCONNECT/Service Library.**

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
23-30-65-9P	Inspect Sunroof Glass Alignment (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
23-30-65-9Q	Inspect and Adjust Sunroof Glass (0 - Introduction)	6 - Electrical and Body Systems	0.4 Hrs.

**FAILURE CODE:**

ZZ	Service Action
----	----------------