

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS6369  
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 13, 2022

Subject: N222359240 - Customer Satisfaction Program  
Outside Rear View Mirror Not Dimming

Models: 2021 – 2022 Chevrolet Blazer

To: All General Motors Dealers

General Motors is releasing Customer Satisfaction Program N222359240 today. The total number of U.S. vehicles involved is approximately 6,723. Please see the attached bulletin for details.

**Customer Letter Mailing**

The customer letter mailing will begin in December 28, 2022.

**Global Warranty Management (GWM)**

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated December 13, 2022. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS

# Customer Satisfaction Program

## N222359240 Outside Rear View Mirror Not Dimming



Release Date: December 2022

Revision: 00

**Attention:** This program is in effect until January 31, 2025.

Make	Model	Model Year		RPO	Description
		From	To		
Chevrolet	Blazer	2021	2022		

Involved vehicles are marked "Open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

<b>Condition</b>	Certain 2021 - 2022 model year Chevrolet Blazer vehicles, may have a condition in which the driver side mirror does not auto dim.
<b>Correction</b>	Dealers are to replace the front door wiring harness.

### Parts

Quantity	Part Name	Part No.
1	HARNESS, FRT S/D DR WRG	87864497
1	HARNESS, FRT S/D DR WRG	87864498
1	HARNESS, FRT S/D DR WRG	87864499

**Note:** Use the VIN and the GM Electronic Parts Catalog (EPC) to determine which harness to order.


**Reminder:** Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

### Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9106297	Replace Front Side Door Wiring Harness	1.0	ZFAT	N/A

### Service Procedure

1. Remove the front side door water deflector. Refer to *Front Side Door Water Deflector Replacement* in SI.
2. Temporarily connect the door trim panel electrical switches to position the window in the fully up position and then disconnect.



6051664

3. Remove the front side door speaker.
4. Disconnect electrical connectors (1). Be sure to disconnect the wire harness connector to the front side door outside handle.
5. Disengage wire harness retaining clips (2).

# Customer Satisfaction Program

## N222359240 Outside Rear View Mirror Not Dimming



6. Push the harness rubber retainers through the door panel.
7. Carefully remove the front side door wiring harness.
8. Install new front side door wiring harness.
9. Install harness rubber retainers.
10. Insert wire harness retaining clips.
11. Connect electrical connectors.
12. Install front side door speaker.
13. Install front side door water reflector. Refer to *Front Side Door Water Deflector* in SI.

### Dealer Responsibility

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this program must be held and inspected/repaired per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealers are to service all vehicles subject to this program at no charge to customers, regardless of mileage, age of vehicle, or ownership, through January 31, 2025. Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the involved vehicle listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Program follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this program enters your vehicle inventory or is in your facility for service through January 31, 2025, you must take the steps necessary to be sure the program correction has been made before selling or releasing the vehicle.

### Dealer Reports – For USA & Export

For dealers with involved vehicles, a listing has been prepared and will be available through GM GlobalConnect Maxis Field Action Reports or sent directly to export dealers. The Inventory tab of the dealer reports will contain VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this field action may be a violation of law in several states.

### Courtesy Transportation – For USA & Canada

Courtesy transportation is available for customers whose vehicles are involved in a product program and still within the warranty coverage period. See General Motors Service Policies and Procedures Manual for courtesy transportation program details.

### Customer Notification

USA & Canada - General Motors will notify customers of this program on their vehicle (see copy of customer letter included with this bulletin).

Export - Letters will be sent to known owners of record located within areas covered by the US National Traffic and Motor Vehicle Safety Act. For owners outside these areas, dealers should notify customers using the attached sample letter.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support  
Voluntary Technician  
Certification**

# Customer Satisfaction Program

## N222359240 Outside Rear View Mirror Not Dimming



December 2022

This notice applies to your vehicle, **VIN:** \_\_\_\_\_

Dear General Motors Customer:

We have learned that your 2021 - 2022 model year Chevrolet Blazer may have a condition where the driver's side mirror does not auto dim.

Your satisfaction with your Blazer is very important to us, so we are announcing a program to prevent this condition or, if it has occurred, to fix it.

**What We Will Do:** Your GM dealer will replace the front door wiring harness. This service will be performed for you at **no charge until January 31, 2025**. After that, any applicable warranty will apply.

**What You Should Do:** To limit any possible inconvenience, we recommend that you contact your dealer as soon as possible to schedule an appointment for this repair. By scheduling an appointment, your dealer can ensure that the necessary parts will be available on your scheduled appointment date.

If you have any questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

For the hearing or speech impaired, please contact our Customer Assistance Center using the Telecommunication Relay Service by dialing 711 then providing the appropriate Customer Assistance Center number for your vehicle.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	711 / 1-800-833-2438
Puerto Rico – English	1-866-467-9700	
Puerto Rico – Español	1-866-467-9700	
Virgin Islands	1-866-467-9700	

We truly appreciate you taking the time to remedy your vehicle as we know your time is valuable. We want you to know that we will do our best, throughout your ownership experience, to ensure that your Chevrolet Blazer provides you many miles of enjoyable driving.

Neelie O'Connor  
Global Executive Director  
Customer Experience Operations

N222359240