



NUMBER: 23-010-22 REV. A

GROUP: 23 - Body

DATE: April 13, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Technical Service Bulletin (TSB) 23-010-22, date of issue March 10, 2022, which should be removed from your files. All revisions are highlighted with **asterisks**** and include an updated clean date.**

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 22-046, date of issue March 10, 2022. All applicable UnSold RSU VINs have been loaded. To verify this RSU service action is applicable to the UnSold vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. This RSU will expire 18 months after the date of issue.

SUBJECT:

Rear Windshield Wash Low Fluid Output / Inoperable

OVERVIEW:

This bulletin involves adjusting the rear wiper washer hose position.

MODELS:

2022 (WS) Grand Wagoneer/Wagoneer

NOTE: This bulletin applies to vehicles within the following markets/countries: North America.

NOTE: This bulletin applies to vehicles built on or after May 31, 2021 (MDH 0531XX) on or before **October 22, 2021 (MDH 1022XX)****.**

SYMPTOM/CONDITION:

Customers may comment on the following:

- The rear wiper wash is inoperative, or low fluid output.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

REPAIR PROCEDURE:

NOTE: Check fluid level in the washer fluid reservoir and fill as necessary before proceeding.

1. Cycle the rear washer spray. Does it have weak fluid output?
 - YES>>> Proceed to [Step 1](#).
 - NO>>> This bulletin has been completed, use inspect LOP (23-43-10-96) to close the active RSU.
1. Remove the D-Pillars. Refer to the detailed procedures available in DealerCONNECT > Service Library> under: 23 - Panel, D-Pillar Trim Removal and Installation.
2. Lower the headliner at the rear.
3. Adjust the washer hose to remove any kinks ([Fig. 1](#)).



Fig. 1

Rear Washer Hose Kink

4. Reposition the headliner at the rear.
5. Install the D-Pillars. Refer to the detailed procedures available in DealerCONNECT > Service Library> under: 23 - Panel, D-Pillar Trim Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-43-10-96	Hose, Washer (Rear) Verify Proper Functionality (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
23-43-10-97	Hose, Washer (Rear) - Partially Lower Headliner to Reposition Hose (0 - Introduction)	6 - Electrical and Body Systems	0.4 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------