



**NUMBER:** 08-079-22

**GROUP:** 08 - Electrical

**DATE:** April 14, 2022

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**SUBJECT:**

Flash: Body Control Module (BCM) Updates

**OVERVIEW:**

This bulletin involves updating the BCM with the latest available software.

**MODELS:**

2022 (DT) RAM 1500 Pickup

**NOTE:** This bulletin applies to vehicles within the following markets/countries: North America, APAC, LATAM and EMEA.

**NOTE:** This bulletin applies to vehicles built on or before March 11, 2022 (MDH 0311XX).

**SYMPTOM/CONDITION:**

Customer may comment one or more of the following:

- AUX switch "recall last state" function does not work, **only if equipped with a 6.2L Supercharged HEMI V8 SRT Engine (Sales Code ESD).**
- AUX output always returns to OFF unless user selects **battery** power over **ignition** power feed, **only if equipped with a 6.2L Supercharged HEMI V8 SRT Engine (Sales Code ESD).**

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

**REPAIR PROCEDURE:**

**NOTE:** Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

**NOTE:** If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the BCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.
3. Cycle the ignition off, unplug wiTECH pod and close the doors to let all modules go to sleep, this may take one minute.
4. Reconfigure the BCM, using wiTECH, restore vehicle configuration. This routine is available under the 'Guided Diagnostic'.

5. Reconnect wiTECH and clear any DTCs that may have been set in any module during the reconfigure.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

<b>Labor Operation No:</b>	<b>Description</b>	<b>Skill Category</b>	<b>Amount</b>
18-19-02-GT	Module, Body Control (BCM) - Reprogram, Includes Restore Vehicle Configuration (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.

**NOTE: The expected completion time for the flash download portion of this procedure is approximately 4 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.**

**FAILURE CODE:**

**The dealer must use failure code CC with this Technical Service Bulletin.**

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

CC	Customer Concern
----	------------------