



Technical Service Bulletin

93 Transmission Shifts to Park or Neutral at or Near a Stop

93 22 92 2068788/1 December 1, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2022	All	Not Applicable

Condition

Customer states:

- Occasionally when at or near a stop the driver finds the transmission has selected Park or Neutral on its own.

Workshop findings:

- No relevant DTCs are stored.
- The concern is intermittent.
- The ignition remains on.
- With the brakes applied the driver can select Drive or Reverse and continue driving.

Technical Background

- Due to a software error the engine control unit receives a message that requires it to command the transmission into “Park” or “Neutral”.
- The concern only happens below 3 mph.
- The concern can happen if the vehicle is in Drive or Reverse.
- The concern is only known with the following software combination:
 - Engine Control Module (ECM), J623 (address word 0001): 9J1907558E__0020 (Figure 1).



Technical Service Bulletin

Address: 0001 System name: 0001 - Engine Electronics Log versions:

<input type="checkbox"/> Identification:	
Data source:	Vehicle
Hardware part number:	9J1907522
Part number:	9J1907558E
Hardware version number:	H02
Software version number:	0020

Figure 1. Engine Control Module software part number and version number.

- High-voltage battery charger (OBC), J1050 (address word 00C6): 5QE915684CR __ 1088 (Figure 2).

Address: 00C6 System name: 00C6 - High-voltage battery charger Log versions:

<input type="checkbox"/> Identification:	
Data source:	Vehicle
Hardware part number:	5QE915684CR
Part number:	5QE915684CR
Hardware version number:	H74
Software version number:	1088

Figure 2. High-voltage battery charger software part number and version number.

Production Solution

Improved Software in Production.

Service

This bulletin replaces TSB 2067797: *PSS 93 Transmission Shifts to Park or Neutral at or Near a Stop*.

- If the above concern has been confirmed check for open Campaigns and Service Actions.
- The software improvement for this concern is included in the Service Action 93P9.
- Perform all open Campaigns and Service Actions in the order that they were released.

Warranty

This TSB is informational only and not applicable to any Audi warranty.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (**2068788**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.