

Advanced Technical Information

Bulletin #: 2234

Part ID: 9025

9

Improper Odometer and/or Speedometer Function

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
All	All	All	n/a	n/a

Revision History

Revision	Release Date	Changes	
0	December 8, 2022	Original document	

Condition

The vehicle's odometer and/or speedometer do not function properly.

Technical Background

A possible installation of an aftermarket-tampering device between the vehicle wiring harness and the instrument cluster that filters or blocks the signals for distance and speed could explain the concern.

Note: If installed, the device's location is typically behind the instrument cluster.







Advanced Technical Information

Bulletin #: 2234

Part ID: 9025

9

Service Information

If an aftermarket device has been found installed in a vehicle, notify the customer and report it to the warranty department via PRMS* with photo documentation.

(*select: Warranty Support -> Vehicle Information -> "Block Flag")

Search Items

Mileage, Odometer, Tampering, Tampered, Stopped, Freeze, Frozen

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.