

“Wanted Car:” 992- Injector Fault

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
911	2020 - 2022	992	N/A	N/A

Revision History

Revision	Release Date	Changes
0	December 20, 2022	Original document

Condition

Customer complains of car shutting down suddenly, engine bucking and/or check engine light coming on, with error code P020X00. X for each cylinder number.

CYLINDER 5	CYLINDER 6	CYLINDER 1	CYLINDER 2	CYLINDER 3	CYLINDER 4
P020500 – 009C7E	P020600 – 009C80	P020100 – 009C75	P020200 – 009C78	P020300 – 009C79	P020400 – 009C7B

Technical Background

These fault codes in combination with the listed vehicles is in analysis, please contact PCNA if this condition is found.

Affected Part Number: OPB128615A or OPB128615B

“Wanted Car:” 992- Injector Fault

Service Information

1. Please make sure to not disconnect or alter the affected injector from the engine wiring harness. PAG will perform a CT scan on the affected assembly therefore, it is crucial to leave the system in its original condition.
2. Please replace the affected injector together with the engine wiring harness.

Please contact Theo Jaeger

Tel: +1.404.229.8283

E-Mail: theodor.jaeger@porsche.us

Search Items

911, 992, injector, cylinder, P020X00

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
