



STAR ONLINE PUBLICATION



Case Number: S2208000193

Release Date: December 2022

Symptom/Vehicle Issue: Check Engine Light On, P057B - Brake Pedal Position Sensor "A" Circuit Performance

Discussion: The customer may bring their vehicle in for a check engine light. Upon scanning the vehicle for Diagnostic Trouble Codes (DTCs) you may find P057B - Brake Pedal Position Sensor "A" Circuit Performance. This may be caused by an incorrectly installed brake pedal position sensor.

Repair Procedure: Use the following procedure to inspect and correct the brake pedal position sensor installation.

1. Remove the driver's knee blocker trim per standard procedure.



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found



STAR ONLINE PUBLICATION




2. Locate the brake pedal position sensor.



3. Verify the brake pedal position sensor installation according to the steps indicated below.

Key Elements



This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found




STAR ONLINE PUBLICATION




Insert tab into pedal
box hole




Push clip rod and pull
lever until secure



Pull lever and
push until secure



Connect wiring
harness



4. Clear fault codes and test vehicle to confirm repair.
5. Install back the knee blocker trim per standard procedure.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found