

REFERENCE:	TSB: 31-002-22 GROUP 31 - Collision Bulletins	Date:	December 15, 2022	REVISION:	31-002-20
VEHICLES AFFECTED:	2019 - Current (DT) RAM 1500 Pickup 2020 - Current (JT) Jeep Gladiator 2019 - Current (BV) Jeep Renegade 2015- Current (4C) Alfa Romeo 4C 2017- Current (BA) FIAT 124 Spider (Convertible) 2013- Current (FF) FIAT 500 2017- Current (GA) Alfa Romeo Giulia 2018- Current (GU) Alfa Romeo Stelvio 2014- Current (KL) Jeep Cherokee 2013-2016 (PF) Dodge Dart 2013-2017 (ZD) Dodge Viper 2013- Current (DS) RAM 1500 Pickup 2013- Current (WK) Jeep Grand Cherokee 2013- Current (WD) Dodge Durango 2017- Current (RU) Chrysler Pacifica 2015-2018 (BU) Jeep Renegade 2018- Current (JL) Jeep Wrangler 2015- Current (LA) Dodge Challenger 2013-2014 (LC) Dodge Challenger 2013- Current (LD) Dodge Charger 2013- Current (LX) Chrysler 300 2017- Current (MP) Jeep Compass 2015-2017 (UF) Chrysler 200 2013- Current (JC) Dodge Journey 2013-2014 (JS) Chrysler 200 /Dodge Avenger 2013- Current (RT) Chrysler Town & Country/Dodge Grand Caravan 2019- Current (D2, DD, DF, DJ and DP) RAM Heavy Duty Trucks	MARKET APPLICABILITY:	<input checked="" type="checkbox"/> NA <input checked="" type="checkbox"/> SA <input checked="" type="checkbox"/> EE	<input checked="" type="checkbox"/> MEA <input checked="" type="checkbox"/> IAP <input type="checkbox"/> CH	
CUSTOMER SYMPTOM:	Aluminum corrosion or bubbling along the leading edge of hood, hinges or other exterior surface areas of the hinges, doors, fenders, swing gates or liftgates.				

This bulletin supersedes Technical Service Bulletin (TSB) 31-002-20, date of issue October 27, 2022, which should be removed from your files. This is a complete revision and no asterisks have been used to highlight revisions.

REPAIR SUMMARY:

NOTE: Digital imaging pre authorization is required for Smart Warranty Base dealers or Pre Approval is required from Regional Office depending on market.

This bulletin involves inspecting and if necessary removing corrosion and refinishing the suspect aluminum panels on the vehicle, hood, door, fenders, hinges, swing gates or liftgate panels.

SPARE PARTS:

Qty	Part No.	Description	Notes
3 (AR)	NPN	500 grit Sandpaper Sheet	
1 (AR)	NPN	800 grit Sandpaper Sheet	
1 (AR)	NPN	80 grit Sandpaper Sheet	
1 (AR)	NPN	180 grit Sandpaper Sheet	
1 (AR)	NPN	3M® 3" Clean and Strip Disc 3M® p/n 07470 or equivalent	
1(AR)	NPN	3M® Scotch-Brite Scuffing Disc 07467 Maroon or equivalent	
1	06103087AA	Anti-Corrosion Pen	

DISCUSSION:

Aluminum corrosion or bubbling along the leading edge of hood, hinges or other exterior surface areas of the hinges, doors, fenders, swing gates or liftgates.

NOTE: This only applies to aluminum panels. To determine if the panel is aluminum, refer to collision manual for material specifications> DealerCONNECT> Service Library> enter year, model, engine> select collision info tab (adjacent to diagnostic tab)> 31- Collision Information> Specifications> Standardize Material Identification.

NOTE: This bulletin does not apply to corrosion in the hem flange area; this will require panel replacement ([Fig. 1](#)).



Fig. 1
Hem Flange Area Example

DIAGNOSIS:

Aluminum corrosion or bubbling on the doors and/or hinges (Fig. 2) .



Fig. 2
Examples of Bubbling

Aluminum corrosion along the leading edge of hood or other exterior surface areas of the doors, fenders or liftgates (Fig. 3) .



Fig. 3
Examples of Corrosion Along Leading Edges

Is corrosion evident on the aluminum panel surface (Fig. 3) ?

- YES>>> Must receive authorization from vehicle digital imaging and/or Regional Office. Once approval is received from digital imaging or Regional Office, Proceed to [Step 1](#) of the diagnosis procedure.
 - NO>>> Submit the vehicle digital image for further analysis.
1. Remove blistered paint from the panel surface with 80 grit grinding disc.
 2. After digital imaging or Regional Office approval and removing the initial blistered paint from the panel surface with 80 grit grinding disc, is severe pitting exhibited that cannot be removed with sandpaper, 3M Clean and Strip Disc or equivalent (Fig. 4) ?



Fig. 4
Corrosion Examples

- YES>>> Replace the panel.
- NO>>> Proceed to [Step 1](#) of the repair procedure.

REPAIR PROCEDURE:

NOTE: When sanding and prep is done you must use clean sanding pads and in a separate room from ferrous metals, as cross contamination will lead to galvanic corrosion.

1. Remove affected panel. Refer to the detail service procedures available in: DealerCONNECT> Service Library under: Service Info> 23-Body> Exterior> Removal.

CAUTION! For any panel with exterior mounted hinges, avoid removal of the hinge from the Class-A panel unless absolutely required. This will minimize the risk of breaking paint around the hinge perimeter which will create further damage and additional sites for subsequent corrosion development.

2. Remove all trim components necessary to refinish the suspect panel.
3. Wash the suspect panel with soap and water to remove all dirt and debris.
4. Grind the corroded areas of affected panel / component to bare aluminum using a right angle grinder equipped with an 80-grit grinding disc.

NOTE: If surface areas are difficult to access with a grinding disc, use a 3" roloc® clean and strip fiber disc attached to a rotary tool to remove.

5. After corrosion removal, feather sand the area with 180 grit sandpaper and finish sand with 3M® Scotch-Brite Scuffing Disc 07467 Maroon or equivalent.
6. Sand the remaining exterior painted surface of the panel with 800 grit sandpaper.
7. Prepare panel for refinish, remove all remaining dust, clean with PPG® DX330 Wax and Grease Remover or equivalent and tack cloth the surface.

NOTE: PPG will be referenced as the primary product. Other approved FCA refinish paint manufacturer brands are acceptable if equivalents are available. Refer to the list of FCA approved refinish paint manufacturers:

Paint Supplier	Approved Paint Systems
Akzo Nobel®	Lesonal, Sikkens
Axalta®	Cromax, Spies Hecker, Standox
BASF®	Glasurit, R-M
PPG®	Deltron, Envirobase, Global, Nexa Autobase and Nexa Autobase Plus
Sherwin Williams®	Martin Senour Paints, Sherwin-Williams Automotive Finishes
Valspar®	DEBEER, Valspar refinish

NOTE: Refer to paint manufacturers preparation and application recommendations.

NOTE: Refer to paint manufacturers mixing and application recommendations.

NOTE: Refer to adhesive manufacturers mixing and application recommendations.

8. Apply Mopar 06103087AA, Anti-Corrosion Pen to the repair areas.
9. Apply PPG® DPLF primer epoxy primer or equivalent to bare aluminum only.
10. Apply PPG® K36 primer surface or equivalent over the repair area only.
11. When the primer surfacer has cured, block sand the surface area with 500 grit sandpaper or finer to prepare the repair area for primer sealer application.
12. If the backside of panels require repair and seam sealer removal was necessary, it must be restored. Apply SEM® 39477 seam sealer or equivalent.
13. Prepare panel for refinish, remove all remaining dust, clean with PPG® DX330 Wax and Grease remover or equivalent and tack cloth the surface.
14. Apply PPG® DAS primer sealer or equivalent and allow to flash.
15. Apply 2-3 coats of PPG® DBC basecoat or equivalent and allow to flash.
16. Apply 2-3 coats of PPG® DC4000 Clearcoat or equivalent and allow to cure.
17. Install the repaired panel. Refer to the detail service procedures available in: DealerCONNECT> Service Library under: Service Info> 23-Body> Exterior> Installation.
18. Install removed trim components and replace adhesive backed components (i.e nameplates).

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.