

NUMBER: 08-212-22

GROUP: 08 - Electrical

DATE: November 18, 2022

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 22-226, date of issue November 18, 2022. All applicable Sold and Un-Sold RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RSU will expire 18 months after the date of issue.

SUBJECT:

Drivetrain Control Module (DTCM) Connector Issue

(DT)

OVERVIEW:

This bulletin involves disconnecting and reconnecting the connectors for the DTCM.

MODELS:

2022

RAM 1500 Pickup

- NOTE: This bulletin applies to vehicles within the following markets/countries: North America.
- NOTE: This bulletin applies to vehicles built on or after August 17, 2022 (MDH 0817XX) and on or before August 18, 2022 (MDH 0818XX) equipped with Four Wheel Drive System (Sales Code 514).

SYMPTOM/CONDITION:

Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation, a technician may find one or more of the following Diagnostic Trouble Codes (DTCs) have been set:

- U0102-00 Lost Communication With Transfer Case Control Module / AWD.
- U1440 Implausible Transfer Case Ratio High Received.
- C1406-15 Transfer Case Brake Control-Circuit Short To Battery Or Open.
- C1406-92 Transfer Case Brake Control-Performance Or Incorrect Operation.
- C1406-11 Transfer Case Brake Control-Circuit Short To Ground.
- C1463-12 Front Axle Disconnect Control-Circuit Short To Battery.
- C1463-13 Front Axle Disconnect Control-Circuit Open.
- C1463-11 Front Axle Disconnect Control-Circuit Short To Ground.

In addition the customer may describe the following:

• A "Service 4WD" message/fault is displayed in the Instrument Panel Cluster (IPC).

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits the symptom/condition or DTC, perform the repair.

REPAIR PROCEDURE:

- Access the DTCM. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info> 08 - Electrical / 8E - Electronic Control Modules / Module, Drivetrain Control (DTCM) / Removal and Installation. Do not remove the DTCM.
- 2. Disconnect and reconnect the electrical connectors, push-pull-push on each connector to ensure it is properly seated (Fig. 1) .




Fig. 1 Electrical Connectors

- 1 Blue Connector
- 2 Grey Connector
- 3 White Connector
- Reassemble the components that were removed to access the DTCM. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info> 08 -Electrical / 8E - Electronic Control Modules / Module, Drivetrain Control (DTCM) / Removal and Installation.
- 4. Clear all DTCs that may have been set in any module. The wiTECH application will automatically present all DTCs and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-19-07-92	Module, Drive Train Control (DTCM) - Verify, Disconnect and Reconnect the Electrical Connec- tors at the Module (0 - Introduction)	6 - Electrical and Body Sys- tems	0.4 Hrs.

FAILURE CODE:

ZZ	Service Action