

01-20-03TT - MIL ON, NOx Sensor Circuit Range/Performance Fault P2201

Release date:

Transaction No:

1/12/2023

Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat	2012-2014	2.0L TDI (CKRA)	All	All	All

levision Table						
Instance Number	Published Date	Version Number	Reason For Update			
2059906/2	1/12/23	01-20-03TT	Updated wiring inspection in service procedure.			
2059906/1	6/19/20	01-20-03TT	Original publication.			

Technical Background

The newest variant of the -*J583*- NOx Sensor, part number 03L 907 807 **AF**, is known to be robust. If there is a fault with a vehicle equipped with the "AF" index NOx sensor variant, there may be other factors (such as exhaust leaks upstream of NOx Sensor or a wiring connector fault) contributing to the DTC.

Service

- 1.) If DTC P2201 is stored, verify the part number of the NOx Sensor. If a sensor version prior to index "AF" is installed, proceed with GFF diagnosis. If sensor is faulty, verify wiring by referring to Safety Recall 23T3 and that there are no leaks in the exhaust (as outlined in step 2) and replace NOx Sensor with latest index per ETKA.
- 2.) If the "AF" index sensor is already installed on the vehicle, do not replace sensor on the first repair visit. Verify wiring by referring to Safety Recall 23T3 and there are no leaks in the exhaust system upstream of the NOx Sensor, which may be contributing to erroneous sensor values. The VAS1687 tool is useful in pressurizing the exhaust, and a soapy water mixture works well to find leak areas. Pay close attention to the exhaust pipe connections on the exhaust flap for the low pressure EGR system. If leaks are identified, repair them as necessary. If the exhaust is verified to be leak free and an "AF" sensor variant is installed, replace the sensor if directed by GFF.

01-20-03TT - MIL ON, NOx Sensor Circuit Range/Performance Fault P2201

Release date:

Transaction No:

1/5/2023



Figure 1. Example of exhaust leak at exhaust flap.

Additional Information

© 2023 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.