GLOBAL SAFETY FIELD INVESTIGATIONS DCS6421 URGENT - DISTRIBUTE IMMEDIATELY

Date: January 24, 2023

Subject: N222362040 - Service Update

Rear Brake Line Inspect for Clearance

Models: 2022 Chevrolet Silverado 1500 LTD

2022 Chevrolet Silverado 1500 New 2022 GMC Sierra 1500 Limited 2022 GMC Sierra 1500 New

To: All General Motors Dealers

General Motors is releasing Service Update N222362040 today. The total number of U.S. vehicles involved is approximately 38,693. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated January 24, 2023. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE GLOBAL SAFETY FIELD INVESTIGATIONS

Service Update

N222362040 Rear Brake Line Inspect for Clearance



Release Date: January 2023 Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

		Model Year		Model Year			
Make	Model	From	То	RPO	Description		
Chevrolet	Silverado 1500 LTD						
Chevrolet	Silverado 1500 New	2022	2022				
GMC	Sierra 1500 Limited						
GMC	Sierra 1500 New						

Involved vehicles are marked "Open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	Certain 2022 model year Chevrolet Silverado 1500 LTD/New and GMC Sierra 1500 Limited/New				
	vehicles may have a condition where the brake line contacts the rear axle.				
Correction	Dealers are to inspect the rear brake lines for clearance and replace if necessary.				

Parts

Quantity	Part Name	Part No.	
3	Bumper	85627552	
6	Zip Ties	Obtain Locally	
1	Rear Brake Pipe - RH	84565798	
1	Rear Brake Pipe - LH	84650221	
As Req.	Brake Fluid	19299570 (US)	
		19299571 (CA)	
		Obtain DOT4 brake fluid locally	
		in compliance with GM spec	
		GMW3356 (All other countries).	

Important: Due to limited initial parts availability, dealers are encouraged not to order recall parts for use as shelf stock. Parts should only be ordered when inspection determines that it is necessary

Parts may have quantity limiters in effect. Do not order for shelf stock and parts will be removed from SPRINT.

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor		Labor	Trans.	Net
Operation	Description		Type	Item
9106553	Inspect Rear Brake Lines for Damage and Clearance	0.3		
9106554	Inspect Rear Brake Lines and Install Bumpers for Clearance	0.4		
	Add: Rear Brake Pipe Replacement (includes inspection and		ZFAT	N/A
	addition of bumpers if necessary)	0.7		
	Add: Replace Other Side of Rear Brake Pipe	0.3		


Service Procedure

1. Lift the vehicle. Refer to Lifting and Jacking the Vehicle in SI.

Service Update

N222362040 Rear Brake Line Insufficient Clearance





- 2. Inspect the rear brake lines at the three areas indicated above to ensure there is at least 3mm (1/8 inch) of clearance between the brake pipe and the rear axle. Additionally ensure that no contact has occurred between the two due to vibration or otherwise look for witness marks or chipped coating.
 - If contact has occurred at any of the three locations indicated, replace the brake pipe in question. Refer to Rear Brake Pipe Replacement Left Side or Rear Brake Pipe Replacement Right Side in SI.
 - If no contact has occurred, and clearance is less than 3mm (1/8 inch), install a rubber bumper at each of the three locations indicated. Secure the bumper with a zip tie at each end.
 - If no contact has occurred, and clearance is GREATER than 3mm (1/8 inch), no further action is required.
- 3. Lower the vehicle. Refer to Lifting and Jacking the Vehicle in SI.

Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Service Update

N222362040 Rear Brake Line Insufficient Clearance



Dealer Reports - For USA & Export

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.