



## TECHNICAL SERVICE BULLETIN

### 5.0L - Illuminated Malfunction Indicator Lamp (MIL) With DTCs P0300, P0301, P0302, P0303, P0304, P0305, P0306, P0307, And/Or P0308

22-2464

12 January  
2023

#### Model:

<b>Ford</b> 2021-2022 Mustang	Engine: 5.0L
----------------------------------	--------------

**Issue:** Some 2021-2022 Mustang vehicles equipped with a 5.0L engine may exhibit an illuminated MIL with diagnostic trouble codes (DTCs) P0300, P0301, P0302, P0303, P0304, P0305, P0306, P0307, and/or P0308 stored in the powertrain control module (PCM). This may be due to various strategies within the PCM software. To correct the condition, follow the Service Procedure to reprogram the PCM.

**Action:** Follow the Service Procedure to correct the condition on vehicles that meet all of the following criteria:

- 2021-2022 Mustang
- 5.0L engine
- Illuminated MIL with DTCs P0300, P0301, P0302, P0303, P0304, P0305, P0306, P0307, and/or P0308 stored in the PCM

**Warranty Status:** Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Emissions Warranty/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/Emissions Warranty/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

#### Labor Times

Description	Operation No.	Time
2021-2022 Mustang 5.0L: Retrieve DTCs And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	222464A	0.4 Hrs.

#### Repair/Claim Coding

Causal Part:	RECALEM
Condition Code:	04

## Service Procedure

1. Reprogram the PCM using the latest software level of the Ford Diagnosis and Repair System (FDRS).

**NOTE: Advise the customer that this vehicle is equipped with an adaptive transmission shift strategy which allows the vehicle's computer to learn the transmission's unique parameters and improve shift quality. When the adaptive strategy is reset, the computer will begin a relearning process. This relearning process may result in firmer than normal upshifts and downshifts for several days.**

© 2023 Ford Motor Company  
All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.