

Display of “Coolant Temperature Too High” in G2, Macan and E3

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Panamera	2017 - 2021	All V6 engines	n/a	n/a
Macan	2019 - 2021	All V6 engines	n/a	n/a
Cayenne	2019 - 2021	All	n/a	n/a

Revision History

Revision	Release Date	Changes
0	December 20, 2022	Original document
1	January 23, 2023	Update of Panamera model type

Condition

Customer complains about “Coolant temperature too high” warning message, fault code B19A750 in the Instrument Cluster: “Display of coolant temperature too high, active”.




Figure 1 - Owner's Manual Information for Over-Temperature Warning (B19A750)

Technical Background

The aforementioned warning message only displays when temperatures exceed the warning thresholds. In contrast to “TI, 1950 Warning Message “Coolant Temperature Too High”: Checking Coolant Pump and Change-Over Valve (173/21)”, please replace the ‘change-over valve’ in combination with this warning, regardless of whether or not it passes the function test as outlined in TI 173/21.

Service Information

1. Check and verify vehicle model year
2. Check for damage in the coolant pump and replace if necessary, per the instruction in *WM – 195019*
3. Replace change-over valve
4. Check for damage and residue in vacuum lines and replace if necessary.

Warranty

As always, please document the repair completely in PQIS.

For this repair, please code the "cause" as follows:

Cause location: 19500 Coolant pump

Cause symptom: 1611 No function

Use the following troubleshooting labor operation:

03350050 On board diagnostic

19010150 Cooling system check

19505521 Check change-over valve, replace change-over valve and coolant pump (V6 engine)

19383550 Coolant inspect and add

03350053 On board diagnostic

Search Items

Coolant leak, water pump, change-over valve, switching valve, overheating, temperature

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
