



# TECHNICAL SERVICE BULLETIN


Classification: EC22-012	Reference: NTB23-006	Date: January 18, 2023
-----------------------------	-------------------------	---------------------------

## MIL ON WITH DTC P0101 AND/OR P010B STORED IN THE ECM

APPLIED VEHICLES: 2023 Z (Z34)

### SERVICE INFORMATION

If the MIL is ON and DTC P0101 (MAF SEN/CIRCUIT-B1) and/or DTC P010B (MAF SEN/CIRCUIT-B2) is stored in the ECM on an **APPLIED VEHICLE**, follow the information in this bulletin along with the ESM to complete the required repairs.



Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

## NOTICE

To avoid damage to the vehicle, only remove the Mass Air Flow Sensor from the Air Cleaner Cover if necessary.

- Never shock the Mass Air Flow Sensor.
  - Never disassemble the Mass Air Flow Sensor.
  - Never touch the sensor of the Mass Air Flow Sensor.
1. Inspect the applicable Air Duct(s) for any leaks or poor connections.
    - For DTC P0101, inspect the passenger (RH) side Air Duct (Figure 2 and Figure 3).
    - For DTC P010B, inspect the driver (LH) side Air Duct (Figure 5 and Figure 4).




Figure 2

Figure 3




Figure 5

Figure 4

2. Disconnect/remove the Air Duct as needed, and then correctly reconnect/reinstall the Air Duct, ensuring there are no leaks.
  - Refer to ESM: **ENGINE > ENGINE MECHANICAL > REMOVAL AND INSTALLATION > AIR CLEANER AND AIR DUCT > Removal and Installation**

### AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
January 18, 2023	NTB23-006	Original bulletin published

