



# TECHNICAL SERVICE BULLETIN

Classification: AN22-032	Reference: NTB23-008	Date: January 23, 2023
-----------------------------	-------------------------	---------------------------

## SOFTWARE UPDATE AFTER AV CONTROL UNIT REPLACEMENT

**APPLIED VEHICLES:** 2021-2023 Armada (Y62)

### SERVICE INFORMATION

After replacement of the AV Control Unit on an **APPLIED VEHICLE**, it is necessary to verify the current software version of the new AV Control Unit to determine if a software version update is required.

Follow the steps outlined in the **SERVICE PROCEDURE** below to determine the current software version and if the AV Control Unit requires a software version update.

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

## REQUIRED SPECIAL TOOL

- One of special tool USB drive J-52727-1 has been previously shipped to each dealer (Figure 1).
  - New part number NI-52727-1.
- Do not use any other USB drive to perform the procedure in this bulletin.
- Additional USB drives may be purchased from TechMate online: [techmatetools.com](http://techmatetools.com), or by phone: 1-833-397-3493.

### HINT:

- The update-software only needs to be downloaded once and can then be used continuously on multiple **APPLIED VEHICLES**.
- The update-software must be the only file on the USB drive.



Figure 1

## SERVICE PROCEDURE

### Check the Software Version

1. Starting from the HOME screen (Figure 2), select **Info**.



Figure 2

2. Select **System Information**.




Figure 3

3. Select **Version Information**.




Figure 4

4. Confirm the **Software Version** number (Figure 5).
  - If the **Software Version** is not “283C315##B”, select the back icon and continue to step 5.
  - If the **Software Version** is “283C315##B”, the new AV Control Unit does not require a Software Version update.




Figure 5

## Update the AV Control Unit

### **IMPORTANT:** Before starting, make sure:

- The CONSULT PC is connected to the internet.
- ASIST has been synchronized (updated) to the current date.

**HINT:** In the following steps, if more than one CONSULT PC is available and the **PVI\_1570** infotainment update-software has already been downloaded through ASIST to one of them, use the CONSULT PC with the pre-existing download.

5. Insert the special tool USB drive into the CONSULT PC.
  - If the infotainment update-software has already been downloaded onto the special tool USB drive from a prior service procedure, skip to step 14 on page 7.

### **HINT:**

- The special tool USB drive is the only USB drive approved for use with this procedure.
- The update-software only needs to be downloaded once and can then be used continuously on multiple **APPLIED VEHICLES**.
- The update-software must be the only file on the USB drive.

6. Open ASIST.

7. Select **Specialty Tools**, and then select **Infotainment Software Updates**.




Figure 6

8. Select the check box next to the **PVI\_1570** infotainment update-software (Figure 7).
  - If the **PVI\_1570** infotainment update-software has already been downloaded, “Transfer” will be displayed instead of “Download” when the box is checked.
9. Use the drop-down menu and select the location of the USB drive that was inserted in step 5 on page 4.




Figure 7

10. Select **Download**, and then wait for the download to complete.

**HINT:**

- The initial download of the update-software to the CONSULT PC and file transfer to the USB drive is estimated to take **6 hours**. After the initial download of the update-software, file transfer to the USB drive is estimated to take 1 hour.
- If while attempting to download the update-software to the CONSULT PC, you receive the message shown in Figure 8:
  - a. Attempt to clear space on the CONSULT PC hard drive (40 GB required).
  - b. If space cannot be cleared and a second CONSULT PC is available with space, use it and start over from step 5.



Figure 8

11. Select **OK**.




Figure 9

12. Once the transfer is complete, safely remove the USB drive from the CONSULT PC.
  - a. From the PC toolbar, select the **Safely Remove Hardware** icon.
    - o The icon is on the toolbar, or can be found after selecting the arrow.
  - b. Select the USB drive to be removed, and then remove the USB drive from the CONSULT PC.

**NOTICE**

Follow the steps to safely remove the USB drive. If not followed, the USB drive may corrupt the infotainment update-software.

- If you are not familiar with the process of safe USB drive removal, ask for assistance at your dealer.



Figure 10

13. Close all ASIST **Infotainment Software Update** screens.
14. Set the parking brake.
15. Start the engine, and then wait 60 seconds for the system to load.

**HINT:** The engine needs to idle for the duration of the update to retain battery charge.

16. Insert the USB drive with infotainment update-software into the vehicle's USB media port (Figure 11).

- Do not remove the USB drive during the update to the vehicle until instructed to.

**NOTICE**

Do not insert the USB drive into a charging port. If used, the update-software and/or USB drive may become damaged. Only insert the USB drive in a USB media port.

**HINT:** Charging ports are marked in the vehicle with a “lightning bolt” symbol.




Figure 11




Figure 12

17. Wait for the update to complete.

- Follow the on-screen instructions while waiting.

**HINT:** The update lasts 20-30 minutes.




Figure 13



- Once the update is complete (Figure 14), remove the USB drive; the system will reboot (restart).

**HINT:** The system will not reboot until the USB drive is removed.




Figure 14

**NOTICE**

Steps 19 - 24 must be completed to reinitialize the AV Control Unit. If they are not completed, the update may become corrupt.

- Press and hold the **MENU** button on the IT Commander (Figure 15) and turn the AV Unit volume knob (Figure 16) left-right at the same time.




Figure 15



Figure 16

20. Select **Confirmation/Adjustment**.




Figure 17

21. Select **Initialize Settings**.




Figure 18

22. Select **User Data Initialization**.




Figure 19

23. Select **Yes**.




Figure 20

24. Select **Yes**.




Figure 21

25. Have the customer remove the stored vehicle from the phone's Bluetooth connection list before trying to connect to the AV Control Unit.

### CLAIMS INFORMATION

Submit a Primary Part (PO) type line claim using the following claims coding:

DESCRIPTION	OP CODE	SYM	DIA	FRT
Perform Software Check and Update	RX8MAA	ZE	32	0.3

### AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
January 23, 2023	NTB23-008	Original bulletin published