



# Preliminary Information

## PIT5819A Exhaust Only Exiting From Right Hand Tailpipe Outlet In Low Temperatures

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	L84 or L87	All
Chevrolet	Silverado 1500	2020 - 2023	All	All	L84 or L87	All
GMC	Sierra 1500 (New Model)	2019	All	All	L84 or L87	All
GMC	Sierra 1500	2020 - 2023	All	All	L84 or L87	All

Involved Region or Country	North America
Additional Options (RPO)	N10 - Dual Outlet Exhaust
Condition	In temperatures below freezing, it may be noticed that exhaust is only exiting from the right hand exhaust tailpipe outlet.
Cause	The cause of this condition is a low point in the left side tailpipe.  This results in condensation building up at the lowest point in the tailpipe.  In freezing temperatures the condensation inside the exhaust system can freeze and form ice, limiting the flow of exhaust out of the left tailpipe.

### Correction:

To correct this concern, locate the low point of the left tailpipe and drill a 1.5 mm (1/16") hole in the bottom of the pipe.

This will prevent the build up of condensation by allowing the condensation to drain.

Do not replace the exhaust system.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*4087868	Drill hole at the bottom of the left tailpipe low point to allow condensation to drain	0.3 hrs
*This is a unique Labor Operation for Bulletin use only.		

### Version History

Version	2
Modified	03/05/2021 - Created 01/05/2023 - Update model years



© 2023 General Motors. All Rights Reserved.