



STAR ONLINE PUBLICATION



Case Number: S2219000005 REV.A

Release Date: January 2023

Symptom/Vehicle Issue: Check Engine Lamp On. Warning Messages In The Cluster. U0131 Lost Communication With Power Steering Control Module Set.

Customer Complaint/Technician Observation: Customer may mention service electric steering message in the cluster along with other warnings and lamps. They may complain the Electronic Power Steering (EPS) assist was lost at start up for a key cycle. Technicians may find modules reporting U0131 Lost Communication Diagnostic Trouble Code (DTC) set against the EPS.


Discussion: First, review any applicable service bulletins and information that may apply to a customer complaint. If DTC U0131 Lost Communication with Power Steering Control Module is set, do not start with replacing the EPS. Verify the EPS connectors are fully snapped in by pushing on the connectors. Comments from field technicians show concerns with the amount of grease found in the EPS connectors. The amount shown in the images is applied at assembly and is correct. Dielectric grease is used in this location due the EPS location and contact with moisture. Do not remove the factory applied grease. Inspect the pins for push out and damage such as being bent. Inspect the EPS ground locations. Clean connection points and tighten grounding cables.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.



STAR ONLINE PUBLICATION



Examples of factory applied dielectric grease. Do not remove the grease.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.