

Service Bulletin

Bulletin No.: 21-NA-116

Date: February, 2023

TECHNICAL

Subject: Malfunction Indicator Lamp (MIL) Illuminated - Multiple DTCs Set

Brand:	Model:	Model Year:		VIN:		Engine	Transmission:
		from	to	from	to	Engine:	mansinission.
Chevrolet	Volt	2016	2019	_	_	1.5L (L3A)	_

Involved Region or Country	North America, GM Korea Company
	Some customers may comment that the MIL is illuminated.
	Some technicians may find open fuse F3UA in the underhood fuse block.
	Some technicians may also find one or more of the following DTCs set in the Engine Control Module (ECM):
	• P0030
	• P0031
Condition	• P0403
	• P0405
	• P0443
	• P0458
	• P0489
	• P0597
	• P0598
	This condition may be caused by an internal short in the exhaust gas recirculation (EGR).
Cause	 This could appear to be intermittent if the EGR is not working at the time the fuse is replaced.
Correction	Inspect for any shorts in the engine harness that could cause the fuse F3UA to Open. Look specifically at the harness going to the EGR (G14), Heated oxygen sensor 1 (B52A), engine coolant thermostat (E41), EVAP purge solenoid Valve (Q12), and engine oil pressure control solenoid Valve (Q44) for any chaffing points.
	⇒ If the harness checks out, replace the EGR valve (Q14).

Service Procedure

Refer to Exhaust Gas Recirculation Valve Replacement in SI.

Parts Information

Causal Part	Description	Part Number	Qty
Х	VALVE, EGR	12691147	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4024770	Exhaust Gas Recirculation Valve Replacement	Use Published Labor Operation Time

Version	1
Modified	Released February 03, 2023