

Service Bulletin

Bulletin No.: 18-NA-279

Date: February, 2023

INFORMATION

Subject: Information on Passive Door Unlocking Inoperative and/or Enabling and Disabling of Passive Unlocking

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission
Brand:		from	to	from	to	Engine:	Transmission:
	Enclave	2019	2023				
	Encore	2019	2022				
Buick	Encore GX	2020	2023]			
	Envision	2019	2023	1			
	LaCrosse	2019	2019	1			
	CT4	0000	2023	1			
	CT5	2020					
	CT6	2019	2020]			
Cadillac	Escalade Models	2019	2023]			
Cadillac	LYRIQ	2023	2023				
	XT4	2019	2022				
	XT5	2019	2021				
	XT6	2020					
	Bolt EV	2019	2023				
	Bolt EUV	2022	2023	_	_	All	All
	Cruze	2019	2019				
	Volt						
	Silverado 1500 (New Model)	2019	2019				
	Blazer	2019	2021				
	Camaro	2019	2021				
Chevrolet	Malibu	2019	2022				
	Spark	2019	2022				
	Suburban	2019	2023				
	Tahoe	2019	2023				
	Trailblazer	2021	2023				
	Traverse	2040	2021				
	Trax	2019	2022				
	Silverado	2020	2023				

Brand:	Model:	Model Year:		VIN:		Funing	Tuonomiosion
		from	to	from	to	Engine:	Transmission:
	Acadia	2020	2021				
	Hummer EV	2022	2023				
GMC	Yukon		2023		_	All	All
Sime	Sierra 1500 (New Model)	2019	2019	_			
	Sierra	2020	2023				

Involved Region or Country	North America, Chile, Colombia, Ecuador, Peru, Europe, Israel, Middle East, Cadillac Korea (South Korea), GM Korea Company, Uzbekistan, China, Japan, Malaysia, Vietnam			
Condition	Some customers may comment that the passive door unlocking feature is inoperative when pressing the button on any door handle or tailgate release handle. They may also comment that all turn signals flash 4 times quickly when the button is pressed.			
Correction	when using the follogenabled to Passive Once any individual disabled for ALL FO vehicles. Additionally, as show	n signals flash 4 times owing procedures, the country unlocking Disabled, and FOB is used to disable obs. This will also disable wn below, some listed were signals.	quickly owner c nd back e Passiv le hand vehicles ter stac	when the button is pressed.
				And the same of th

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

With the vehicle off:

Starting State	Do:	Results in:	
Passive Unlocking is Enabled	Press and Hold both Lock and Unlock FOB buttons for 3 seconds.	Turn Signals flash 4 times and Passive Unlocking is Disabled. When the button on the door handle is pressed, the Turn Signals flash 4 times and the doors remain locked.	
Passive Unlocking is Disabled	Press and Hold both Lock and Unlock FOB buttons for 3 seconds.	Turn Signals flash 2 times and Passive Unlocking is Enabled. When the button on the door handle is pressed, the door(s) will unlock.	

Note: If it is necessary to contact the Technical Assistance Center (TAC) for this issue, please obtain the following information from the customer prior to calling:

How long driver had vehicle?

Was issue there from beginning of vehicle delivery or occurred after?

Where does the driver keep the FOB? Front pocket, rear pocket, etc.

Single driver or multiple drivers for vehicle?

Does customer remember pressing both lock and unlock on FOB at the same time?

Has anyone else used the FOB?

Customer Information

Please share this information with the customer, including a copy of this bulletin.

Version	7
Modified	Released September 13, 2018
	Revised May 29, 2019 – Added the Chevrolet Blazer and Cadillac XT6 Models, updated the Involved Region or Country section and added a Note to the Results in section.
	Revised October 10, 2019 – Added Models, 2020 Model Year, removed the Opel Karl model, updated the Involved Region or Country section, removed RPO information, added Correction statements and graphic and removed the Note in the Results in section.
	Revised January 22, 2020 – Corrected Flash Information in Results in section.
	Revised May 12, 2021 – Added the Buick Encore GX and Chevrolet Trailblazer models, 2021 Model Year to certain models, updated the Involved Region or Country section and added several Additional SI Keywords.
	Revised January 20, 2023 – Added the 2020–2022 Model Years to Bolt EV, added Bolt EUV model, added "This will also disable hands free liftgate on liftgate equipped vehicles." in the Correction section and added an Important statement to start of Service Procedure.
	Revised February 10, 2023 – Added the Hummer EV and Cadillac LYRIQ models and the 2022–2023 Model Years to applicable vehicles.

Additional SI Keywords: disable, enable, entry, flashes, FOBs, four, free, gate, hand, hands, hands-free, handsfree, inop, key, keyless, left, lift, liftgate, locking, passenger, PEPS, right, tail, transmitter, door, flash, light, lights, lock