

# Service Bulletin

Bulletin No.: 15-06-01-002N

Date: February, 2023

# **TECHNICAL**

Subject: Engine Misfire/Tick Noise, Malfunction Indicator Lamp (MIL) Illuminated - DTC

P0300 Set

Models: 2015-2020 Cadillac Escalade

2016–2019 Cadillac CTS-V

2014 Chevrolet Silverado 1500 2014–2019 Chevrolet Corvette 2015–2018 Chevrolet Silverado

2015-2020 Chevrolet Suburban, Tahoe

2016–2023 Chevrolet Camaro 2019 Chevrolet Silverado LD

2014 GMC Sierra 1500 2015–2018 GMC Sierra

2015-2020 GMC Yukon, Yukon XL

2019 GMC Sierra Limited

Equipped with 5.3L Engine (RPOs L83, L8B) or 6.2L Engine (RPOs L86, LT1, LT4)

Attention: This bulletin also applies to any of the above models from North America, Europe,

Uzbekistan, Russia, Middle East, Iraq, Israel, Palestine, Argentina, Brazil, Bolivia, Chile, Colombia, Ecuador, Paraguay, Peru, Uruguay, Venezuela, Japan, Cadillac Korea (South Korea), GM Korea Company, China, Taiwan, Thailand, Singapore, Philippines, Egypt,

Other Africa. South Africa

This bulletin has been revised to add the Important statement above the Recommendation/ Instructions section, update the Parts Information section to add a Note, update a Note and add part numbers. Please discard Corporate Bulletin Number 15-06-01-002M.

#### Condition

Some customers may comment on a malfunction indicator lamp (MIL) on and/or an engine misfire/tick noise.

Technicians may find DTC P0300 set or in history.

#### Cause

This may be caused by one of the following conditions:

- Active fuel management (AFM) lifter that is mechanically collapsed and/or stuck all of the time.
- Internal locking pin damage in the lifter, due to oil aeration.
- Lifter that has collapsed and is stuck in the lifter bore.
- · The engine may have a bent push rod.

### Correction

**Note:** Thoroughly inspect the camshaft and lifters for any damage to the lobes or rollers. If you find excessive wear on either component, it will be necessary to replace the camshaft and lifters. It is not necessary to replace the engine assembly. Refer to Service Bulletin # 18-NA-073: Repair Guidelines for Engine Component Wear.

If SI diagnosis does not isolate the cause of this concern, technicians should inspect for valve operation. If the valve(s) are not moving, replace the valve lifter oil manifold and affected bank of AFM lifters. Refer to Valve Lifter Oil Manifold Replacement and Valve Lifter Replacement in SI.

If the lifter has spun the bore, the guides should also be replaced.

Page 2 February, 2023 Bulletin No.: 15-06-01-002N

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

#### Recommendation/Instructions


**Important:** Any time a lifter is replaced, the lifter guide(s) must also be replaced.

There are two approved processes for removing the lifter when stuck in the bore.



4250109

1. Use vice grips with a slide hammer.



4921302

**Note:** Be sure **NOT** to pry on the sealing surface of the block, as shown in the illustration above.

2. Use vice grips with a small pry bar.

Typically, one of the above approved processes will remove the lifter that is stuck in the bore. If not, the engine will need to be replaced.

With the lifter removed, be sure to inspect the bore for any damage. Typically, the lifter bores will look good with no indication of damage.

**Note:** Refer to Service Bulletin # 20-NA-038 for additional information on AFM and DFM usage.

### **Parts Information**

Note: Only select the parts that coincide with the repair performed. Replace the part with the P/N outlined in the Electronic Parts Catalog (EPC) in accordance with the vehicle VIN.

**Note:** Only replace the valve lifter oil manifold assembly (LOMA) if SI diagnosis leads to a fault within the manifold assembly.

Causal Part	Part Number	Description	Qty
N/A	12697806	MANIFOLD, VLV LFTR OIL (L83, L86, L8B or LT1)	1
N/A	12677002 1st Design 12703668 2nd Design	PIPE, FUEL FEE INTER (PIPE ONLY) (FROM PUMP TO RAIL) (L83, L86, L8B or LT1) (NOTE: need to confirm what pipe part number was removed from engine. They are different.)	1
N/A	12677004	PIPE, FUEL FEED INTER (182 mm) (FROM PUMP TO RAIL) (L83 L86)	1
N/A	12677006	PIPE, FUEL FEED INTER (177 mm) (FROM PUMP TO RAIL) (L83)	1
N/A	12679463	PIPE, FUEL FEED INTER (FROM PUMP TO RAIL) (LT1)	1
N/A	12697807	MANIFOLD, VLV LFTR OIL (LT4)	1
N/A	12677005	PIPE, FUEL FEE INTER (PIPE ONLY) (FROM PUMP TO RAIL) (LT4)	1
N/A N/A	12677003 1st Design 12703669 2nd Design	PIPE, FUEL FEED INTER (LT4) (NOTE: need to confirm what pipe part number was removed from engine they are different)	1
N/A	12669185	GUIDE, VLV LFTR (see catalog reference)	2
N/A	12669184	GUIDE, VLV LFTR (see catalog reference)	2
N/A	12688943	GASKET-CYL HD (6.2L)	1
N/A	12622325	GASKET-CYL HD (5.3L)	1
N/A	11546959	RIGHT SIDE CYLINDER HEAD BOLTS	10
N/A	11611976	LEFT SIDE CYLINDER HEAD BOLT	1
N/A	11546959	LEFT SIDE CYLINDER HEAD BOLTS	9
N/A	12657093	GASKET-EXH MANIF	1
N/A	12626354	GASKET-INT MANIF	8
N/A	Refer to EPC	SEAL, EXH SYS	1
N/A	12619787	GASKET-VLV RKR ARM CVR	1
N/A	12623308	GASKET-F/PMP BRKT	1
N/A	12672366	SEAL KIT-F/INJR (O RING)	2
N/A	11546600	BOLT, EXH MANIF	5

## **Warranty Information**

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4080978*	Valve Lifter Oil Manifold and Valve Lifter Left Side Replacement	9.4 hrs (Silverado, Sierra)
		14.8 hrs (CTS-V)
		9.2 hrs (Escalade, Suburban, Tahoe, Yukon)
		11.7 hrs (Corvette)
		7.0 hrs (Camaro)
4080988*	Valve Lifter Oil Manifold and Valve Lifter Right Side Replacement	10.9 hrs (Silverado, Sierra)
		15.5 hrs (CTS-V)
		9.3 hrs (Escalade, Suburban, Tahoe, Yukon)
		11.4 hrs (Corvette)
		9.0 hrs (Camaro)